

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 N C B E P 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5

CON'T REPORT SOURCE L 0 5 0 - 0 3 2 4 7 0 2 2 5 8 1 8 0 3 2 7 8 1 9

02 During a review of the plant prestartup checklist, while performing a normal reactor startup, it was discovered that RCIC System Component Test, PT 10.1.1a, had not been performed prior to expiration of the performance tolerance date of February 22, 1981. The RCIC System was then declared inoperable in accordance with technical specifications. This event did not affect the health or safety of the public.

08 Technical Specifications 3.7.4, 6.9.1.9b

09 SYSTEM CODE C E 11 CAUSE CODE D 12 CAUSE SUBCODE Z 13 COMPONENT CODE Z Z Z Z Z Z 14 COMP. SUBCODE Z 15 VALVE SUBCODE Z 16

10 This event occurred because the plant operating instructions do not adequately provide for rescheduling PT's not performed on their due date. The PT was satisfactorily performed on February 26, 1981, and the RCIC System was declared operable and returned to service. Plant operating instructions are being revised to correct the rescheduling deficiency.

15 FACILITY STATUS C 28 % POWER 0 0 2 29 OTHER STATUS NA 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Operational Event 32

16 ACTIVITY CONTENT Z 33 RELEASED OF RELEASE Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36

17 PERSONNEL EXPOSURES NUMBER 0 0 0 17 TYPE Z 38 DESCRIPTION NA 39

18 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43

20 PUBLICITY ISSUED N 44 DESCRIPTION NA 45

LER ATTACHMENT - RO #2-81-34

Facility: BSEP Unit No. 2

Event Date: 2-25-81

This event resulted from a deficiency of the plant operating instructions in that they do not adequately deal with rescheduling periodic tests that are not performed on the required date. PT 10.1.1a was scheduled for performance on February 15, 1981, but due to the plant being in cold shutdown it was not performed. Plant operating instructions presently provide for identification of deficiencies encountered during the performance of a periodic test through the use of the PT exception form, but are unclear who is responsible for the actual rescheduling of PT's not performed. To prevent future similar events the PT exception form is now being revised to provide for better identification of PT's requiring rescheduling. In addition, plant operating instructions are also being revised to provide instructions to the now identified persons responsible for ensuring that PT's requiring rescheduling are identified and assigned performance dates in accordance with ongoing plant conditions. After the discovery on February 25, 1981, that the PT had not been performed by the required date, following the unit startup on February 26, 1981, it was satisfactorily performed and the RCIC System returned to normal operability.