

U.S. NUCLEAR REGULATORY COMMISSION  
LICENSEE EVENT REPORT

CONTROL BLOCK / / / / / (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

/0/1/ /V/A/N/A/S/1/ (2) /0/0/-/0/0/0/0/0/-/0/0/ (3) /4/1/1/1/1/ (4) / / / (5)  
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT

/0/1/ REPORT /L/ (6) /0/5/0/0/0/3/3/8/ (7) /0/4/2/0/8/1/ (8) /0/5/1/3/8/1/ (9)  
SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

/0/2/ / On April 20, 1931, with Unit I at 100% power, the pressurizer level channel I /  
/0/3/ / (LI-1459A) indicated high and deviated from the average of the other level /  
/0/4/ / indications by greater than 3.5%. Since the channel was placed in trip in /  
/0/5/ / one hour as required by T.S. 3.3.1.1, and two redundant level protection /  
/0/6/ / channels remained available for reactor trip actuation if needed, the public /  
/0/7/ / health and safety were not affected. /  
/0/8/ /

SYSTEM	CAUSE	CAUSE	COMP.	VALVE
CODE	CODE	SUBCODE	SUBCODE	SUBCODE

/0/9/	/I/A/ (11)	/E/ (12)	/A/ (13)	/I/N/S/T/R/U/ (14)	/T/ (15)	/Z/ (16)
	LER/RO	EVENT YEAR	SEQUENTIAL	OCCURRENCE	REPORT	REVISION
(17)	REPORT		REPORT NO.	CODE	TYPE	NO.
	NUMBER	/8/1/	/-/	/0/1/9/	/ / /	/0/3/
					/L/	/-/
						/0/

ACTION	FUTURE	EFFECT	SHUTDOWN	ATTACHMENT	NPRD-4	PRIME COMP.	COMPONENT
TAKEN	ACTION	ON PLANT	METHOD	SUBMITTED	FORM SUB.	SUPPLIER	MANUFACTURER
/E/ (18)	/Z/ (19)	/Z/ (20)	/A/ (21)	/0/0/0/0/ (22)	/Y/ (23)	/N/ (24)	/N/ (25)
							/B/0/8/0/ (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

/1/0/ / The cause of this event was instrument drift, a root valve on the condensate /  
/1/1/ / pot packing leak, and an isolation valve on pressure transmitter (PT1455) /  
/1/2/ / leaking. The level transmitter was recalibrated, the root valve backseated and /  
/1/3/ / the leaking isolation valve tightened. The affected transmitter was then /  
/1/4/ / returned to service. /

FACILITY	METHOD OF
STATUS	DISCOVERY
%POWER	DISCOVERY DESCRIPTION (32)
OTHER STATUS	OPERATOR OBSERVATION
(30)	

/1/5/	/E/ (28)	/1/0/0/ (29)	/ NA /	/A/ (31)	/

ACTIVITY	CONTENT
RELEASED	OF RELEASE
AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)

/1/6/	/Z/ (33)	/Z/ (34)	/ NA /	/ NA /
-------	----------	----------	--------	--------

PERSONNEL EXPOSURES
NUMBER
TYPE
DESCRIPTION (39)

/1/7/	/0/0/0/ (37)	/Z/ (38)	/ NA /
-------	--------------	----------	--------

PERSONNEL INJURIES
NUMBER
DESCRIPTION (41)

/1/8/	/0/0/0/ (40)	/ NA /
-------	--------------	--------

LOSS OF OR DAMAGE TO FACILITY
TYPE
DESCRIPTION (43)

/1/9/	/Z/ (42)	/ NA /
-------	----------	--------

PUBLICITY

ISSUED	DESCRIPTION (45)
--------	------------------

/2/0/	/N/ (44)	/ NA /	/ / / / / / / / / / /
-------	----------	--------	-----------------------

NRC USE ONLY

NAME OF PREPARER W. R. CARTWRIGHT

PHONE (703) 894-5151

8105190263

Virginia Electric and Power Company  
North Anna Power Station, Unit #1  
Docket No. 50-338  
Report No. LER 81-019/03L-0

Attachment: Page 1 of 1

#### Description of Event

On April 20, 1981, with Unit I in Mode I at 10% power, the pressurizer level indication provided by level transmitter (LT-1459A) deviated by > 3.5% from the average of the other level transmitter indications. This event is contrary to T.S. 3.3.1.1 and reportable pursuant to T.S. 6.9.1.9.a.

#### Probable Consequences of Occurrence

Since two redundant protection channels remained available and the affected level channel was placed in trip within one hour, the public health and safety were not affected.

#### Cause of Event

The causes for level transmitter 1459A reading high were the following three problems: instrument drift (worse case was 500 mv high); a root valve on the condensate pot packing leak, and a leaking isolation valve on pressure transmitter 1455. Both pressure transmitter 1455 and the affected level transmitter 1459A have a common tap which caused the leak on one to affect the other. No problems existed with pressure transmitter 1455 and no further problems were found with the affected level transmitter. Both channels were subsequently returned to service.

#### Immediate Corrective Action

The immediate action was to declare the affected channel inoperable and place it in a trip mode. Subsequent to placing channel I (L-1459A) in the trip mode, the affected transmitter was recalibrated and the leaking root valve on the condensate pot was backseated. Additional action taken prior to returning the loop to service included tightening a leaking isolation drain valve on pressure transmitter P-455.

#### Scheduled Corrective Action

No further action is scheduled.

#### Actions Taken to Prevent Recurrence

No further action is required.

#### Generic Implications

There are no generic implications to this event.