

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	C	B	E	P	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4	5
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	
LICENSEE CODE								LICENSE NUMBER								LICENSE TYPE								CAT 58		

0	1	L	0	5	0	-	0	3	2	4	7	0	4	1	2	8	1	8	0	4	1	1	8	1	3
7	8	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	
CON'T		REPORT SOURCE		DOCKET NUMBER								EVENT DATE				REPORT DATE									

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During normal plant operation following a unit outage that involved maintenance to

0 3 | the main condenser waterboxes, routine reactor coolant analysis revealed vessel

0 4 | conductivity > 10 μmho/cm². Vessel conductivity remained > 10 μmho/cm² for 8 hours

0 5 | with the highest recorded value at 24.8 μmho/cm². Following the discovery that vessel

0 6 | conductivity had exceeded specifications a manual reactor scram was then initiated.

0 7 | This event did not affect the health or safety of the public.

Technical Specification 3.4.4.a.2, 6.9.1.9b

0	9	H	C	11	E	12	F	13	H	T	E	X	C	H	14	D	15	Z	16
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26
SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE					COMP. SUBCODE		VALVE SUBCODE						
17	LER/RO REPORT NUMBER	EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.									
7	8	9	10	11	12	13	14	15	16	17	18								
18	19	20	21	22	23	24	25	26	27	28	29								
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER			
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47					

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | This event resulted from excessive main condenser waterbox tube leakage that occurred

1 1 | when tube plugs to approximately 75 - 100 tubes fell out allowing circulating water

1 2 | leakage into the hotwells. The plugs were replaced with a different type plug and

1 3 | a satisfactory leak check of the tubes was performed. Vessel conductivity was

1 4 | returned to within specifications by the RWCU System.

1	5	F	28	0	2	8	29	NA	30	A	31	Operational Event				32
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	
FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION								
1	6	Z	33	Z	34	NA	35	NA	36	LOCATION OF RELEASE						36
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	
ACTIVITY CONTENT RELEASED		AMOUNT OF ACTIVITY		PERSONNEL EXPOSURES		PERSONNEL INJURIES		LOSS OF OR DAMAGE TO FACILITY								
1	7	0	0	0	37	Z	38	NA	39	DESCRIPTION						39
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	
1	8	0	0	0	40	NA	41	NA	42	DESCRIPTION						41
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	
1	9	Z	42	NA	43	DESCRIPTION						43				
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	
2	0	N	44	NA	45	DESCRIPTION						45				
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	
PUBLICITY ISSUED		NRC USE ONLY														

NAME OF PREPARER: M. J. Pastva, Jr. PHONE: 919-457-9521

LER ATTACHMENT - RO # 2-81-45

Facility: BSEP Unit No. 2

Event Date: 4-12-81

This event resulted from unexpected main condenser waterbox tube leakage which occurred due to the falling out of approximately 75-100 waterbox tube plugs. These plugs had been installed on both ends of tubes known to have seawater leakage to prevent that seawater from entering the Condensate System. Prior to this event a unit maintenance outage had been performed that involved the draining of the waterboxes for required work. As a result, a large portion of the installed waterbox tube plugs apparently dried out and became loose. After completion of the outage work, the waterboxes were returned to normal service and the plugs forced out by the circulating water flow and turbulence. Following a routine unit startup, an initial reactor Condensate System conductivity spike was detected by in-plant monitoring equipment and was verified by routine Condensate System chemistry analysis. At this time vessel conductivity was measured within specifications. This initial conductivity spike was adequately dealt with by the condensate filter and polishing system. Hourly chemistry analysis of vessel and reactor feedwater appeared to indicate that the conductivity excursion was short-lived as a result of measured reactor conductivities that were steadily decreasing in numerical value at the time. However, several hours later one of the hourly coolant samples revealed that vessel conductivity had suddenly and unexpectedly exceeded specifications at a measured value of $15.5 \mu\text{mho}/\text{cm}^2$. In response to the observed sudden conductivity spike, a manual reactor scram was initiated. Following the scram and during recovery operation, hourly vessel coolant analysis revealed conductivity peak at $24.8 \mu\text{mho}/\text{cm}^2$. In addition, during this event a maximum chloride concentration of 5 ppm and a pH value of 6.4 - 7.4 were recorded for vessel coolant. By utilization of the RWCU System and a feed and bleed Condensate System lineup to the reactor, the vessel conductivity was then reduced to within specifications. An evaluation of the conductivity excursion experienced by the reactor was then performed by General Electric which led to the establishment of operational guidelines for the startup of the unit following this event.

An inspection of main condenser waterboxes revealed the missing waterbox tube plugs that were previously described in this report. The damaged plugs were replaced with different design plugs utilizing a brass ring and plug construction. The waterboxes were satisfactorily leak checked and were then returned to normal service. It is believed that utilization of the different design waterbox tube plugs will help alleviate the conditions that could lead to future similar events.

o - Rx Conductivity
 x - Natural Conductivity



Vessel in Cold Shutdown - 2200

Rx SURVEYED AT 1305
 Rx Cond. at 1305 was 24.72

POOR ORIGINAL