

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | ALBRF2 | 200-00000-00 | 341111 | 4 | 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T
01 | L | 605000260 | 7052781 | 8 | 060981 | 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

07 | During normal operation, while performing turbine first stage pressure permissive
03 | test (SI 4.1.A-14), switches PS-1-81A, B; and PS-1-91A, B were found an average of
04 | 4.2 percent above the limit of T.S. Table 3.1.A. The greatest out of tolerance
05 | was 5.2 percent. There was no danger to the health or safety of the public. There
06 | were no redundant systems. Previous similar events: BFR0-50-259/79008, 80058;
07 | 260/79016, 79017, 79024, 80057, 80020; 296/79007, 79012, 80030, 80045, 81017.

09 | IA | E | E | INSTRU | S | Z |
10 11 12 13 14 15 16
SYSTEM CODE CAUSE CODE CAUSE SURCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE
17 | 81 | 023 | 01 | T | 0 |
18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
18 | E | F | Z | Z | 000 | Y | N | L | B069 |
19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NRC-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | The Barksdale model B2T-A12SS pressure switch setpoints had drifted. The switches
11 | were reset to prescribed setpoints and SI 4.1.A-14 was successfully completed.
12 | A design change request (DCR 1398) has been initiated to replace these switches with
13 | an analog transmitter with a trip switch.

15 | E | 099 | NA | B | Routine test.
16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION
16 | Z | Z | NA | NA |
17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE
17 | 000 | Z | NA | NA |
18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION
18 | 000 | Z | NA |
19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
PERSONNEL INJURIES NUMBER DESCRIPTION
19 | 000 | NA |
20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION
19 | Z | NA |
20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
PUBLICITY ISSUED DESCRIPTION
20 | N | NA |
21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

NAME OF PREPARER _____ PHONE: _____

LER SUPPLEMENTAL INFORMATION

BFRO-50- 260/81023 Technical Specification Involved Table 3.1.A

Reported Under Technical Specification 6.7.2.a(5)

Date of Occurrence 5/27/81 Time of Occurrence 1415 Unit 2

Identification and Description of Occurrence: SI 4.1.A-14 revealed switches PS-1-81A,B, and PS-1-91A, B above the setpoint limit of T.S. Table 3.1.A.

Switch	Setpoint Found	Switch	Setpoint Found
PS-1-91A	172 psi	PS-1-81A	177 psi
PS-1-91B	172 psi	PS-1-81B	175 psi

Conditions Prior to Occurrence:

Unit 1 refueling outage
Unit 2 at 99%
unit 3 at 96%

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

None

Apparent Cause of Occurrence:

Drift of instrument setpoint. This drift historically seems to occur during times of the year when there are ambient temperature changes.

Analysis of Occurrence:

There was no danger to the health or safety of the public, no release of activity, no damage to the plant or equipment, and no resulting significant chain of events.

Corrective Action:

Setpoints adjusted to prescribed setpoint values and SI 4.1.A-14 successfully completed. Recent revision to SI has lower setpoints.

Failure Data: BFRO-50-259/79008, 80058; 260/79016, 79017, 79024, 80057, 80020; 296/79007, 79012, 80030, 80045, 81017.

*Retention: Period - Lifetime; Responsibility - Document Control Supervisor

*Revision: SA