

DUKE POWER COMPANY
POWER BUILDING
422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

June 17, 1981

TELEPHONE AREA 704
373-4083

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303




Re: Catawba Nuclear Station
Units 1 and 2
Docket Nos. 50-413 and 50-414

Dear Mr. O'Reilly:

Please find attached a final response to Significant Deficiency Report
SD 413-414/80-02.

Very truly yours,


William O. Parker, Jr.

RWO:pw
Attachment

cc: Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

NRC Resident Inspector
Catawba Nuclear Station

IE27
~~IE27~~
S
1/1

S
8106240255

POOR ORIGINAL

CATAWBA NUCLEAR STATION

REPORT NO: SD413-414/80-02

REPORT DATE: June 17, 1981

FACILITY: Catawba Nuclear Station - Units 1 & 2

IDENTIFICATION OF DEFICIENCY:

Solid State Protective Relays and Trip Devices - Deficiency SCR's

DESCRIPTION OF DEFICIENCY:

The deficiency is as described in initial report filed February 29, 1980. In addition, further information was provided to Mr. Victor Stello, NRC/OIE by letter of July 16, 1980, from Mr. D. D. Duvall of Gould-Brown Boveri indicating that the problem had been evaluated further and was determined to be random in nature rather than generic.

CORRECTIVE ACTION:

Based on the manufacturer's evaluation and our own testing and operating experience at Catawba, no equipment changes or corrective action is required.