Central Files



UNITED STATES NUCLEAR REGULATORY COMMISSION REGION IV 611 RYAN PLAZA DRIVE, SUITE 1000 ARLINGTON, TEXAS 76012 10 OCT 1980

Docket No. 99900047/80-02

Westinghouse Electric Corporation Nuclear Components Division, Tampa Plant ATTN: Mr. T. D. Miller Product Assurance Manager PO Box 19218 Tampa, Florida 33686

Gentlemen:

This refers to the QA Program inspection conducted by Mr. L. E. Ellershaw of this office on September 8-12, 1980, of your facility at Tampa, Florida, associated with the fabrication of nuclear steam generators and to the discussions of our findings with you and members of your staff at the conclusion of the inspection.

This inspection was made to confirm that, in the areas inspected, your QA Program is being effectively implemented. The inspection effort is not designed to assure that unique quality requirements imposed by a customer are being implemented; nor to assure that a specific product, component or service provided by you to your customers, is of acceptable quality. As you know, the NRC requires each of its licensees to assume full responsibility for the quality of specific products, components or services procured from others. You should therefore not conclude that the NRC's inspection exempts you from inspections by an NRC licensee or his agents nor from taking effective corrective action in response to their findings.

Areas examined and our findings are discussed in the enclosed report. Within these areas, the inspection consisted of an examination of procedures and representative records, interviews with personnel, and observations by the inspector.

During the inspection it was found that the implementation of your QA Program failed to meet certain NRC requirements. The specific findings and references to the pertinent requirements are identified in the enclosures to this letter.

Please provide us within thirty (30) days of your receipt of this report a written statement containing, (1) a description of steps that have been or will be taken to correct these items, (2) a description of steps that have been or will be taken to prevent recurrence, and (3) the date your corrective actions and preventive measures were or will be completed.

You will note that Item A. of the Notice of Deviation resulted from your continuing failure to assure effective implementation of actions to prevent recurrence of a deviation regarding segregation and identity of welding electrodes being maintained in holding ovens. This deviation was previously identified in Inspection Reports 79-02 and 80-01. Your responses have stated that your practice

8012190 098

Westinghouse Electric Company

allows simultaneous baking and holding of electrodes of different sizes and test numbers provided they are segregated in the ovens in accordance with the maps on the oven doors. In addition, the procedure had been reviewed with all Storeroom attendants. In your response to Report 80-01, you further stated that you believed this was an isolated instance of noncompliance.

The results of this latest inspection, however, serve to identify that your preventive measures have not been effective, and it cannot be considered an isolated instance.

Consequently, in your response, in addition to verifying correction of the specific deviations as requested above, please indicate what actions you have taken or are planning to take which would assure effective implementation of your corrective action commitments.

In accordance with Section 2.790 of the Commission's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter with enclosure and your reply, together with the enclosed inspection report will be placed in the Commission's Public Document Room. If this report contains any information that you believe to be proprietary, it is necessary that you make a written application within thirty (30) days to this office to withhold such information from public disclosure. Any such application must include a full statement of the reasons on the basis of which it is claimed that the information is proprietary, and should be prepared so that proprietary information identified in the application is contained in a separate part of the document. If we do not hear from you in this regard within the specified period, the report will be placed in the Public Document Room.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

. Seyfrit Regional Director

Enclosures:

- 1. Notice of Deviation
- 2. Inspection Report No. 99900047/80-02

2