LICENSEE EVENT REPORT

	LICENSEE EVENT HEFORT
	CONTROL BLOCK:
0 1	P A B V S 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 57 CAT SE
ONT	SOURCE SO 61 DOCKET NUMBER OF 69 EVENT DATE 74 75 REPORT DATE 80 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
0 2	While conducting a redundant channel check for removal from service of the 101C
0 3	chlorine detector for surveillance testing, it was discovered that the 101A and 101B
0 4	detectors' electrolyte was not dripping. Both detectors were declared out of
0 5	service and the 101A detector was tripped. The Control Room Ventilation System was
0 6	isolated from outside air in accordance with Technical Specification 3.3.3.7. This
0 7	was the eighth failure of this type at BVPS.
0 8	
09	SYSTEM CAUSE CAUSE COMPONENT CODE SUBCODE SUBC
	TO LER/RO EVENT YEAR SEQUENTIAL REPORT NO. 17 REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 32
	ACTION FUTURE COMPONENT SHUTDOWN HOURS 22 ATTACHMENT SUBMITTED FORM SUB. PRIME COMP. COMPONENT MANUFACTURER X 18 F 19 Z 20 Z 21 0 0 0 0 Y 23 N 24 A 25 W 0 2 5 26
	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) The fluid tank was under a slight vacuum and the wick and glass orifice were
10	
11	clogged. The wick and orifice were cleaned and the top vent filter was loosened.
1 2	Engineering has been requested to evaluate this system due to the repeated
1 3	failures.
14	
7 8	FACILITY STATUS OTHER STATUS OF DISCOVERY DESCRIPTION (32) E 28 0 7 5 29 N/A B 31 Redundant channel check
	ACTIVITY CONTENT ELEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36
7 8	Z 33 Z 34 N/A
17	NUMBER TYPE DESCRIPTION (39) N/A N/A 80
1 8	PERSONNEL INJURIES NUMBER DESCRIPTION 1 N/A
, ,	LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION
1 8	Z 42 N/A
20	Z 42 N/A

Attachment To LER 80-107/03L Beaver Valley Power Station Duquesne Light Company Docket No. 50-334

No further information is available or needed to satisfy the reporting requirement.