(7-77)	LICENSEE EVENT REPORT
•	CONTROL BLOCK: PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION
0 1	A L J M F 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5 5 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58
CON'T	REPORT L 6 0 5 0 0 0 3 4 8 7 1 1 2 8 8 0 8 0 1 0 6 8 1 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
0 2	At 0055 on 11/28/80, while performing FNP-1-STP-11.7 (Verifying RHR Relief Valve
0 3	Isolation Valves Are Open) the loop suction valve for A train RHR closed which
0 4	resulted in A train RHR being inoperable. Tech. Spec. 3.9.8 requires at least one
0 5	RHR loop to be in operation. Tech. Spec. 3.9.8 action statement requirements were
0 6	met. B train RHR was placed in service at 0059 on 11/28/80. Health/safety of the
0 7	public were not affected.
0 8	9 80
0 9	SYSTEM CAUSE CODE SUBCODE COMPONENT CODE SUBCODE SUBCO
	17 REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 32
-	ACTION FUTURE ON PLANT SHUTDOWN HOURS 22 ATTACHMENT FORM SUB. SUPPLIER SUPP
10	I & C troubleshooting revealed that dirry contacts on a card in the circuitry for
11	pressure transmitter (PT) 402 caused the valve to receive an erroneous close signal.
1 2	The card was cleaned and proper operation of the valve was verified at 1300 on
13	11/28/80.
14	50
1 5	FACILITY STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 H 28 0 0 0 29 NA B 31 Performance of surveillance test 30 METHOD OF DISCOVERY DESCRIPTION 32 B 31 Performance of surveillance test 80
	ELEASED OF RELEASE AMOUNT OF ACTIVITY 35 Z 33 Z 34 NA PERSONNEL EXPOSURES AMOUNT OF ACTIVITY 35 NA NA NA 80
1 7 8	NUMBER TYPE DESCRIPTION (39) NA NA NA NA NA NA NA N
1 8	NUMBER DESCRIPTION 41) O O O O NA 9 11 12 LOSS OF OR DAMAGE TO FACILITY (43)
1 9	TYPE DESCRIPTION Z 42 NA 9 10 NBC USE ONLY
2 0	ISSUED DESCRIPTION (45) NA 68 69 80
	NAME OF PREPARER W. G. Hairston, III PHONE: (205) 899-5156