

## LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	A	L	B	R	F	3	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4	5
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34
LICENSEE CODE		LICENSE NUMBER										LICENSE TYPE				CAT											

0	1	L	6	0	5	0	0	0	2	9	6	7	0	1	2	7	8	1	8	0	2	1	3	8	1	9
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33
REPORT SOURCE		DOCKET NUMBER										EVENT DATE				REPORT DATE										

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During normal operation, containment atmosphere hydrogen analyzer, 3-H<sub>2</sub>M-76-94,

0 3 | was removed from service for two hours and 25 minutes for maintenance. (T.S. 3.7.H.2)

0 4 | The analyzer was declared inoperable during this period of time. Redundant

0 5 | analyzer 3-H<sub>2</sub>M-76-104 was operable. There was no effect on the health or safety

0 6 | of the public. Previous events: BFRO-50-296/8106.

0 7 | \_\_\_\_\_

0 8 | \_\_\_\_\_

0	9	I	C	11	X	12	Z	13	I	N	S	T	R	U	14	C	15	Z	16	17	8	1	—	0	0	5	—	0	3	L	—	0
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39
SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE										COMP SUBCODE		VALVE SUBCODE		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.				
LER/RO REPORT NUMBER		ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER														
X		Z		Z		Z		0		0		Y		N		L		B														

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | Water had collected in a sensing line at 3-FIC-76-94, a Brooks Model 1350.

1 1 | The water was removed from the lines and 3-H<sub>2</sub>M-76-94 was returned to service.

1 2 | No recurrence control action is planned.

1 3 | \_\_\_\_\_

1 4 | \_\_\_\_\_

1	5	E	28	0	7	6	29	NA	30	A	31	Discovered during maintenance.	32
7	8	9	10	11	12	13	14	15	16	17	18	19	20
FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION					

1	6	Z	33	Z	34	NA	35	NA	36
7	8	9	10	11	12	13	14	15	16
ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE			

1	7	0	0	0	17	Z	38	NA	39
7	8	9	10	11	12	13	14	15	16
PERSONNEL EXPOSURES		TYPE		DESCRIPTION					

1	8	0	0	0	40	NA	41
7	8	9	10	11	12	13	14
PERSONNEL INJURIES		DESCRIPTION					

1	9	Z	42	NA	43
7	8	9	10	11	12
LOSS OF OR DAMAGE TO FACILITY		DESCRIPTION			

2	0	N	44	NA	45	NRC USE ONLY							
7	8	9	10	11	12	13	14	15	16	17	18	19	20
PUBLICITY ISSUED		DESCRIPTION											

8102280539 OF PREPARER

PHONE

LER SUPPLEMENTAL INFORMATION

AFB 296 / 8105 Technical Specification involved 3.7.H.2  
Under Technical Specification 6.7.2.b(2)  
Date of Occurrence 1/27/81 Time of Occurrence 1230 Unit 3

Identification and Description of Occurrence:

Containment atmosphere hydrogen analyzer, 3-H<sub>2</sub>M-76-94, was removed from service for two hours and 25 minutes for maintenance.<sup>2</sup> The analyzer was declared inoperable during this period.

Conditions Prior to Occurrence:

Unit 1 at 98% power.

Unit 2 at 99% power.

Unit 3 at 76% power.

Actions specified in the Technical Specification Surveillance Requirements met  
due to inoperable equipment. Describe.

None

Apparent Cause of Occurrence:

Water in sensing lines

Severity of Occurrence:

There was no danger to the health or safety of the public, no release of activity, no damage to plant or equipment and no resulting significant chain of events.

Corrective Action:

Water removed from the sensing lines and the analyzer returned to service.

File number:

BFRO-50-296/8106.

Retention: Period - Lifetime; Responsibility - Administrative Supervisor

Remarks:

