

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 A L B R F 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T
0 1 REPORT SOURCE L 6 0 5 0 0 0 2 5 9 7 0 1 3 1 8 1 8 0 2 0 9 8 1 9
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During steady state operation, pH of the reservoir near the plant was found to be
0 3 in excess of the allowable discharge limit of 9.0 pH. Monitoring was in progress
0 4 to support the routine release of spent demineralizer regenerants. Technical
0 5 Specification: ETS 2.2.1. There was no danger to the public. No previous
0 6 occurrences.
0 7
0 8
7 8 9

0 9 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE
P C 11 X 12 Z 13 Z Z Z Z Z Z 14 Z 15 Z 16
7 8 9 10 11 12 13 14 15 16 17 18 19 20
17 LER NO REPORT NUMBER 21 EVENT YEAR 22 8 1 23 24 0 0 5 25 26 27 28 0 4 29 30 T 31 32 0
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS 22 ATTACHMENT SUBMITTED NPRO-4 FORM SUB PRIME COMP SUPPLIER COMPONENT MANUFACTURER
X 18 X 19 Z 20 Z 21 0 0 0 0 Y 23 N 24 Z 25 Z 9 9 9 26
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The cause of the excess pH value is unknown. However, it appears to be caused by
1 1 an upstream source. The discharge of spent regenerants was stopped. A temporary
1 2 program was established to monitor the reservoir pH. No recurrence control required.
1 3
1 4
7 8 9

1 5 FACILITY STATUS 28 E 29 0 9 8 30 OTHER STATUS NA 31 METHOD OF DISCOVERY B 32 DISCOVERY DESCRIPTION Radiochemical personnel
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
1 6 ACTIVITY CONTENT RELEASED OF RELEASE 33 Z 34 Z 35 AMOUNT OF ACTIVITY NA 36 LOCATION OF RELEASE NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
1 7 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 37 0 0 0 38 Z 39 NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
1 8 PERSONNEL INJURIES NUMBER DESCRIPTION 40 0 0 0 41 NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
1 9 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION 42 Z 43 NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
2 0 PUBLICITY ISSUED DESCRIPTION 44 N 45 NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

LER SUPPLEMENTAL INFORMATION

BFPO-00- 259 / 8105 Technical Specification Involved ETS 2.2.1

Reported Under Technical Specification 5.6.3.b (App B)

Date of Occurrence 1/31/81 Time of Occurrence 1645 Unit 1, 2, and 3

Identification and Description of Occurrence:

pH of the reservoir near Browns Ferry Nuclear Plant was found to be in excess of the allowable discharge limit of 9.0. pH monitoring was being conducted at the time to support the discharge of spent demineralizer regenerants.

Conditions Prior to Occurrence:

Unit 1 at 1078 MWe.

Unit 2 at 960 MWe.

Unit 3 at 965 MWe.

Action specified in the Technical Specification Surveillance Requirements met due to operable equipment. Describe

None

Apparent Cause of Occurrence:

Unknown. The high pH appears to have been caused by an upstream source.

Analysis of Occurrence:

There was no damage to plant equipment. There was no activity release, no personnel exposure or injury and no danger to the health or safety of the public.

Corrective Action:


The discharge of the demineralizer regenerants was stopped. Raw water samples from around the plant were taken and analyzed for pH.

Failure Data:

None

*Attention: Period - Lifetime; Responsibility - Administrative Supervisor

*Revision:



SUPPLEMENTAL WHEELER RESERVOIR pH DATA

| <u>DATE</u> | <u>TIME</u> | <u>pH (1)</u> | |
|-------------|-------------|---------------|--------------------------|
| 12/2/80 | - | 7.1 | |
| 12/9/80 | - | 7.7 | |
| 12/16/80 | - | 7.2 | |
| 12/27/80 | - | 7.2 | |
| 12/30/80 | - | 7.1 | |
| 1/7/81 | - | 7.4 | |
| 1/13/81 | - | 7.3 | |
| 1/23/81 | - | 6.9 | |
| 1/29/81 | - | 8.5 | |
| 1/30/81 | 0045 | 8.7 | Biothermal stream (2) |
| 1/30/81 | 0845 | 8.9 | Biothermal stream (2) |
| 1/31/81 | 0250 | 9.0 | Biothermal stream (2) |
| 1/31/81 | 1645 | 9.4 | Biothermal stream (2) |
| 1/31/81 | 1745 | 9.3 | Biothermal stream (2) |
| 1/31/81 | 2120 | 9.1 | * upstream from plant |
| 2/1/81 | 2245 | 9.0 | |
| 2/1/81 | 2310 | 8.9 | |
| 2/1/81 | 0800 | 9.0 | |
| 2/1/81 | 0900 | 8.7 | |
| 2/1/81 | 1145 | 8.7 | |
| 2/1/81 | 1145 | 9.0 | *intake bay |
| 2/1/81 | 1145 | 8.8 | * down stream from plant |
| 2/1/81 | 1545 | 8.8 | |
| 2/1/81 | 2015 | 8.5 | |
| 2/1/81 | 2330 | 8.5 | |
| 2/2/81 | 0330 | 8.2 | |
| 2/2/81 | 0850 | 8.3 | |
| 2/2/81 | 1250 | 8.2 | |
| 2/2/81 | 1510 | 8.1 | |
| 2/2/81 | 2045 | 8.1 | |
| 2/2/81 | 2310 | 8.2 | |
| 2/3/81 | 0420 | 8.1 | |
| 2/3/81 | 0800 | 8.3 | |
| 2/3/81 | 1300 | 8.3 | |

SUPPLEMENTAL WHEELER RESERVOIR pH DATA

| <u>DATE</u> | <u>TIME</u> | <u>pH</u> |
|-------------|-------------|-----------|
| 2/3/81 | 1510 | 8.3 |
| 2/3/81 | 2130 | 8.1 |
| 2/4/81 | 0130 | 8.0 |

- (1) Unless otherwise noted, sample obtained from raw water systems within plant.
- (2) Biothermal stream analyzed during release of spent regenerants. Source of the stream is raw water cycled through biothermal research facility.