(7-77)	LICENSEE EVENT REPORT
•	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	C O F S V 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 2 0 4 57 CAT 58 5
ON'T	SOURCE 1 6 0 5 0 0 2 6 7 7 0 3 1 7 8 1 3 0 4 1 6 8 1 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
0 2	During March testing, five of the twelve helium circulator seal malfunction pressure
0 3	differential switch units were discovered to have a trip point outside the limits of
0 4	LCO 4.4.1, Table 4.4-3. These are reportable per Fort St. Vrain Technical Specifica-
0 5	tions AC 7.5.2(b)1 and AC 7.5.2(b)2. No effect on public health or safety. Redun-
0 6	dant systems available and operable. Similar reports are RO 77-47, Final and Prelimi-
0 7	nary reports RO 78-27, 79-32, 79-56, 80-07, 80-16, 80-20, 80-26, 80-34, 80-41, 80-51,
0 B	80-72, 81-606, and 81-016.
0 9	CODE SUBCODE COMPONENT CODE SUBCODE SU
	TO REPORT VEAR REPORT NO. 17 REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 31 32 28 29 30 31 31 32 28 29 30 31 31 32 28 29 30 31 32 28 29 30 31 32 32 32 32 32 32 32 32 32 32 32 32 32
	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
1 0	ITT Barton Model 289 pressure differential switches failed to actuate at trip point
11	due to dirt accumulation in electrical switches. Affected switches re-adjusted to
1 2	proper trip points. Trip settings being checked on a monthly basis. Redesign of
1 3	system being evaluated.
7 8	FACILITY SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION (32)
1 5	E 28 0 6 9 29 N/A C 31 Operability Test
	RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) Z 33 Z 34 N/A PERSONNEL EXPOSURES AMOUNT OF ACTIVITY (35) N/A 45
1 7	NUMBER TYPE DESCRIPTION (39) O O O O O O O O O O O O O O O O O O O
1 B	NUMBER DESCRIPTION (41) O O O O O N/A Solution (41) 12 LOSS OF OR DAMAGE TO FACILITY (43)
1 9	TYPE DESCRIPTION Z 42 N/A 30
20	PUBLICITY ISSUED DESCRIPTION 45 NAC USE ONLY NAC USE ONLY
, 8	NAME OF PREPARER 44/11 PHONE: (303) 785-2224
8100	6030251