THE CLEVELAND ELECTRIC ILLUMINATING COMPANY

P.O. BOX 97 PERRY, OHIO 44081

TELEPHONE (216) 259-3737 FROM CLEVELAND: 479-1260 ADDRESS-10 CENTER ROAD

TELEX: 241599 ANSWERBACK: CEI PRYO

Serving The Best Location in the Nation PERRY NUCLEAR POWER PLANT

January 19, 1990 PY-CEI/NRR-1123 L

U.S. Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

> Perry Nuclear Power Plant Docket No. 50-440 LER 89-032

Dear Sir:

Enclosed is Licensee Event Report 89-032 for the Perry Nuclear Power Plant.

Very truly yours,

Al Kaplan Vice President Nuclear Group

AK/njc

Enclosure: LER 89032

cc: T. Colburn NRC Resident Inspector

> U.S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, Illinois 60137

9001250368 900119 PDR ADOCK 05000440 PDC

Al Kaplan

VICE PRESIDENT NUCLEAR GROUP

NAC FOI	M 366			•		LICE	NS	EE	EVE	NT	REP	ORT (LER)	EGULATO	IV COMMIS	SIDN	ESTIMA INFORM COMME AND RI REGUL THE FI OF MAT	TED NATE NTS EPOR ATOM NPERINAGE	APPR BURDEN DN COLL REGARD TS MANJ IV COMM WORK RI MENT AN	OVED EXPI PER ECTIO NG BU ISSION EDUCT	OME N RES 4 RESPO N REO IRDEN NT BR I WASI ION PI	ID. 3150-0 /30/92 INSE TO IUEST SI ESTIMAT ANCH (P. HINGTON ROJECT VASHING	COM 0.0 H E TO 6301, 0.0C (3150 TON,	NLY WT RS FOI THE RE U.S. NL 20555. 01041. DC 205	H THIS RWARD ICORDS ICLEAR AND TO OFFICE 13.																					
FACILITY	NAME	(1)																DO	CKET NU	MBER	(2)		F	PAC	(3)																					
Per	ry l	Nu	cle	a	r P	owe	r P	lan	it,	Un	it l							0	1510	10	04	141	q	OF	0 14																					
	Divi	is	ion	Ind	3 B	att	ery	Lo	w I	le	ctro	lyte	Tempe	ratur	e Caus	se ł	ligh I	Pre	ssure	Co	re	Spray	y																							
EVENT DATE (B)				LER NUMBER IS					REPORT DATE (7)				OTHER FACILITIES INVO																																	
MUNTH	DATH DAY YEAR			+		NUMBER				NUMBER	MONTH		TEAN							0 11	5101	0 1	0,																							
1 2	2] 3	2	8	9 8 9 - 0 3 2 - 0 0 0 1 1 9 9 0							0 15 10 10 10 1 1 1																																			
00	RATING	,	T		THE	REPO	RT 18	-	ITTEC	PU	BUANT	TO THE REQUIREMENTS OF		ENTS OF	O CFR &: /Check and or more a			• • •	te tollow	ng/ (11)																									
			0	20.405(a)(1)(i) 20.405(a)(1)(i) 20.405(a)(1)(ii) 20.405(a)(1)(iii) 20.405(a)(1)(iii) 20.405(a)(1)(iii)				20.406(c) 50.36(c)(1) 50.36(c)(2) 50.73(c)(2)(i) 50.73(c)(2)(ii) 50.73(c)(2)(ii) 50.73(c)(2)(iii)				80.7363(2)((v) 80.7363(2)(v) 80.7363(2)(vi) 60.7363(2)(vii)(6) 90.7363(2)(vii)(6) 90.7363(2)(vii)(6) 90.7363(2)(x)					73.71(b) 73.71(c) OTHER (Specify in Abstract below and in Test, NRC Form 366A)																													
													CONTAC			*****																														
Hen	ry L		He	gra	at,	Co	mpl	iar	ice	En	igine	er, E	xtens	ion 6	855 DESCRIBI	ED IN		-	2 11	001 16	2 1	5191	-1	317	1 31 7																					
CAUSE	SYSTE	~	co	MPO	NEN	•	MANUFAC			MANUFAC REPO		REPORTABLE TO NPRDS				CAUSE	SYSTEM	co	COMPONENT		MANUFAC TURER		Rap	EPORTABLE TO NPRDS																						
x	ч	I	F	U	ULI		G1118		G11817		G11817		G11817		G11817		G11817		G111817		G11817		G11817		G11817		G11811		G11817			N				1				11	1					
x	Ky 1	M	TI	C	U		F	113	310		N								11	1																										
		-						SUPP	LEME	NTA	REPOR	EXPECT	ED (14)					_		PECTE	D	MON	TH	DAY	YEAR																					
7.6	5 (If ym		-	• • •	PEC	TED SU		SION	DATE	,			X NO						SUL SUL	TE I	0N 6)			1																						
Or te Di Sp ir HF 1e	Dec Decificoper CS sevela	ce ra lo f1 ra sy s.	mbe tur n 3 cat ble ste	r e to io	22 wa oat ons op	, 1 s di ter: rec peri eral	989 isc y w qui ato	, a ove as red rs wh	nd red ino th too en	on t pe k ba	Janu o be rable High actio ttery	ary below below due Prese ons to y elec	5, 19 w Tec to m sure o rai ctrol	90, Un hnica hainte Core se ba yte to	nit 2 1 Spec nance Spray ttery empera	Div ifi bei (HF roc	vision leation leation PCS) so om ten res re	n 3 on erf sys npe etu	bat limi orme tem ratu rned	tery ts. d, 1 to 1 re a to	y el Be Plan be d and acc	ectr caus t Te ecla decl epta	oly e U chn red are ble	te nit ical d th	1 L																					

The cause of the December 22, 1989 event was Equipment Failure, specifically, a blown fuse in the battery room ventilation duct heater circuitry. Loss of the heater combined with the low heat load in the Unit 2 Division 3 battery room resulted in the battery electrolyte temperature decrease. The January 5, 1990 event was caused by a temperature control valve malfunction which allowed excess cooling water to the battery room ventilation system at a time when cooling water was not desired. This also resulted in the decrease of battery electrolyte temperature.

To prevent recurrence, the blown fuse for the ventilation duct heater was replaced and the heater checked to ensure proper operation. The temperature control valve actuator hydromotor pump was replaced and the valve checked for proper operation. Additionally, operators revised the plant equipment round procedure to include checking battery room temperature once per shift, and a design change proposal to install low temperature alarm instrumentation for the battery rooms is presently being evaluated. As part of the established requalification training program, all plant licensed operators will be instructed on the lessons learned from this event.

LICENSEE EVENT REPORT	APPROVED OMS NO. 3150-0104 EXPIRES: 4/30/92 ESTIMATED BURDEN PER RESPONSE TO COMPLY WTH THIS INFORMATION COLLECTION REQUEST: 500 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P&SD). U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20505. AND TO THE FARERWORK REDUCTION PROJECT DISDOIDAL OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.										
FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)						PAGE (3)			
		YEAR		NUMBER	AL .	NUMBER		T			
Perry Nuclear Power Plant, Unit 1	0 15 10 10 10 14 14 10	8 9	9 - 0 3 2		2 -	010	0 2	OF	0 4		
TEXT IN more space is required, use additional NRC Form JBEA's/ (17)											

On December 22, 1989, and on January 5, 1990, the High Pressure Core Spray [BG] (HPCS) system was declared inoperable due to the inoperability of the associated Division 3 battery [EJ]. At the time of both events, the plant was in Operational Condition 1 (Power Operation) at approximately 100 percent of rated thermal power with the Reactor Pressure Vessel [RPV] at saturated conditions at approximately 1000 psig. The Unit 1 Division 3 battery [BTRY] was inoperable due to a low pilot cell voltage and a cell with a slow electrolyte leak.

On December 22, 1989, at 1027, Unit 2 Division 3 battery electrolyte temperature was discovered to be approximately 69 degrees Fahrenheit (F). In accordance with Technical Specification action requirements associated with D.C. electrical power sources, operators declared High Pressure Core Spray (HPCS) system and the Division 3 Diesel Generator inoperable and initiated troubleshooting efforts to determine the cause of the low temperature. Maintenance troubleshooting revealed a blown power fuse [FU] in a heater circuit for the MCC, Switchgear, and Miscellaneous Electrical Equipment Areas HVAC system [VI]. The fuse was replaced and HPCS/Division 3 operability was declared on December 23, 1989 at 0445, after the battery electrolyte temperature increased above 72 degrees F. All action statements of associated Technical Specifications were satisfied.

On January 5, 1990, at 0241, train "B" of the battery room ventilation system was shifted to recirculation mode due to Unit 2 Division 3 battery room temperature decreasing to 73 degrees F. The ventilation system shift was ineffective due to a malfunctioning temperature control valve [TCV] which, unknown to operators, was the initial cause of the decrease in battery room temperature. The temperature control valve remained closed approximately 50 percent instead of 100 percent as it was supposed to. The failure of the temperature control valve to completely close allowed cooling water to continue flowing to the ventilation system cooler while temperature conditions required cooling flow to be secured. As a result, the Unit 2 Division 3 battery room temperature continued to drop instead of increase as was intended. At approximately 1010, the Unit 2 Division 3 battery room temperature was discovered to be below 72 degrees F and the battery electrolyte temperature was also below 72 degrees F. Operators declared the HPCS system inoperable at that time. At 1024 operators shifted the battery room ventilation system to train "A" in recirculation mode which caused battery room temperature to increase. On January 5, 1990 at approximately 2130 Unit 2 Division 3 battery electrolyte temperature had risen to 72.9 degrees F and battery room temperature had risen to 76 degrees F. Operators then declared Unit 2 Division 3 battery, Division 3 diesel generator and HPCS system operable.

The cause of the December 22, 1989 event was equipment failure, specifically, a blown power fuse in the ventilation duct heater circuitry. The loss of the heater combined with the low heat load in the Unit 2 Division 3 battery room resulted in the battery electrolyte temperature decreasing below the Technical Specification limit. The absence of a battery room low temperature alarm to alert operators to low temperature conditions is considered to be a contributing factor.

LICENSEE EVENT REPOR TEXT CONTINUATION	APPROVED OME NO. 3150-0104 EXPIRES 4/30/82 ESTIMATED BURDEN 13 R RESPONSE TO COMPLY WTH THIS INFORMATION COLLECTION REQUEST NOL HRS. FORMARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANGEMENT BRANCH (P-30). U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20565. AND TO THE FARERWORK REDUCTION FROJECT (DISDOILG). OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.							
FACILITY NAME (1)	DOCKET NUMBER (2)		PAOS (3)					
		VEAR SEQUENTIAL REVISE NUMBER NUMBER	-					
Perry Nuclear Power Plant, Unit 1	0 15 10 10 10 44410	819 - 01312 - 010	0 013 01 014					
TEXT if more appear is required, use additions' MRC form 3864 to (17) The cause of the January 5, 1990 control valve in the Control Comp close completely when its control operators were aware of decreasin took action to shift to the reci:	event was equipment of plex Chilled Water [Ku l signal required full ng Unit 2 Division 3 b rculation mode which a	malfunction. A temp M] (CCCW) system did l closure. Although battery room tempera should have prevente	perature d not h ature and ed					

exceeding the Technical Specification limit for electrolyte temperature, the valve malfunction resulted in continued cooling of the Unit 2 Division 3 battery room. Again the absence of a battery room low temperature alarm to alert operators to low temperature conditions is considered to be a contributing factor as this would have provided more time to evaluate system conditions and take corrective action.

The objective of the Division 3, 125-volt dc power system is to provide a continuous and independent 125-volt dc source of control and motive power as required for HPCS system logic, HPCS diesel generator control and protection, and all Division 3 related 125-volt dc control. Upon loss of these control power systems, the HPCS system is required by Technical Specification to be declared inoperable.

The HPCS system pumps water through a peripheral spray ring sparger mounted above the reactor core. Coolant is supplied over the entire range of system operation pressures. The primary purpose of HPCS is to maintain reactor vessel inventory after small breaks which do not depressurize the reactor vessel. HPCS also provides spray cooling heat transfer during leaks in which core uncovery is calculated. During the periods of time the HPCS system was declared inoperable, the Automatic Depressurization System and Low Pressure Core Spray, as well as the Low Pressure Coolant Injection Systems were operable ensuring adequate core cooling as described in Chapter 15 of the Updated Safety Analysis Report. Additionally, although the batteries were required to be declared inoperable, the HPCS system was not removed from service and would have automatically initiated if required. Engineering calculations indicate that the Unit 2 Division 3 battery would perform its intended function with electrolyte temperature as low as 65 degrees F. Therefore, these events are not considered to be safety significant.

One other previous event involving low battery electrolyte temperature was documented by LER 87-008. A faulty thermostat had caused Division 1 battery electrolyte temperature to be less than 72 degrees F. The Division 1 battery room thermostat was replaced. Additionally, to address a delay by maintenance personnel in notifying the control room of their findings, maintenance personnel were counseled to ensure prompt notification of the Unit Supervisor if Technical Specification acceptance criteria is exceeded. These corrective actions could not have prevented the December 22, 1989 and January 5, 1990 events.

LICENSEE EVENT REPORT TEXT CONTINUATION	L NUCLEAR REQULATORY COMMISSION	ESTINU INFOR COMMI AND R REGUL THE P OF MA	ATED MATI ENTS IEPOP ATO APEP NAGI	APPROV EURDEN P ION COLLEC REGARDING ITS MANAGE RY COMMISS IWORK RED IMENT AND	IOVED DME NO. 3150-0104 EXPIRES 4/30/02 V PER RESPONDE TO COMPLY WTH THIS LECTION REQUEST. 50.0 HRS. FORWARD ING BURDEN ESTIMATE TO THE RECORDS AGENENT BRANCH (P430), U.S. NUCLEAR AISSION WASHINGTON, DC 20555, AND TO EDUCTION PROJECT (3150-0104), OFFICE ND BUDGET, WASHINGTON, DC 20503.					
FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)				T	PAGE (5			
		YEAR		NUMBER	REVISIO		TT			
Perry Nuclear Power Plant, Unit 1	0 15 10 10 10 14 14 10	8 9	-	0 3 2	- 010	014	OF	0 14		
Text # more used a required out additions WHC form JBA 2017 To prevent recurrence, on December room ventilation duct heater circ	r 23, 1989, the blow uit was replaced and	n pov volt	ser tag	fuse e and	for the current	batt	ery			

readings were taken to ensure the heater was working as designed. On January 12, 1990, the CCCW temperature control valve actuator hydromotor pump was replaced due to internal leakage, and subsequently the temperature control valve was tested satisfactorily in the system. Additionally, operators revised the plant equipment round procedure to include checking battery room temperatures once per shift. Finally, a previously submitted design change proposal to install low temperature alarm instrumentation for the battery room is presently being evaluated. As part of the established requalification training program, all plant licensed operators will be instructed on the lessons learned from this event.

Energy Industry Identification System Codes are identified in the text as [XX].