

Appendix
Notice of Violation

Maine Yankee Atomic Power Company

Docket No. 50-309

Based on the results of an NRC inspection conducted on May 16, 1980 of the shipment of radioactive waste which was shipped from your facility on or about May 14, 1980, it appears that one of your activities was not conducted in full compliance with federal regulations and the conditions of your NRC facility license DPR-36 as indicated below.

10 CFR 71.5 prohibits delivery of licensed material to a carrier for transport unless the licensee complies with applicable regulations of the Department of Transportation in 49 CFR Parts 170-189.

49 CFR 173.392(c)(8) requires that the outside of low specific activity radioactive materials transported in a sole use vehicle must be stencilled or otherwise marked "Radioactive LSA".

Contrary to the above, on or about May 14, 1980, the licensee delivered a package of low specific activity (LSA) radioactive licensed material to a carrier for transport to the waste burial site on a tractor-trailer assigned for sole use and upon arrival at the burial site on May 16, 1980, the outside of the package (a Model CN5I-21-300-2 shipping cask) was not stencilled or otherwise marked "Radioactive-LSA" to identify the contents.

This is a Severity Level IV noncompliance.

8011210363

U.S. NUCLEAR REGULATORY COMMISSION
OFFICE OF INSPECTION AND ENFORCEMENT

Region I

Report No. 50-309/80-13

Docket No. 50-309

License No. DPR-36 Priority _____ Category _____

Licensee: Maine Yankee Atomic Power Company
25 Research Drive
Westborough, Massachusetts

Facility Name: Maine Yankee

Inspection at: Barnwell, South Carolina Burial Site

Inspection conducted: May 16, 1980

Inspectors: (See Attached Report Cover Sheet)

date signed

date signed

date signed

Approved by: (See Attached Report Cover Sheet)

date signed

Inspection Summary: (See Attached Report Cover Sheet)