

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 A L B R F 3 2 0 0 - 0 0 0 0 0 0 0 0 3 4 1 1 1 1 4 5
7 8 9 14 15 25 26 30 37 CAT 38

CON'T
0 1 L 6 0 5 0 0 0 2 9 6 7 1 0 1 7 8 0 8 1 1 1 4 8 0 9
7 8 60 61 66 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 2 During normal operation while performing SI 4.2.B-5, Drywell High Pressure, switch
0 3 2 on PS-64-58B operated at 2.07 psig 0.07 psig above T.S. table 3.2.B limit. There
0 4 was no effect on the health and safety of the public. Redundant switches were
0 5 operable. Previous event: 260/7919.
0 6
0 7
0 8

0 9 I A 11 E 12 E 13 I N S T R U 14 S 15 Z 16
9 10 11 12 13 18 19 20
17 LER/RO REPORT NUMBER 8 0 23 0 4 2 27 0 3 30 L 31 0 32
21 22 23 24 26 27 28 29 30 31 32
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB PRIME COMP SUPPLIER COMPONENT MANUFACTURER
E 18 Z 19 Z 20 Z 21 0 0 0 0 Y 23 N 24 L 25 S 3 8 2 47
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 Model 12NAA4 drifted out of tolerance. The switch was inspected, recalibrated and
1 1 functionally tested for repeatability. No recurrence control action is planned
1 2 due to low random failure rate.
1 3
1 4

1 5 E 28 0 9 7 29 NA 30 B 31 SI Testing 32
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47
FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE
1 6 Z 33 Z 34 NA 35 NA 36
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION
1 7 0 0 0 37 Z 38 NA 39
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47
PERSONNEL INJURIES NUMBER DESCRIPTION
1 4 0 0 0 40 NA 41
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION
1 9 Z 42 NA 43
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47
PUBLICATION ISSUED DESCRIPTION
2 0 N 44 NA 45
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

NRC USE ONLY

NAME OF PREPARER

PHONE

8011210 606

LER SUPPLEMENTAL INFORMATION

BFRO-50- 296 / 8042 Technical Specification Involved Table 3.2.B

Reported Under Technical Specification 6.7.2.b(2)

Date of Occurrence 10/17/80 Time of Occurrence 1430 Unit 3

Identification and Description of Occurrence:

While performing SI 4.2.B-5, Drywell High Pressure, switch 2 on PS-64-58B operated .07 psig above T.S. table 3.2.B limit. The limit is 2.00 psig.

Conditions Prior to Occurrence:

Unit 1 at 98% power

Unit 2 at refueling

Unit 3 at 97% power

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

Returned to service within 24 hours.

Apparent Cause of Occurrence:

Instrument Drift.

Analysis of Occurrence:

There was no damage to plant equipment. There was no activity release, no personnel exposure or injury and no danger to the health or safety of the public.

Corrective Action:

Inspected switch contacts, recalibrated and functionally tested for repeatability.

Failure Data:

260/7919

*Retention: Period - Lifetime; Responsibility - Administrative Supervisor

*Revision: 