	Unit 3 LICENSEE EVENT REPORT Report No. 3-81-03/1T
0	CONTROL BLOCK:
0 1	P A P B S 3 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 57 CAT SB
0 1 7 8	SOURCE L 6 0 5 0 - 0 2 7 8 7 0 1 1 3 8 1 8 0 1 2 7 8 1 9
0 2	During a Surveillance Test with the unit at full power, an oil leak of
0 3	about 3 to 5 GPM was discovered on the oil supply line to the HPCI
0 4	turbine manual/overspeed trip mechanism. If HPCI turbine had started
0 5	with oil leaking from the line, oil would still have been supplied to
0 6	the bearings for about 30 minutes at reduced pressure. At that point a
0 7	turbine bearing low pressure alarm would have been received. Remaining
0 8	ECCS systems were immediately verified to be operable.
0 9	SYSTEM CAUSE CAUSE COMPONENT CODE SUBCODE SUBC
	17 REPORT 18 1
	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
110	The cause was determined to be a ruptured diaphragm on the Robertshaw
1 1	oil pressure control valve Model VC-210. A new diaphragm was installed
1 2	in the valve and the system satisfactorily tested and returned to
1 3	service on January 13, 1981.
1 4 8	9 80
	STATUS SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 B 31 Surveillance Test
1 6 AF	CTIVITY CONTENT ILEASED OF RELEASE AMOUNT OF ACTIVITY 35 Z 33 Z 34 N/A N/A N/A SO SO SO SO SO SO SO SO SO S
1 7 8	PERSONNEL EXPOSURES NUMBER O O O O O O O O O O O O O O O O O O O
1 8	PERSONNEL INJURIES NUMBER DESCRIPTION 41 O O O O O O N/A
1 9	SO TOPS OF OR DAMAGE TO FACILITY (3) TYPE DESCRIPTION N/A
2 0	PUBLICITY SSUED DESCRIPTION 45 N/A N/A N/A N/A N/A N/A N/A N/
81	02100355 M. J. Cooney (215) 841-5020