

CONTROL BLOCK: | | | | | | | (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
---	---

REPORT SOURCE

L	6	0	5	0	0	0	2	6	7	7	0	1	0	6	8	1	8	0	2	0	3	8	1	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 9

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE

I B 11 X 12 X 13 I N S T R U 14 S 15 Z 16

LER RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.	
17		8	1	0	0	3	0	3	L		0
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED	
A	18	Z	19	Z	20	Z	21	0	0	0	0
NPRD-4 FORM SUB		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER							
N	24	N	25	G	0	6	3				

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The cause of the channel inoperability was a blown fuse in switch module, Model SW-2D.

1 1 No cause for the fuse blowing could be found. The fuse was replaced and the channel

1 2 returned to service. The fuse is a 0.5 amp miniature and has operated with no prob-

1 3 lems since replacement. Public Service Company Nuclear Projects Department requested

1 4 to evaluate circuit design to determine if blown fuse indication is feasible.

FACILITY STATUS % POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)

1 5 G (28) 0 0 0 (29) N/A B (31) Routine Test Observation

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 2 33 7 34 N/A

AMOUNT OF ACTIVITY (35)

LOCATION OF RELEASE (36)

N/A

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	37	Z	38	N/A	39

PERSONNEL INJURIES	
NUMBER	DESCRIPTION
0 0 0	(40) N/A

4 9 11 12		LOSS OF OR DAMAGE TO FACILITY		(43)
		TYPE	DESCRIPTION	
1	9	Z (42)	N/A	

		PUBLICATION			NRC USE ONLY	
ISSUED	DESCRIPTION	(45)				
20	N/A	(44)				

NAME OF PREPARER

PHONE: (303) 785-2224