

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 M D C C N 2 000 - 000000 - 000 411111 _____
7 8 9 14 15 25 26 30 37 CAT 58

CON'T
01 REPORT SOURCE L 050000318 0 0781 020581 _____
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 At 0930, Channel B reactor protective system trip units for Hi Power,
03 Thermal Margin/Low Pressure (TM/LP) and Axial Flux Offset (AFO) were
04 bypassed for troubleshooting the linear power range instrument. The
05 detector output was faulty therefore Channel B Hi Power, TM/LP, and
06 AFO trip units were placed in the tripped condition at 1255 on 1-8-81
07 per T.S. 3.3.1.1. The three redundant channels were operable. LER's
08 79-50 and 80-05 (U-2) report earlier symptoms of the problem.

09 SYSTEM CODE I A 11 CAUSE CODE E 12 CAUSE SUBCODE F 13 COMPONENT CODE I N S T R U 14 COMP. SUBCODE X 15 VALVE SUBCODE Z 16
7 8 9 10 11 12 13 18 19 20

17 LER/RO REPORT NUMBER 81 21 22 23 24 26 27 28 29 30 31 32
EVENT YEAR 81 SEQUENTIAL REPORT NO. 001 OCCURRENCE CODE 03 REPORT TYPE L REVISION NO. 0

ACTION TAKEN X 18 FUTURE ACTION A 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 00000 ATTACHMENT SUBMITTED N 23 NPRD-4 FORM SUB. Y 24 PRIME COMP. SUPPLIER A 25 COMPONENT MANUFACTURER X999 26
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The upper subchannel detector's field cable connector (King Electronics
11 Co., Inc. #KH5905) was found loosened, making intermittent contact. The
12 connector will be replaced during the current refueling outage. This has
13 not been a repetitive failure; it is considered to be due to wear and
14 handling during its service. No preventive action is necessary.

15 FACILITY STATUS E 28 % POWER 055 29 OTHER STATUS NA 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Operator Observation
7 8 9 10 12 13 44 45 46 80

16 ACTIVITY CONTENT Z 33 RELEASED OF RELEASE Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36
7 8 9 10 11 44 45 80

17 PERSONNEL EXPOSURES NUMBER 000 37 TYPE Z 38 DESCRIPTION NA 39
7 8 9 11 12 13 80

18 PERSONNEL INJURIES NUMBER 000 40 DESCRIPTION NA 41
7 8 9 11 12 80

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43
7 8 9 10 80

20 PUBLICITY ISSUED N 44 DESCRIPTION NA 45
7 8 9 10 80

LER NO. 81-01/3L
DOCKET NO. 50-318
LICENSE NO. DPR-69
EVENT DATE 01-07-81
REPORT DATE 02-05-81
ATTACHMENT

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (CONT'D)

Operations personnel reported a high deviation between the Channel "B" Ex-core Nuclear Instrument calculated ASI and the In-core calculated ASI. Subsequent attempts at calibration and troubleshooting revealed a further degeneration of the upper subchannel detector signal previously reported on LER's 05000318/79-50 and 05000318/80-05. Oscilloscope checks revealed regular noise spikes at this time, vice the sinusoidal patterns detected in earlier troubleshooting.

In this and in earlier attempts at troubleshooting, connector cleaning and insulation resistance checks on the cable were included. Results were in expected ranges. After reactor shutdown for the current refueling and during preparations for the detector (2-NE-006) replacement, the faulted connector was noted. During the Unit 2 Refueling Outage, all similar Ex-core Nuclear Instrumentation connectors have been sight verified as part of an engineering review in progress. Routine refueling surveillance tests of detectors and cables have disclosed no additional problems in cables or connectors. The connector will be replaced during the current refueling outage. Therefore, no preventive action is deemed necessary.