/0/1/	CONTROL BLOCK / / / / / (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)  /V/A/N/A/S/1/ (2) /0/0/-/0/0/0/0/-/0/0/ (3) /4/1/1/1/1/ (4) / / (5)  LICENSEE CODE LICENSE NYBER LICENSE TYPE CAT
/0/1/	REPORT /L/ (6) /0/5/0/0/0/3/3/8/ (7) /0/1/2/4/8/1/ (8) /0/2/0/4/8/1/ (9)
	EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
/0/2/	/ During the last refueling outage, the first row of tubes in each steam /
/0/3/	generator was explosively plugged due to observed defects in the tube
10/4/	/ manufacturing. On January 15, 1981, "C" steam generator tube inspections /
/0/5/	revealed the plug missing from the tube at row 1 column 12. The tube was
10/6/	replugged on January 24, 1981. This information is being submitted to satisfy /
/0/7/	the reporting requirements of T.S. 4.4.5.5.a. The health and safety of the
/0/8/	/ general public were not affected by this event.  SYSTEM CAUSE CAUSE COMP. VALVE CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCODE
<u>/0/9/</u> (17	/C/A/ (11) /X/ (12) /Z/ (13) /Z/Z/Z/Z/Z/Z/ (14) /Z/ (15) /Z/ (16)  SEQUENTIAL OCCURRENCE REPORT REVISION LER/RO EVENT 1 REPORT NO. CODE TYPE NO.
	NUMBER /8/1/ /-/ /0/0/7/ /\/ /9/9/ /X/ /-/ /0/
ACT TAK	THE COME OF THE PARTY OF THE COME OF THE PARTY OF THE PAR
/X/	(18) $\frac{Z}{(19)}$ $\frac{Z}{(20)}$ $\frac{Z}{(21)}$ $\frac{(0/0)0/0}{(22)}$ $\frac{Y}{(23)}$ $\frac{N}{(24)}$ $\frac{Z}{(25)}$ $\frac{Z}{9/9/9}$ (26)
	AUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
	그 맛이 되었다. 그 사람이 많아보고 있는 것이 없었다고 있다면 하는데 없는데 그리고 있다면 하는데 없는데 그리고 있다면 그리
/1/0/	/ The tube plug fell out during unit operation because of a bad seal which can /
/1/1/	/ result when plugs are installed by explosive charge. Corrective action was to /
/1/2/	/ replug the tube mechanically/
/1/3;	
/1/4/	
	FACILITY  STATUS %POWER OTHER STATUS (30) DISCOVERY DESCRIPTION (32)  /H/ (28) /0/0/0/ (29) / NA / (30) /B/ (31) / INSERVICE INSPECTION /
/1/6/	ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36) /Z/ (33) /Z/ (34) / NA / NA / NA / PERSONNEL EXPOSURES
/1/7/	NUMBER TYPE DESCRIPTION (39)  /0/0/0/ (37) /Z/ (38) / NA /  PERSONNEL INJURIES
/1/8/	NUMBER DESCRIPTION (41)  /O/O/O/ (40) / NA  LOSS OF OR DAMAGE TO FACILITY  TYPE DESCRIPTION (43)
	TIFE DESCRIPTION
/1/9/	/Z/ (42) / NA PUBLICITY /
/2/0/	ISSUED DESCRIPTION (45)  /N/ (44) / NA  /////////////////////////////////
816	NAME OF PREPARER W. R. CARTWRIGHT PHONE (703) 894-5151

Virginia Electric and Power Company North Anna Power St tion, Unit #1 Docket No. 50-338 Report No. LER 81-007/99X-0

# Attachment: Page 1 of 1

# Description of Event

On January 15, 1981, inservice inspection of "C" steam generator tube bundle revealed that the tube plug at row 1 column 12 had fallen out. This particular tube was explosively plugged during the last refueling outage due to observed manufacturing defects. All other tubes in the first row of each steam generator were also plugged during the outage. On January 24, 1981, the tube at row 1 column 12 was mechanically replugged. This information is being submitted to satisfy the 15 day reporting requirement of T.S. 4.4.5.5.a.

# Probable Consequences of Occurrence

The steam generator tube involved was not defective and therefore with its plug missing a release of radioactive material to the environment due to primary to secondary leakage did not occur. Because the discrepancy was found and corrected prior to return to power, the health and safety of the general public were not affected.

## Cause of Event

It is believed that the tube plug fell out during unit operation due to an improper fit which can occur when plugs are installed by an explosive charge.

### Immediate Corrective Action

The steam generator tube at row 1 column 12 was mechanically replugged on January 24, 1981.

#### Scheduled Corrective Act on

Any other missing plugs identified will be mechanically replaced during the current refueling outage.

#### Actions Taken to Prevent Recurrence

No further actions are required.

#### Generic Implications

The are no generic implications.