



KANSAS GAS AND ELECTRIC COMPANY

GLENN L. KOESTER
VICE PRESIDENT - NUCLEAR

February 18, 1981

Mr. W.C. Seidle, Chief
Reactor Construction and
Engineering Support Branch
U.S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive
Suite 1000
Arlington, Texas 76012

KMLNRC 81-059
Re: Docket No. 50-482
Subj: 50.55(e) Report - General Electric HFA Relays
NRC Information Notice 81-01

Dear Mr. Seidle:

In December, 1980, we received a letter from General Electric Co. (GE) which advised us that failures had been experienced with certain lexan coil spools supplied with their HFA type relays. Mr. ECreel advised Mr. WACrossman of this letter on December 23, 1980.

On January 15, Information Notice 81-01 was issued to advise the industry of this problem.

On February 4, Mr. ECreel advised Mr. Crossman that an investigation had been initiated to determine if any of the potentially defective coils were installed in safety-related relays at Wolf Creek, and that several of the potentially defective coils had been found.

At this time an inspection to determine if the coils are cracked is not planned because we will replace the relays as recommended by GE, regardless of the present condition of the coils. Our schedule for replacing the coils will be dependent upon the availability of replacement relays from GE.

Please advise if you need additional information.

Yours very truly,

GLK:bb
cc: TVandel (NRC Site Inspector)
Director Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555
Attach 15 copies

8102250191