LICENSEE EVENT REPORT
CONTROL BLOCK: 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
0 1 N C B E P 2 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 6 5 EIGENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58
CON'T 0 1 8 1 6 0 5 0 - 0 3 2 4 7 0 1 2 0 8 1 8 0 2 1 3 8 1 9
During the performance of RHR Service Water System Component Tests, PT 8.1.4 and
PT 8.2.4, the "A" RHR Service Water subsystem suction valve from the conventional
Service Water System, 2-SW-V101, would not fully open, making the "A" RHR Service
0 5 Water subsystem inoperable. The "B" RHR Service Water subsystem remained operable
O 6 during this event. This event did not affect the health or safety of the pu'lic.
0 7 1
Technical Specifications 3.7.1.1, 6.9.1.9b
SYSTEM CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCOD
LERIRO EVENT YEAR 8 1
TAKEN ACTION ON PLANT METHOD HOURS (22) SUBMITTED FORM SUB. SUPPLIER MANUFACTURER B 8 Z 19 Z 20 Z 21 0 0 0 0 0 0 0 0 0
1 0 One of the two hex nuts on the input shaft of the valve motor operator, model
No. H3BC-SMB-00, froze to the shaft preventing electrical or manual operation of
1 2 the valve due to mechanical binding. Both hex nuts and the input shaft were re-
worked and checked for proper thread alignment and were lubricated to ensure
proper operation. The valve was then returned to satisfactory operation.
FACILITY STATUS OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 1 5 F 28 0 8 9 29 N/A B 31 Periodic Test
ACTIVITY CONTENT RELEASED OF RELEASE N/A AMOUNT OF ACTIVITY 35 N/A LOCATION OF RELEASE 36 N/A AMOUNT OF ACTIVITY 35 N/A AMOUNT OF ACTIVITY 35 N/A
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 N/A 1 1 12 13
PERSONNEL INJURIES NUMBER DESCRIPTION 41 N/A N/A
LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION N/A N/A
PUBLICITY SSUED DESCRIPTION 45 8102250466 N/A
NAME OF PREPARER M. J. Pastva, Jr. PHONE 919-457-9521