

CONTROL BLOCK: | | | | | | | (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

L	6	0	5	0	-	0	3	4	6	7	0	1	2	2	8	1	8	7	2	2	0	8	1	9	
60	DOCKET NUMBER										68	EVENT DATE						74	REPORT DATE						80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

03 (fuel handling area, elevation 585) was partially open. With this door open, the

04 | spent fuel pool emergency ventilation system would not have been able to maintain the

05 | spent fuel pool area at a negative pressure of $\geq 1/8$ inch water gauge. The action

9 6 | statement of T.S. 3.9.1.2 prohibits fuel handling operations and movements of loads

over the pool without an operable system. These restrictions were not violated.

08 | There was no danger to the health and safety of the public or station personnel.

7 8 9

0	9
7	8

SYSTEM CODE: S (9), H (10), 11

CAUSE CODE: E (11), 12

CAUSE SUBCODE: B (12), 13

COMPONENT CODE: X (13), X (14), X (15), X (16), X (17), X (18), 14

COMP. SUBCODE: Z (19), 15

VALVE SUBCODE: Z (20), 16

(17) LER/RO REPORT NUMBER 81 —

EVENT YEAR —

SERIAL REPORT NO. 007 /

CODE 03

TYPE L —

NO. 0

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NRPD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

[E] (18) [Z] (19) [Z] (20) [Z] (21) [0] [0] [0] [0] [Y] (23) [N] (24) [L] (25) [9] [9] [9]

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The door was immediately closed and latched. The cause of the finding was a door

closure which needed adjustment. It was not closing hard enough to latch the door.

1 2 Maintenance Work Order 81-1187-009 was issued the same day to check and adjust the

$\boxed{1} \boxed{2}$ | closure.

1 4

7 8 9
FACILITY STATUS 1 5 G 28
% POWER 10 11 12 13 29
OTHER STATUS 30
METHOD OF DISCOVERY A 31 noticed while walking through plant
DISCOVERY DESCRIPTION 32
81

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 2 33 34 NA

AMOUNT OF ACTIVITY (35)

LOCATION OF RELEASE (36)

NA

PERSONNEL EXPOSURES										
NUMBER		TYPE		DESCRIPTION (39)						
1	7	0	0	0	(37)	Z	(38)	NA		

PERSONNEL INJURIES NUMBER	DESCRIPTION
41	

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	-----

LOSS OF OR DAMAGE TO FACILITY		(43)
TYPE	DESCRIPTION	
1 9	Z (42)	NA

7	8	9	10	NRC USE ONLY										
PUBLCITY				(45)										
ISSUED DESCRIPTION														

7 8 9 10 68 69 8
2 0 N 44 NA 8102250 474

NRC USE ONLY

8102250 474

(419) 259-5000, Ext. 225

TOLEDO EDISON COMPANY
DAVIS-BESSE NUCLEAR POWER STATION UNIT ONE
SUPPLEMENTAL INFORMATION FOR LER NP-33-81-06

DATE OF EVENT: January 22, 1981

FACILITY: Davis-Besse Unit 1

IDENTIFICATION OF OCCURRENCE: Spent Fuel Pool Emergency Ventilation System inoperable due to unlatched door 306

Conditions Prior to Occurrence: The unit was in Mode 5 with Power (MWT) = 0 and Load (Gross MWE) = 0.

Description of Occurrence: On January 22, 1981 at 0850 hours, an Instrument and Controls mechanic reported that door 306 (fuel handling area, elevation 585') was not latched. The door closing device did not fully close the door. Since the door opens into the area that the spent fuel pool emergency ventilation system draws from, the door would be pulled further open when the system started. With the door open, the system would not be able to maintain the storage pool area at a negative pressure of $\geq 1/8$ inches water gauge relative to the outside atmosphere. Technical Specification 3.9.1.2 requires two independent emergency ventilation systems servicing the storage pool area to be operable whenever irradiated fuel is in the pool. The action statement prohibits the movement of fuel and crane operation with loads over the storage pool until at least one system is restored to operable status. These restrictions were not violated.

Designation of Apparent Cause of Occurrence: The cause of the occurrence was a door closing device which needed adjustment. When the door was pulled shut by the person that found it ajar, it did latch and remain closed. Apparently, the door had been opened and then allowed to close itself but the closing device did not latch the door.

Analysis of Occurrence: There was no danger to the health and safety of the public or to station personnel. There were not any fuel movements or crane operations with loads over the pool during this time. Had the spent fuel pool emergency ventilation system been needed, it could have been started and would have created a negative pressure in the area even though it would not have been able to reach the $\geq 1/8$ water gauge negative pressure.

Corrective Action: The door was immediately closed and latched. Maintenance Work Order 81-1187-009 was issued the same day to adjust the door closing device. The door closures will be included on a preventive maintenance program.

Failure Data: There have been no previous incidents caused by a door closure needing adjustment. Previous reports of doors being blocked open were reported in Licensee Event Reports NP-33-80-56 (80-047) and NP-33-80-79 (80-066).