

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | N | Y | J | A | F | I | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | - | 0 | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | _____ | 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35
LICENSEE CODE LICENSE NUMBER LICENSE TYPE DATE

CON'T
0 1 | R | P | O | S | 0 | 0 | 0 | 0 | 3 | 3 | 3 | 7 | 0 | 2 | 0 | 3 | 8 | 1 | 9 | 0 | 2 | 2 | 3 | 8 | 1 | 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 13

0 2 | During normal operation, Reactor Core Isolation Cooling (RCIC) was intentionally
0 3 | made inoperable when required to be operable by TS 3.5.E in order to repair a
0 4 | thermocouple connection associated with a portion of the RCIC isolation subsystem.
0 5 | High pressure Coolant Injection was verified operable as required by TS 4.5.E.2
0 6 | No significant hazard existed.

0 9 | SYSTEM CODE: C F 11 | CAUSE CODE: F 12 | CAUSE SUBCODE: F 13 | COMPONENT CODE: E L E C T R I C I O N 14 | COMP SUBCODE: 7 15 | VALUE SUBCODE: 7 16
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | 25 | 26 | 27 | 28 | 29 | 30 | 31 | 32 | 33 | 34 | 35 | 36 | 37 | 38 | 39 | 40 | 41 | 42 | 43 | 44 | 45 | 46 | 47 | 48 | 49 | 50
EVENT YEAR: 8 1 | SEQUENTIAL REPORT NO.: 1 | OCCURRENCE CODE: 1 | REPORT TYPE: L | REVISION NO.: 1
ACTION TAKEN: B 16 | FUTURE ACTION: F 17 | EFFECT ON PLANT: Z 18 | SHUTDOWN METHOD: Z 19 | HOURS: 0 0 0 0 | ATTACHMENT SUBMITTED: N 20 | NRC FORM SUB.: Y 21 | PRIME COMP SUPPLIER: N 22 | COMPONENT MANUFACTURER: T 2 8 7 23

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 | Cause of the broken thermocouple wire is attributed to normal wear and tear
1 1 | as a result of routine monthly surveillance. Monthly surveillance requires
1 2 | disconnecting and reconnecting each thermocouple as part of the test. The
1 3 | connection was repaired and RCIC was returned to service approximately five
1 4 | (5) hours later. Future modifications will eliminate the problem.

1 5 | FACILITY STATUS: F 15 | % POWER: 100 | OTHER STATUS: NA | METHOD OF DISCOVERY: B 16 | DISCOVERY DESCRIPTION: Surveillance
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 6 | ACTIVITY CONTENT RELEASED OR RELEASE: Z 16 | AMOUNT OF ACTIVITY: NA | LOCATION OF RELEASE: NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 7 | PERSONNEL EXPOSURES NUMBER: 0 0 0 | TYPE: Z | DESCRIPTION: NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 8 | PERSONNEL INJURIES NUMBER: 0 0 0 | DESCRIPTION: NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 9 | LOSS OF OR DAMAGE TO FACILITY TYPE: Z | DESCRIPTION: NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

2 0 | PUBLICITY ISSUED DESCRIPTION: NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50