



UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D. C. 20555

Lera

Docket No. 50-341

MAR 20 1981

Mr. Harry Tauber
Vice President
Engineering & Construction
Detroit Edison Company
2000 Second Avenue
Detroit, Michigan 48226



Dear Mr. Tauber:

SUBJECT: REQUESTS FOR ADDITIONAL INFORMATION IN FERMI 2 OPERATING LICENSE APPLICATION

As a result of our continuing review of the operating license application for the Enrico Fermi Atomic Power Plant Unit 2, we have developed the enclosed requests for additional information.

Please amend your application to comply with the requirements listed in the enclosure. Our review schedule is based on the assumption that the additional information will be available for our review by May 1, 1981. If you wish clarification of the requests or if you cannot meet these dates, please telephone the Licensing Project Manager, L. Kintner, within 7 days after receipt of this letter.

Sincerely,

Robert L. Tedesco
Assistant Director for Licensing
Division of Licensing

Enclosures:
Requests for Additional
Information

cc w/enclosures:
See next page

A

8104020277

Mr. Harry Tauber
Vice President
Engineering & Construction
Detroit Edison Company
2000 Second Avenue
Detroit, Michigan 48226

cc: Eugene B. Thomas, Jr., Esq.
LeBoeuf, Lamb, Leiby & MacRae
1333 New Hampshire Avenue, N. W.
Washington, D. C. 20036

Peter A. Marquardt, Esq.
Co-Counsel
The Detroit Edison Company
2000 Second Avenue
Detroit, Michigan 48226

Mr. William J. Fahrner
Project Manager - Fermi 2
The Detroit Edison Company
2000 Second Avenue
Detroit, Michigan 48226

Mr. Larry E. Schuerman
Licensing Engineer - Fermi 2
Detroit Edison Company
2000 Second Avenue
Detroit, Michigan 48226

Charles Bechhoefer, Esq., Chairman
Atomic Safety & Licensing Board
Panel
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Dr. David R. Schink
Department of Oceanography
Texas A & M University
College Station, Texas 77840

Mr. Frederick J. Shon
Atomic Safety & Licensing Board
Panel
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

David E. Howell, Esq.
21916 John R
Hazel Park, Michigan 48030

Mr. Bruce Little
U. S. Nuclear Regulatory Commission
Resident Inspector's Office
6450 W. Dixie Highway
Newport, Michigan 48166

ENCLOSURE 1

REQUESTS FOR ADDITIONAL INFORMATION IN THE SAFETY REVIEW

ENRICO TERMI ATOMIC POWER PLANT UNIT 2

DOCKET NO. 50-341

Requests by the following branches in NRC are included in this enclosure. Requests and pages are numbered sequentially with respect to previously transmitted requests.

<u>Branch</u>	<u>Page No.</u>
Mechanical Engineering Branch	110-14
Instrumentation and Control Systems Branch	222-42 through 222-45

110.0 MECHANICAL ENGINEERING BRANCH

110.19

It is the staff's position that all essential safety-related instrumentation lines should be included in the vibration monitoring program during pre-operational or start-up testing. We require that either a visual or instrumented inspection (as appropriate) be conducted to identify any excessive vibration that will result in fatigue failure.

Provide a list of all safety-related small bore piping and instrumentation lines that will be included in the initial test vibration monitoring program.

The essential instrumentation lines to be inspected should include (but are not limited to) the following:

- a) Reactor pressure vessel level indicator instrumentation lines (used for monitoring both steam and water levels).
- b) Main steam instrumentation lines for monitoring main steam flow (used to actuate main steam isolation valves during high steam flow).
- c) Reactor core isolation cooling (RCIC) instrumentation lines on the RCIC steam line outside containment (used to monitor high steam flow and actuate isolation).
- d) Control rod drive lines inside containment (not normally pressurized but required for scram).

222.0 Instrumentation & Control Systems Branch222.51 Loss of Non-Class 1E Instrumentation and Control Power System Bus
During Power Operation (IE Bulletin 79-27)

If reactor controls and vital instruments derive power from common electrical distribution systems, the failure of such electrical distribution systems may result in an event requiring operator action concurrent with failure of important instrumentation upon which these operator actions should be based. This concern was addressed in IE Bulletin 79-27. On November 30, 1979, IE Bulletin 79-27 was sent to operating license (OL) holders, the near term OL applicants (North Anna 2, Diablo Canyon, McGuire, Salem 2, Sequoyah, and Zimmer), and other holders of construction permits (CP), including Detroit Edison Company for the Fermi 2 CP. Of these recipients, the CP holders were not given explicit direction for making a submittal as part of the licensing review. However, they were informed that the issue would be addressed later.

Provide your response to IE Bulletin 79-27 with two exceptions. First, the 90 day limit in Item 4 is not applicable. Second, your response should be in the form of an amendment to the FSAR.

222.52

Engineered Safety Features (ESF) Reset Controls (IE Bulletin 80-06)

If safety equipment does not remain in its emergency mode upon reset of an engineered safeguards actuation signal, system modification, design change or other corrective action should be planned to assure that protective action of the affected equipment is not compromised once the associated actuation signal is reset. This issue was addressed in IE Bulletin 80-06. IE Bulletin 80-06 required that reviews be conducted to determine which, if any, safety functions might be unavailable after reset, and what changes could be implemented to correct the problem. With minor modifications the wording of the original Bulletin 80-06 is an appropriate basis for the current OL applicants to review their systems. A copy of IE Bulletin 80-06 was previously sent to Detroit Edison for the Fermi 2 CP.

Provide your response to IE Bulletin 80-06 with two exceptions. First, the 90-day limit for response in Item 4 is not applicable. Second, your response should be in the form of an amendment to the FSAR.

222.53

Qualification of Control Systems (IE Information Notice 79-22)

If control systems are exposed to the environment resulting from the rupture of reactor coolant lines, steamlines or feedwater lines, the control systems may malfunction in a manner which would cause consequences to be more severe than calculated in safety analyses. This concern was addressed in IE Information Notice 79-22.

Provide the results of an analysis of interactions between non-safety grade or control equipment to demonstrate they will not cause consequences more severe than those found in safety analyses when subjected to the harsh environment of a high energy line break.

222.54

Control System Failures

The analyses reported in Chapter 15 of the FSAR are intended to demonstrate the adequacy of safety systems in mitigating anticipated operational occurrences and accidents.

Based on the conservative assumptions made in defining these design-basis events and the detailed review of the analyses by the staff, it is likely that they adequately bound the consequences of single control system failures.

To provide assurance that the design basis event analyses adequately bound other more fundamental credible failures you are requested to provide the following information:

- (1) Identify those control systems whose failure or malfunction could seriously impact plant safety.
- (2) Indicate which, if any, of the control systems identified in (1) receive power from common power sources. The power sources considered should include all power sources whose failure or malfunction could lead to failure or malfunction of more than one control system and should extend to the effects of cascading power losses due to the failure of higher level distribution panels and load centers.
- (3) Indicate which, if any, of the control systems identified in (1) receive input signals from common sensors. The sensors considered should include, but should not necessarily be limited to, common hydraulic headers or impulse lines feeding pressure, temperature, level or other signals to two or more control systems.
- (4) Provide justification that any simultaneous malfunctions of the control systems identified in (2) and (3) resulting from failures or malfunctions of the applicable common power source or sensor are bounded by the analyses in Chapter 15 and would not require action or response beyond the capability of operators or safety systems.