	CONTROL BLOCK:
0 1	T   N   S   N   P   1   2   0   0   -   0   0   0   0   -   0   0
CONT	SOURCE SO SI DICKET NUMBER (8 69 EVENT DATE 14 75 REPORT DATE 80
0 2	At 1204 CST with unit in mode 3 after a reactor trip, the steam-driven auxiliary feed-
0]3]	water pump IA-S was declared inoperable when the operator experienced problems with the
0 4	steam supply controls. The plant entered action statement "a" of LCO 3:7.1.2. There
0 5	was no effect on public health or safety. There have been no previous occurrences.
0 6	
0 7	
0 8	
7 8	SYSTEM CAUSE CAUSE COMPONENT CODE SUBCODE SUBCODE
7 8	SEQUENTIAL OCCURRENCE REPORT REVISION
	17 REPORT NUMBER 21 22 28 29 30 31 32
	ACTION FUTURE CFFECT SHUTDOWN HOURS 22 ATTACHMENT FORM SUB. SUPPLIER WANUFACTURER LET 18 F 19 C 20 Z 21 C O O O O O O O O O O O O O O O O O O
	CALLES DESCRIPTION AND CORRECTIVE ACTIONS (22)
10	The problems with the steam supply controls developed when the steam supply to the
10	
	The problems with the steam supply controls developed when the steam supply to the
	The problems with the steam supply controls developed when the steam supply to the pump was automatically isolated by PDIS-1-17 and 18. Initial trouble-shooting could not ;
112	The problems with the steam supply controls developed when the steam supply to the pump was automatically isolated by PDIS-1-17 and 18. Initial trouble-shooting could not industrial the problem. After three successful tests, the pump was declared operable at 2300 CST. Subsequent investigations resulted in modifying the setpoints for PDIS-1-17 and 18.
112	The problems with the steam supply controls developed when the steam supply to the pump was automatically isolated by PDIS-1-17 and 18. Initial trouble-shooting could not industrate the problem. After three successful tests, the pump was declared operable at 2300 CST. Subsequent investigations resulted in modifying the setpoints for PDIS-1-17 and 18.  PDIS-1-17 and 18.  OTHER STATUS (30) METHOD OF DISCOVERY DESCRIPTION (32)
112	The problems with the steam supply controls developed when the steam supply to the pump was automatically isolated by PDIS-1-17 and 18. Initial trouble-shooting could not industrate the problem. After three successful tests, the pump was declared operable at 2300 CST. Subsequent investigations resulted in modifying the setpoints for pDIS-1-17 and 18.  [A 30 Operator observation 32 Operator observation 33 Operator observation 34 Operator observation 35 Operator observation 36 Operator observation 37 Operator observation 37 Operator observation 37 Operator observation 38 Operator observation 39 Operator observation 39 Operator observation 30 Operat
112	The problems with the steam supply controls developed when the steam supply to the pump was automatically isolated by PDIS-1-17 and 18. Initial trouble-shooting could not duplicate the problem. After three successful tests, the pump was declared operable at 2300 CST. Subsequent investigations resulted in modifying the setpoints for PDIS-1-17 and 18.  PDIS-1-17 and 18.  OTHER STATUS (30) DISCOVERY DISCOVERY DESCRIPTION (32) DISCOVERY DESCRIPTION (32) DISCOVERY DISCOVERY DESCRIPTION (32) DISCOVERY DESCRIPTION (33) Operator observation
	The problems with the steam supply controls developed when the steam supply to the pump was automatically isolated by PDIS-1-17 and 18. Initial trouble-shooting could not industry the problem. After three successful tests, the pump was declared operable at 2300 CST. Subsequent investigations resulted in modifying the setpoints for poiscovery obscription of piscovery obscription obscription of piscovery obscription obscription of piscovery obscription obs
112	The problems with the steam supply controls developed when the steam supply to the pump was automatically isolated by PDIS-1-17 and 18. Initial trouble-shooting could not industry the problem. After three successful tests, the pump was declared operable at 2300 CST. Subsequent investigations resulted in modifying the setpoints for poiscovery obscription of piscovery obscription obscription of piscovery obscription obscription of piscovery obscription obs
112	The problems with the steam supply controls developed when the steam supply to the pump was automatically isolated by PDIS-1-17 and 18. Initial trouble-shooting could not identificate the problem. After three successful tests, the pump was declared operable at 2300 CST. Subsequent investigations resulted in modifying the setpoints for problem at 2300 CST. Subsequent investigations resulted in modifying the setpoints for problem in the status of problems of p
112	The problems with the steam supply controls developed when the steam supply to the pump was automatically isolated by PDIS-1-17 and 18. Initial trouble-shooting could not industry the pump was declared operable at 2300 CST. Subsequent investigations resulted in modifying the setpoints for pDIS-1-17 and 18.  POWER OTHER STATUS (3) NA DISCOVERY DESCRIPTION (32) DISCOVERY DESCRIPTION (32) DISCOVERY DESCRIPTION (32) DISCOVERY DESCRIPTION (33) DESCRIPTION (34) DISCOVERY DESCRIPTION (35) DISCOVERY DESCRIPTION (36) DISCOVERY DESCRIPTION (37) DISCOVERY DISCOVERY DESCRIPTION (37) DISCOVERY DISCOVERY DESCRIPTION (37) DISCOVERY DISCOVERY DISCOVERY DISCOVERY DISCOVERY DISCOVERY DIS

Tennessee Valley Authority Sequoyah Nuclear Plant

## LER SUPPLEMENTAL INFORMATION

SQRO-50-327/81024 Technical Specification Involved: 3.7.1.2.b

Reported Under Technical Specification: 6.9.1.13.b

Date of Occurrence: 3/14/81 Time of Occurrence: 1204 CST

# Identification and Description of Occurrence:

Operator experienced difficulty with steam supply controls to steam-driven auxiliary feedwater pump IA-S. Pump was declared inoperable.

## Conditions Prior to Occurrence:

Unit in mode 3 following reactor trip

## Apparent Cause of Occurrence:

An initial pressure spike (over 50-feet WC) in addition to a bias error caused by a clog in the sense lines to PDIS-1-17 and 18 (approximately 5-feet WC) caused PDIS-1-17 and 18 to isolate the steam supply to the AFW pump turbine.

#### Corrective Action:

The setpoints for PDIS-1-17 and 18 were temporarily modified with engineering design's concurrence from 55.68 ft. WC to 95 ft. WC to prevent recurrence of this event in the future. A permanent setpoint change will be implemented by a design change request now being prepared and expected to be submitted by May 1, 1981.