. . LICENSEE EVENT REPORT

the 1 0h	LICENSEE EVENT REPORT
	CONTROL BLOCK: []]] [] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	C T M N S 2 2 0 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 5 LICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58
CON'T	REPORT LIGIO 5 0 0 0 3 3 6 7 0 3 11 2 8 1 6 0 4 0 2 8 1 9 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80
0 2	EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) During normal operation, routine surveillance found both chlorine detectors with
0 3	detector solution drin rates less than that allowable. The control room ventilation
0 4	the recirculation mode in accordance with Technical Specifi-
0 5	antions Action Statement 3 3 3 6b for 40 minutes. LER 79-13/3L-0 involved a similar
06	
0 7	
0 8	9 SYSTEM CAUSE CAUSE COMPONENT CODE SUBCODE SUBCODE
0 9	S G 11 X 12 Z 13 I N S T R U 14 E 15 Z 16 SEQUENTIAL OCCURRENCE REPORT REVISION
	17 REPORT 8 1
	ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT SUBMITTED FORM SUB. PRIME COMP. COMPONENT MANUFACTURER W 0 2 5 6 7 6 7 6 7 6 7 6 7 6 7 6 7 6 7 6 7 6
10	Clogged detector solution filters were found in both chlorine detectors. These
1 2	clean, fresh detector solution has been emphasized to those personnel performing
13	maintenance.
1 4 7 8	9 FACILITY SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32
1 5	E 28 1 0 0 29 NA B 31 Operator Survet Hance
16	ACTIVITY CONTENT LOCATION OF RELEASE 36 NA N
1.13	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)
7 8	9 11 12 13 PERSONNEL INJURIES
1 8	0 0 0 0 0 NA 80
1 9	LOSS OF OH DAMAGE TO FACILITY 43 TYPE DESCRIPTION Z (42) NA
7 8	PUBLICITY ISSUED DESCRIPTION 45 8104170493