

UNITED STATES NUCLEAR REGULATORY COMMISSION WASHINGTON, D. C. 20555

April 23, 1981

Docket No. 50-289

Mr. Henry D. Hukill, Vice President and Director - TMI-1 Metropolitan Edison Company P. O. Box 480 Middletown, Pennsylvania 17057

Dear Mr. Hukill:

SUBJECT: REVISION TO APPENDICES B AND C OF THE THREE MILE ISLAND UNIT 1 EQUIPMENT QUALIFICATION SAFETY EVALUATION

Enclosed are revised pages to the TMI-1 equipment qualification Safety Evaluation Report (SER) forwarded to you March 24, 1981. The revised Appendices reflect changes in the deficiencies for Foxboro transmitters and include a manufacturers recommended corrective action. The potential deficiencies affecting the transmitters were identified during recent testing by a utility owners group. The revised pages should be substituted for the corresponding original pages in the SER. Your response to our request for additional information identified in Sections 3 and 4 of the SER should also address these deficiencies.

Sincerely,

John F. Stolz, Chief Operating Reactors Branch #4 Division of Licensing

Enclosure: Revised pages to Safety Evaluation Report

cc w/enclosure: See next three pages

Metropolitan Edison Company

cc w/enclosure(s):

Mr. Marvin I. Lewis 6504 Bradford Terrace Philadelphia, Pennsylvania 19149

Walter W. Cohen, Consumer Advocate Department of Justice Strawberry Square, 14th Flocr Harrisburg, Pennsylvania 17127

Robert L. Knupp, Esq. Assistant Solicitor Knupp and Andrews P. O. Box P 407 N. Front Street Harrisburg, Pennsylvania 17108

John E. Minnich, Chairman Dauphin Co. Board of Commissioners Dauphin County Courthouse Front and Market Streets Harrisburg, Pennsylvania 17101

 * Atomic Safety and Licensing Appeal Board U.S. Nuclear Regulatory Commission Washington, D. C. 20555

* Atomic Safety and Licensing Board Panel U.S. Nuclear Regulatory Commission Washington, D. C. 20555

Docketing and Service Section
U.S. Nuclear Regulatory Commission
Washington, D. C. 20555

Robert Q. Pollard 609 Montpelier Street Baltimore, Maryland 21218

Chauncey Kepford Judith H. Johnsrud Environmental Coalition on Nuclear Power 433 Orlando Avenue State College, Pennsylvania 16801

Ms. Frieda Berryhill, Chairman Coalition for Nuclear Power Plant Postponement 2610 Grendon Drive Wilmington, Delaware 19808

Mrs. Rhod. D. Carr 1402 Marene Drive Harrisburg, Pennsylvania 17109 Dr. Walter H. Jordan 881 W. Outer Drive Oak Ridge, Tennessee 37830

Dr. Linda W. Little 5000 Hermitage Drive Raleigh, North Carolina 27612

Ms. Gail P. Bradford Anti-Nuclear Group Representing York 245 W. Philadelphia Street York, Pennsylvania 17404

John Levin, Esq. Pennsylvania Public Utilities Comm. Box 3265 Harrisburg, Pennsylvania 17120

Jordan D. Cunningham, Esq. Fox, Farr and Cunningham 2320 North 2nd Street Harrisburg, Pennsylvania 17110

Ms. Louise Bradford TMIA 1011 Green Street Harrisburg, Pennsylvania 17102

Ms. Marjorie M. Aamodt R.D. #5 Coatesville, Pennsylvania 19320

Ms. Karen Sheldon Sheldon, Harmon & Weiss 1725 I Street, N.W. - Suite 506 Washington, D. C. 20006

Earl B. Hoffman Dauphin County Commissioner Dauphin County Courthouse Front and Market Streets Harrisburg, Pennsylvania 17101

Ms. Ellen R. Weiss, Esq. Sheldon, Harmon & Weiss 1725 I Street, N.W. Suite 506 Washington, D. C. 20006

Mr. Steven C. Sholly Union of Concerned Scientists 1725 I Street, N. W., Suite 601 Washington, DC 20006

- 1 -

Metropolitan Edison Company

Mr. Thomas Gerusky Bureau of Radiation Protection Department of Environmental Resources P. O. Box 2063 Harrisburg, Pennsylvania 17120

Mr. G. P. Miller Mr. R. R. Wilson Metropolitan Edison Company P. O. Box 480 Middletown, Pennsylvania 17057

G. F. Trowbridge, Esq. Shaw, Pittman, Potts & Trowbridge 1800 M Street, N.W. Washington, D. C. 20036

Mr. E. G. Wallace Licensing Manager GPU Service Corporation 100 Interpace Parkway Parsippany, New Jersey 07054

Mr. R. W. Conrad Vice President, Generation Pennsylvania Electric Company 1007 Broad Street Johnstown, Pennsylvania 15907

Ms. Virginia Southard, Chairman Citizens for a Safe Environment 264 Walton Street Lemoyne, Pennsylvania 17043

Government Publications Section State Library of Pennsylvania Box 1601 (Education Building) Harrisburg, Pennsylvania 17126

Mr. David D. Maxwell, Chairman Board of Supervisors Londonderry Township RFD#1 - Geyers Church Raod Middletown, Pennsylvania 17057

U. S. Environmental Protection Agency Region III Office ATTN: EIS COORDINATOR Curtis Building (Sixth Floor) 6th and Walnut Streets Philadelphia, Pennsylvania 19106

Mr. J. G. Herbein Director, Nuclear Assurance Metropolitan Edison Company P. O. Box 480 Middletown, PA 17057 Ms. Jane Lee R.D. 3, Box 3521 Etters, Peonsylvania 17319

Karin W. Carter, Esq. 505 Executive House P. O. Box 2357 Harrisburg, Pennsylvania 17120

Honorable Mark Cohen 512 D-3 Main Capital Building Harrisburg, Pennsylvania 17120

Dauphin County Office Emergency Preparedness Court House, Room 7 Front & Market Streets Harrisburg, Pennsylvania 17101

Department of Environmental Resources ATTN: Director, Office of Radiological Health P. O. Box 2063 Harrisburg, Pennsylvania 17105

Director, Criteria and Standards Division Office of Radiation Programs (ANR-460) U. S. Environmental Protection Agency Washington, D. C. 20460

Mr. Robert B. Borsum Babcock & Wilcox Nuclear Power Generation Division Suite 420, 7735 Old Georgetown Road Bethesda, Maryland 20014

* Ivan W. Smith, Esq.
Atomic Safety & Licensing Board Panel
U.S. Nuclear Regulatory Commission
Washington, D. C. 20555

Ms. Kathy McCaughin Three Mile Island Alert, Inc. 23 South 21st street Harrisburg, Pennsylvania 17104

Mr. L. W. Harding Supervisor of Licensing Metropolitan Edison Company P. O. Box 480 Middletown, Pennsylvania 17057

- 2 -

Metropolitan Edison Company

Mr. R. J. Toole Manager, TMI-1 Metropolitan Edison Company P. O. Box 430 Middletown, Pennsylvania 17057

Mr. W. E. Potts Radiological Controls Manager, TMI-1 Metropolitan Edison Company P. O. Box 480 Middletown, Pennsylvania 17057

Mr. I. R. Finfrock, Jr. Jersey Central Power & Light Company Madison Avenue at Punch Bowl Raod Morristown, New Jersey 07950

J. B. Lieberman, Esq. Berlock, Israel & Liberman 26 Broadway New York, NY 10004

Mr. J. J. Colitz Plant Engineering Manager, TMI-1 Metropolitan Edison Company P. O. Box 480 Middletown, Pennsylvania 17057

York College of Pennsylvania Country Club Road York, Pennsylvania 17405

Mr. G. K. Hovey Director, TMI-2 Metropolitan Edison Company P. O. Box 480 Middletown, Pennsylvania 17057

Mr. B. Elam Manager, Plant Engineering, Unit 2 Metropolitan Edison Company P. O. Box 480 Middletown, Pennsylvania 17057

Mr. Richard Roberts The Patriot 812 Market Street Harrisburg, Pennsylvania 17105

Mr. R. W. Heward Manager, Radiological Control, Unit 2 Metropolitan Edison Company P. O. Box 480 Middletown, Pennsylvania 17057 Allen R. Carter, Chairman Joint Legislative Committee on Energy P. O. Box 142 Suite 513 Senate Gressette Building Columbia, South Carolina 29202

Daniel M. Pell, Esq. ANGRY 32 South Beaver Street York, Pennsylvania 17401

William S. Jordan, III, Esq. Harmon & Weiss 1725 I Street, NW, Suice 305 Washington, DC 20006

General Counsel Federal Emergency Management Agency ATTN: Docket Clerk 1725 I Street, NW Washington, DC 20472

Mr. J. J. Barton Manager, Site Operations TMI-2 Netropolitan Edison Company P. O. Box 480 Middletown, Pennsylvania 17057

Mr. E. D. Fuller TMI-2 Licensing Supervisor Metropolitan Edison Company P. O. Box 480 Middletown, Pennsylvania 17057

Mr. Donald R. Haverkamp Senior Resident Inspector (TMI-1) U. S. N. R. C. P. O. Box 311 Middletown, Pennsylvania 17057

Governor's Office of State Planning and Development ATTN: Coordinator, Pennsylvania State Clearinghouse P. O. Box 1323 Harrisburg, Pennsylvania 17120

- 3 -

APPENDIX B

Equipment Requiring Additional Information and/or Corrective Action (Category 4.2)

LEGEND:

Designation for Deficiency

- R Radiation
- T Temperature
- QT Qualification time
- RT Required time
- P Pressure
- H Humidity
- CS Chemical spray
- A Material aging evaluation, replacement schedule, ongoing equipment surveillance
- S Submergence
- M Margin
- I HELB evaluation outside containment not completed
- QM Qualification method
- RPN Equipment relocation or replacement, adequate schedule not provided
- EXN Exempted equipment justification inadequate

SEN - Separate effects qualification justification inadequate

- QI Qualification information being developed
- RPS Equipment relocation or replacement schedule provided

Equipment Description	Manufacturer	Plant ID No.	Deficiency
Pressure Switch	Static-O-Ring	PS-600	QT,CS,R,A,EXN,QM
Pressure Switch	Static-O-Ring	PS-601	QT,CS,R,A,EXN,QM
Pressure Switch	Static-O-Ring	PS-602	QT,CS,R,A,EXN,QM
Pressure Switch	Static-O-Ring	PS-603	QT,CS,R,A,EXN,QM
Pressure Switch	Static-O-Ring	PS-604	QT,CS,R,A,EXN,QM
Pressure Switch	Static-O-Ring	PS-605	QT,CS,R,A,EXN,QM
Pressure Switch	Static-O-Ring	PS-606	QT,CS,R,A,EXN,QM
Pressure Switch	Static-O-Ring	PS-607	QT,CS,R,A,EXN,QM
Pressure Transmitt	er Foxboro	SP6A-PT1	CS,A,R

*See Attachment 1: Foxboro Letter (3/12/81), "Potential Deficiency Affecting Foxboro Transmitters," for corrective action. Rev.

Rev.

81 05060017

Equipment Description	Manufacturer	Plant ID No.	Deficiency
Pressure Transmitter	Foxbero	SP6A-PT2	CS,A,R
Pressure Transmitter	Foxboro .	SP6B-PT1	CS,A,R
Pressure Transmitter	Foxboro	SP6B-PT2	CS,A,R
Limit Switch	NAMCO	LSA/MSV-6	T,P,H,A,EXN
Limit Switch	NAMCO	LSB/MSV-6	T,P,H,A,EXN
Limit Switch	NAMCO	LSB/MSV-13A	T,P,H,A,EXN
Limit Switch	NAMCO	33/MSV-13A	T,P,H,A,EXN
Solenoid Valve	ASCO	SV/MSV-13A	T,P,H,A,EXN
Solenoid Valve	ASCO	SV/MSV-13B	T,P,H,A,EXN
Limit Switch	NAMCO	LSA/MSV-13B	T,P,H,A,EXN
Limit Switch	NAMCO	LSB/MSV-13B	T,P,H,A,EXN
Motor	Westinghouse	EF-P2A	QT,T,P,H,A
Motor	Westinghouse	EF-P2B	QT,T,P,H,A
Motor Operator	Limitorque	EF-V-1A	T,A
Motor Operator	Limitorque	EF-V-1B	T,A
Motor Operator	Limitorque	EF-V-2A	T,A
Motor Operator	Limitorque	EF-V-2B	T,A
Pneumatic Converter	Bailey	EF-V-30A/Cont.	QT,T,P,H,R,A,RPN
Pneumatic Converter	Bailey	EFV-30B/Cont.	QT,T,P,H,R,A,RPN
Motor Operator	Limitorque	FW-V-5A	T,A
Motor Operator	Limitorque	FW-V-5B	T,A
Motor Operator	Limitorque	FW-V-92A	T,A
Motor Operator	Limitorque	FW-V-928	TA

APPENDIX B (continued)

*See Attachment 1: Foxboro Letter (3/12/81), "Potential Deficiency Affecting Foxboro Transmitters," for corrective action.

Rev.

R.

Equipment Description	Manufacturer	Plant ID No.	Deficiency
Pressure Switch	Square D	PS-289	R,A
Pressure Switch	Square D •	PS-290	R,A
Pressure Transmitter	Foxboro	RC3A-PT3	CS,A,R
*Pressure Transmitter	Foxboro	RC3A-PT4	CS,A,R
Pressure Transmitter	Foxboro	RC3B-PT3	CS,A,R
Fan Motor	GE	AH-E-1A	CS,A
Fan Motor	GE	AH-E-1B	CS,A
Fan Motor	GE	AH-E-1C	CS,A
Motor Operator	Limitorque	CF-V-1A	CS,R,A,EXN
Motor Operator	Limitorque	CF-V-1B	CS,R,A,EXN
Motor Operator	Limitorque	CF-V-2A	CS,M,A
Motor Operator	Limitorque	CF-V-2B	CS,M,A
Motor Operator	Limitorque	CF-V-3A	CS,A
Motor Operator	Limitorque	CF-V-3B	CS,A
Limit Switch	Micro Swtich	LSA/CFV-19A	R,A
Limit Switch	Micro Swtich	LSB/CFV-19A	R,A
Limit Switch	Micro Swtich	LSA/CFV-19B	R,A
Limit Switch	Micro Swtich	LSA/CFV-19B	R,A
Solenoid Valve	ASCO	20/CF-V19A	R,A
Solenoid Valve	ASCO	20/CF-V19B	R,A
Limit Switch	Micro Switch	LSA/CFV-20A	R,A
Limit Switch	Micro Switch	LSB/CFV-20A	R,A
Limit Switch	Micro Switch	LSA/CFV-20B	R,A
Limit Swtich	Micro Switch	LSB/CFV-20B	R,A
Solenoid Valve	ASCO	SV/CF-V20A	R.A

APPENDIX B (continued)

*Sae Attachment 1: Foxboro Letter (3/12/81), Potential Deficiency Affecting Foxboro Transmitters," for corrective action. B-6 Rev.

Rev.

Description	Manufacturer	Plant ID No.	Deficiency
Conax Connectors	Conax .	Rosemount Connectors PL-14-B2	QT,T,P,H,CS,R,A
Conax Connectors	Conax	Bailey Connectors TG-14-2	CS,R,A
Conax Connectors	Conax	Bailey Connectors PL-16-B4	CS,R,A
Solenoid	ASCO	SV/EF-V-8A	T,P,H,A,EXN
Solenoid	ASCO	SV/EF-V-8B	T,P,H,A,EXN
Solenoid	ASCO	SV/EF-V-8C	T,P,H,A,EXN
Diff. Press. Transmitter	Barton	FI-S-77	QT,T,P,H,R,A
Diff. Press Transmitter	Barton	FI-S-78	QT,T,P,H,R,A
Diff. Press Transmitter	Barton	FI-79	QT,T,P,H,R,A
Solenoid Valve	ASCO	SV3 & SV4 FW-V-16A	T,P,H,A,EXN
Solenoid Valve	ASCO	SV3 & SV4 FW-V-16B	T,P,H,A,EXN
Solenoid Valve	ASCO	SV3 & SV4 FW-V-17A	T,P,H,A,EXN
Solenoid Valve	ASCO	SV1 & SV2 FW-V-17B	T,P,H,A
Solenoid Valve	ASCO	SV3 & SV4 FW-V-17B	T,P,H,A,EXN
Pressure Transmitter	Foxboro	PT-282	A,R
Pressure Transmitter	Foxboro	PT-285	A,R
Pressure Transmitter	Foxboro	PT-288	A,R

APPENDIX B (continued)

*See Attachment 1: Foxboro Letter (3/12/81), "Potential Deficiency Affecting Foxboro Transmitters," for corrective action.

Rev.

Rev.

Equipment Description	Manufacturer	Plant ID No.	Deficiency		
Limit Switch	NAMCO	33/ICV-4	A		
Limit Switch	NAMCO	LSB/ICV-4	A		
Limit Switch	NAMCO	33/ICV-6	A		
Limit Switch	NAMCO	LSB/ICV-6	A		A
Solenoid Valve	ASCO	SV/ICV-6	Α		
Motor Operator	Limitorque	RB-V-2	Α		
Pump Motor	Westinghouse	BS-P1A	A		
Pump Motor	Westinghouse	BS-P1B	Α		
Motor Operator	Limitorque	BS-V-1A	A		
Motor Operator	Limitorque	BS-V-1B	A		
Motor Operator	Limitorque	BS-V-2A	A		
Motor Operator	Limitorque	BS-V-2B	Α		
Motor Operator	Limitorque	BS-V-3A	A		
Motor Operator	Limitorque	BS-V-3B	A		
Neutron Detector	Westinghouse	NI-5	Exempt		
Neutron Detector	Westinghouse	NI-6	Exempt		
Neutron Detector	Westinghouse	NI-7	Fxempt		
Neutron De' tor	Westinghouse	NI-8	Exempt		

APPENDIX C (continued)

Motor	Operator	Limitorque	RR-V-3A	A
Motor	Operator	Limitorque	RR-V-3B	A
Motor	Operator	Limitorque	RR-V-3C	A
Motor	Operator	Limitorque	RR-V-4A	A
Motor	Operator	Limitorque	RR-V-4B	A

Rev.

ATTACHMENT 1

The Foxboro Company

12 March 1981

Subject: Potential Deficiency Affecting Foxboro Transmitters, Model Numbers N-Ell, N-El3 or Ell, El3 with suffix Codes /MCA, /MCA/RRW, or /MCA/RR

Gentlemen:

Our records indicate that you have received one or more of the Foxboro model numbered transmitters listed above. This letter is to notify you that two deficiencies have been discovered in some of these transmitters which may exist in the units shipped to you. The transmitters in question operate at a signal level of 10-50mA. Similar model numbered units operating at 4-20mA are not affected.

The first issue involves the possible use of incorrect insulating sleeving on transistor and zener diode lead wires in the amplifier. The second issue involves the use of a specific vendor's capacitor which is not hermetically sealed (although claimed to be so). As a result, the capacitor electrolyte can leak under adverse service conditions, specifically heat and time. The failure mode is a decrease in resistance across the capacitor resulting in electrical leakage. The transmitter operation can be affected by limiting the output to something less than full value which, in time, can degrade to no output at all.

<u>Insulating Sleeving</u> - Radiation resistant sleeving consisting of a silicone coated glass fiber braid has been substituted by a teflon sleeving in some transmitters. Tests have shown that teflon will become brittle and deteriorate with a substantial integrated radiation dose. Foxboro testing has demonstrated that the teflon sleeving used in these devices will withstand an integrated dose of 10 megarads with no noticeable deterioration. Tests to 200 megarads produce the brittle conditions which can result in the teflon flaking from the wires. Based on these tests, operating plants not expected to exceed an integrated dose of 10 megarads have no potential problem and no action is required.

Where the integrated dose rate could exceed 10 megarads, then units in service should be inspected to determine if the proper insulating material has been used. This can be accomplished by opening the transmitter in accordance with Foxboro Master Instruction MI 20-145. The amplifier cover must be removed exposing the amplifier assembly. At one end of the assembly, a transistor and a zener diode are mounted in the base casting which serves as a heat sink. The insulating material in question is a sleeving slipped over the lead wires from these two components. The proper material is white and heavy looking. Positive



Foxboro, MA 02035 U.S.A. (617) 543-8750 Page 2 12 March 1981

Subject:

identification can be made by inspecting one end of the material to establish that the outer material covers an inner braid. Teflon, if used, will be a single layer material and could be either clear or white.

If improper insulation is present, then the corrective action is to replace theamplifier (Foxboro P/N NO148PW). Replacement amplifiers can be purchased from your local Foxboro Sales or Service Representatives. If you prefer to have Foxboro Service Personnel inspect the equipment and, if necessary, replace the amplifier, this can be arranged at standard service rates.

<u>Capacitor</u> - The capacitor degradation problem was discovered over time through tracking failure situations. Internal corrective action has been taken to remove the vendor involved from the qualified vendor list and to purge all stock of capacitors from this vendor. Degradation of this capacitor is a function of time and service conditions with heat being a primary contributor. This phenomenon was observed in recent tests of transmitters using these capacitors. The capacitor in question is manufactured by Cornell-Duebilier and can be specifically identified by a type number in the form TX-65-XXXX as well as a monogram in a box followed by a date code, e.g. <u>CDE</u> 0874. It is assigned Foxboro part number NO141MF.

To determine if this capacitor is present requires a visual inspection of the amplifier which can be accomplished as described above for the insulating sleeving inspection. The recommended corrective action should the above described capacitor be present is to replace the amplifier (Foxboro P/N NO148PW) although is is possible to replace the capacitor with a Foxboro provided substitute. Use of Foxboro Service personnel to perform the inspection and replacement, if necessary, can be arranged at standard service rates as described above.

Due to lack of knowledge of specific application, redundancy, and the like, Foxboro cannot determine if the NRC reporting requirements of 10CFR Part 21 are applicable. This determination is the responsibility of the user and any such reporting would be made by them after completing their evaluation of the situation.

If you have any questions regarding the above, please contact the undersigned directly.

Very truly yours,

THE FOXBORO COMPANY

William Calder, Mänager Corporate Quality Assurance

joy 120381

Enclosure MI 20-145

