

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	A	L	J	M	F	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4	5																							
LICENSEE CODE							LICENSE NUMBER														LICENSE TYPE					CAT 58																							
REPORT SOURCE		L		0		5		0		0		0		3		6		4		7		0		4		2		1		8		1		3		0		5		2		0		8		1		9	
60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80									

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | At 0112 on 4/21/81, the containment atmosphere particulate and gaseous radioactivity

0 3 | monitoring systems (R11 and R12 respectively) were declared inoperable when the inboard

0 4 | pump tripped. Tech. Spec. 3.4.7.1 requires R11 and R12 to be operable. Tech. Spec.

0 5 | 3.4.7.1 action statement requirements were met. The health and safety of the general

0 6 | public were not affected by this occurrence.

0 7 | _____

0 8 | _____

0 9 | _____

SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE		COMP. SUBCODE		VALVE SUBCODE	
B B		D		Z		Z Z Z Z Z		Z		Z	
9 10		11 12		13 14		15 16		17 18		19 20	
EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.			
8 1		0 0 7		0 3		L		0			
21 22		23 24		25 26		27 28		29 30		31 32	
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED	
E		Z		Z		Z		0 0 0 0		Y	
33 34		35 36		37 38		39 40		41 42		43 44	
NPRD FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER							
N		Z		Z 9 9 9							
45 46		47 48		49 50		51 52		53 54		55 56	

CAUSE DESCRIPTION AND CORRECTIVE ACTION (27)

1 0 | This incident is attributable to a procedural deficiency. The inboard pump tripped due

1 1 | to a flow control valve not being lock-wired in the correct position. Upon discovery of

1 2 | the condition, the parallel pump was started and R11 and R12 were returned to service

1 3 | at 0145 on 4/21/81. Subsequently the flow control valve was lock-wired in the correct

1 4 | flow control position, inboard pump repaired and the surveillance test procedure

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
G		0 0 0		NA		A		Operator observation	
7 8		9 10		11 12		13 14		15 16	
ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE			
Z		Z		NA		NA			
33 34		35 36		37 38		39 40		41 42	
PERSONNEL EXPOSURES NUMBER		TYPE		DESCRIPTION					
0 0 0		Z		NA					
7 8		9 10		11 12		13 14		15 16	
PERSONNEL INJURIES NUMBER		TYPE		DESCRIPTION					
0 0 0		Z		NA					
7 8		9 10		11 12		13 14		15 16	
LOSS OF OR DAMAGE TO FACILITY TYPE		DESCRIPTION							
Z		NA							
33 34		35 36		37 38		39 40		41 42	
PUBLICITY ISSUED		DESCRIPTION							
N		NA							
7 8		9 10		11 12		13 14		15 16	

NAME OF PREPARER: W. G. Hairston, III

PHONE: (205) 899-5156

8105270 386

LER 81-007/03L-0 . . . continued

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

modified to require lock-wiring the flow control valve in the correct position.