LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK.
1 0 R T N P 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 0 57 CAT 58 5
ON'T SOURCE L 6 0 5 0 - 0 3 4 4 7 0 4 1 9 8 1 3 0 5 1 8 8 1 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES TO
10 12 AFTER OPENING VALVE MO-4005 TO ALLOW WATER TO BE PUMPED FROM THE REACTOR
COOLANT DRAIN TANK TO THE CLEAN RADIOACTIVE WASTE SYSTEM, IT WAS NOTED
THAT THE VALVE HAD FAILED IN ITS OPEN POSITION. THIS VALVE SERVES AS
[0] PART OF THE CONTAINMENT BOUNDARY. TECHNICAL SPECIFICATIONS REQUIRE THAT
THIS VALVE BE OPERABLE AND CAPABLE OF BEING AUTOMATICALLY SHUT IF A
O[7] CONTAINMENT ISOLATION IS REQUIRED. IN ITS FAILED CONDITION, THE VALVE
COULD NOT MEET THE REQUIREMENTS OF THIS SPECIFICATION.
SYSTEM CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCOD
LEA/RO EVENT YEAR REPORT NO. 17) REPORT VEAR REPORT NO. 17) REPORT VEAR REPORT NO. 18 1
TIO L THE CAUSE IS ATTRIBUTED TO COMPONENT FAILURE. THE VA. OPERATOR WAS
INADVERTENTLY SUBMERGED IN WATER CAUSING DAMAGE TO THE VALVE OPERATOR.
1 8 9 90
FACILITY STATUS SPOWER OTHER STATUS OTHER
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) NA NA NA NA NA NA NA NA NA N
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 NA NA 11 12 13
PERSONNEL INJURIES NUMBER DESCRIPTION 41 NA 1 8 9 11 12 NA 30
LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION NA NA
PUBLICITY ISSUED DESCRIPTION 45 NA N
NAME OF PREPARER R. P. Schmitt PHONE 503/556-3713, ext. 235