

LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[illegible]

LER SUPPLEMENTAL INFORMATION

BFRO-50- 260 / 81020 Technical Specification Involved Table 4.2.B

Reported Under Technical Specification 6.7.2.b (2)

Date of Occurrence 5/5/81 Time of Occurrence 0800 Unit 2

Identification and Description of Occurrence:

Suppression chamber level switches LS 73-57A and LS 73-57B operated at correct setpoint, but annunciator and relays failed to operate.

Conditions Prior to Occurrence:

Unit 1 refueling outage.

Unit 2 at 100%

Unit 3 at 100%

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

Notified maintenance personnel and the relay was replaced.

Apparent Cause of Occurrence:

Relay 23AK51 failed.

Analysis of Occurrence:

There was no danger to the health or safety of the public, no release of activity, no damage to the plant or equipment, and no resulting significant chain of events.

Corrective Action:

Replaced component and tested successfully.

Failure Data:

None

\*Retention: Period - Lifetime; Responsibility - Document Control Supervisor

\*Revision: SA