



June 2, 1981

L81-444

FILE: RR 2 (NP-33-81-30)

Docket No. 50-346
License No. NPF-3

Mr. James G. Keppler
Regional Director, Region III
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137



Dear Mr. Keppler:

Reportable Occurrence 81-027
Davis-Besse Nuclear Power Station Unit 1
Date of Occurrence: May 5, 1981

Enclosed are three copies of Licensee Event Report 81-027 with a supplemental information sheet which is being submitted in accordance with Technical Specification 6.9 to provide 30 day written notification of the subject occurrence.

Yours truly,

Terry D. Murray
Station Superintendent
Davis-Besse Nuclear Power Station

TDM/ljk

Enclosure

cc: Mr. Victor Stello, Jr., Director
Office of Inspection and Enforcement
Encl: 30 copies

Mr. Norman Haller, Director
Office of Management Program Analysis
Encl: 3 copies

Mr. Luis Reyes
NRC Resident Inspector
Encl: 1 copy

TOLEDO EDISON COMPANY
DAVIS-BESSE NUCLEAR POWER STATION UNIT ONE
SUPPLEMENTAL INFORMATION FOR LER NP-33-81-30

DATE OF EVENT: May 5, 1981

FACILITY: Davis-Besse Unit 1

IDENTIFICATION OF OCCURRENCE: High pressure injection flow indication failure

Conditions Prior to Occurrence: The unit was in Mode 1 with Power (MWT) = 2770 and Load (Gross MWE) = 916

Description of Occurrence: At 1315 hours on May 5, 1981, flow indicator FYI HP3A was found to be indicating about 380 gpm with the pump off and the valves closed. High Pressure Injection (HPI) Train 2 was declared inoperable, and the unit entered the action statement of Technical Specification 3.5.2.

Designation of Apparent Cause of Occurrence: The cause of this occurrence is a component failure. The buffer amplifier for FYI HP3A failed causing the bad indication.

Analysis of Occurrence: There was no danger to the health and safety of the public or to station personnel. HPI Train 1 was operable during the time that HPI Train 2 was inoperable.

Corrective Action: The buffer amplifier was repaired under Maintenance Work Order IC-410-81, and the unit was removed from the action statement of Technical Specification 3.5.2 at 1730 hours on May 6, 1981.

Failure Data: A previous failure of a buffer amplifier was reported in Licensee Event Report NP-33-81-10 (LER 81-011).

LER #81-027