

UPDATE REPORT--PREVIOUS REPORT DATE 5/15/81
LICENSEE EVENT REPORT

U.S. NUCLEAR REGULATORY COMMISSION

[illegible]

LER SUPPLEMENTAL INFORMATION

BFRO-50- 296 / 81019 R1 Technical Specification Involved 3.5.E.1(2)

Reported Under Technical Specification 6.7.2.b.2

Date of Occurrence 4/23/81 Time of Occurrence 0830 Unit 3

Identification and Description of Occurrence:

Unit 3 HPCI inoperable to replace gland seal condenser gaskets.

Conditions Prior to Occurrence:

Unit 1 refueling outage

Unit 2 at 99%

Unit 3 scram due to low reactor water level.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

Requirements of T.S. 3.5.E.1(2) were met.

Apparent Cause of Occurrence:

Overpressurizing gland seal condenser (tube side).

Analysis of Occurrence:

There was no danger to the health or safety of the public, no release of activity, no damage to the plant or equipment, and no resulting significant chain of events.

Corrective Action:

Replaced head gaskets. Instrumentation will be installed to monitor piping pressures to determine cause of overpressurization.

Failure Data:

BFRO-50-260/74016W, 74017W, 74024W, and 74028W.

*Retention: Period - Lifetime; Responsibility - Document Control Supervisor

*Revision: SA