




# Public Service Company of Colorado

16805 ROAD 19½  
PLATTEVILLE, COLORADO 80651

May 22, 1981  
Fort St. Vrain  
Unit No. 1  
P-81150



Mr. Karl V. Seyfrit, Director  
Nuclear Regulatory Commission  
Region IV  
Office of Inspection and Enforcement  
611 Ryan Plaza Drive  
Suite 1000  
Arlington, Texas 76012

Reference: Facility Operating License  
No. DPR-34

Docket No. 50-267

Dear Mr. Seyfrit:

Enclosed please find a copy of Reportable Occurrence Report No. 50-267/81-030, Preliminary, submitted per the requirements of Technical Specification AC 7.5.2(b)1 and AC 7.5.2(b)2.

Also, please find enclosed one copy of the Licensee Event Report for Reportable Occurrence Report No. 50-267/81-030.

Very truly yours,

*Don Warembourg*  
Don Warembourg  
Manager, Nuclear Production

DW/clb

Enclosure

cc: Director, MIPC

A002  
S  
1/1

5 8106090 657

OCCURRENCE REPORT DISTRIBUTION

Number of Copies

Department of Energy - - - - - San Francisco Operations Office Attn: California Patent Group 1333 Broadway Oakland, California 94612	1 (P Letter)
Department of Energy - - - - - Mr. Glen A. Newby, Chief HTR Branch Division of Nuclear Power Development Mail Station B-107 Washington, D.C. 20545	1 (P Letter)
Department of Energy - - - - - Attn: Project Manager 110 West A Street, Suite 460 San Diego, California 92101	1 (P Letter)
Mr. Karl V. Seyfrit, Director - - - - - Region IV Office of Inspection and Enforcement Nuclear Regulatory Commission 611 Ryan Plaza Drive Suite 1000 Arlington, Texas 76012	① (Original of P Letter and Copy of LER)
Director - - - - - Office of Management Information and Program Control U. S. Nuclear Regulatory Commission Washington, D.C. 20555	1 (P Letter, LER)
Mr. Richard Phelps - - - - - FSV, CA, Site Representative General Atomic Company P. O. Box 426 Platteville, Colorado 80651	10 (Original of FPLG Letter plus Two Copies, One Copy of P Letter, One Copy of LER)
Mr. Bill Lavalee - - - - - Nuclear Safety Analysis Center 3412 Hillview Avenue P. O. Box 10414 Palo Alto, California 94303	1 (P Letter, LER)
NRC Resident Site Inspector - - - - -	1 (P Letter, LER)

REPORT DATE: May 22, 1981

REPORTABLE OCCURRENCE 81-030

OCCURRENCE DATE: April 22, 1981

ISSUE 0

Page 1 of 5

FORT ST. VRAIN NUCLEAR GENERATING STATION  
PUBLIC SERVICE COMPANY OF COLORADO  
16805 WELD COUNTY ROAD 19 1/2  
PLATTEVILLE, COLORADO 80651

REPORT NO. 50-267/81-030/03-L-0

Preliminary

IDENTIFICATION OF  
OCCURRENCE:

Testing of the primary coolant programmed pressure scram revealed that two of the pressure transmitters were out of calibration and could have allowed operation with trip setpoints less conservative than required by LCO 4.4.1, Table 4.4-1.

This is reportable per Fort St. Vrain Technical Specification AC 7.5.2(b)1 and AC 7.5.2(b)2.

EVENT  
DESCRIPTION:

See Figure 1. While performing the monthly calibration check of the primary coolant pressure scram channels, plant instrument personnel observed that two of the pressure transmitters (1) were out of calibration in the nonconservative direction and would have resulted in the pressure switch highs (2) tripping at a higher pressure than allowed by LCO requirements. The low readings of the pressure transmitters (1) would have caused the pressure switch lows (3) to trip sooner at a higher, more conservative pressure than required.

The high and low pressure trips (2) and (3) are programmed by circulator inlet temperature through an auctioneer circuit (4) and a bistable setpoint programmer (5) or (6). The programmed pressure temperature curve is shown in Figure 2. The low output signal from the pressure transmitter could have resulted in the high pressure trips occurring above the allowable high pressure curve (line (A) (A)). The low pressure trips would have occurred above low pressure trip curve (line (B) (B)) in a conservative direction.

Although the high pressure trips could have occurred at a value less conservative than that established in the Technical Specifications, they would not prevent the fulfillment of the functional requirements of the systems.

|mtext

CAUSE

DESCRIPTION:

The low pressure signals were due to instrument drift of the pressure transmitter.


CORRECTIVE

ACTION

The pressure transmitters were calibrated during the procedure and returned to service.

Once a month, on a temporary basis, the pressure transmitter voltage outputs will be checked against reactor pressure to determine if further instrument drift is occurring. The monthly test will be conducted until the next regularly scheduled surveillance calibration is required or until it is determined that instrument drift is not occurring.

The results will be included in a future supplement report.



Reactor pressure instrument channel (typ. for channels B&C)

FIGURE 1



FIGURE 2




Fig. 1-14--Programmed reactor pressure high-low trip points

Prepared By: Asa B. Reed  
Asa B. Reed  
Technical Services Technician

Reviewed By: J. W. Gahn  
J. W. Gahn  
Technical Services Supervisor

Reviewed By: Frank M. Machie  
Frank M. Machie  
Operations Manager

Approved By: Don Warembourg  
Don Warembourg  
Manager, Nuclear Production