## LICENSEE EVENT REPORT

	CONTROL BLOCK: [ ] [ ] [PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION]
0 1	COFS V 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 2 0 4 57 CAT 58
CON'T	REPORT L 6 0 5 0 0 0 2 6 7 7 0 4 2 7 8 1 3 0 5 2 7 8 1 9  EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
0 2	On April 27, 1981, with the plant operating at 30% power and 70 MWe, "B" diesel engine
03	tripped and declutched on low exhaust temperature during surveillance testing on "A"
0 4	diesel generator set. Degraded mode of LCO 4.6.1(d). Reportable per Fort St. Vrain
0 5	Technical Specification AC 7.5.2(b)2. No accompanying occurrence. No effect on pub-
0 6	lic health or safety. Redundant equipment available and operable. Similar occurrence
0 7	RO 79-20.
08	9 SYSTEM CAUSE CAUSE COMP. VALVE
0 9	CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCO
	TO REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 32
	ACTION FUTURE EFFECT SHUTDOWN METHOD HOURS 22 ATTACHMENT FORM SUB. PRIME GOMP. SUPPLIER MANUFACTURER  [E 18 Z 19   Z 20   Z 21   0 0 0 0   Y 23   N 24   N 25   W 2 9 0 26    13 36 37 40 41 41 42
110	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)   Load imbalance between "A" and "B" diesel engines due to normal wear of linkage be-
	tween governor terminal shaft and fuel rack of "B" diesel engine caused "B" engine to
	trip and declutch. Linkage was adjusted to balance load between "A" and "B" engine
113	and "A" diesel generator was returned to service, and the Surveillance Test was com-
114	pleted successfully.
7 8	FACILITY SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32    E   28   0   3   0   29   N/A   B   31   Operator Observation
7 8	ACTIVITY CONTENT  ACTIVITY CONTENT  AMOUNT OF ACTIVITY 35  AMOUNT OF ACTIVITY 35  N/A  N/A  N/A
7 8	9 10 11 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39  0 0 0 37 Z 38 N/A
7 8	PERSONNEL INJURIES NUMBER DESCRIPTION 41
7 3	9 11 12 LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION 43
7 3	PUBLICITY DESCRIPTION 45 8106090680 NRC USE ONLY
2 0	N 44 N/A
	NAME OF PREPARER 16/1/2/24 PHONE: (303) 785-2224