

LER SUPPLEMENTAL INFORMATION

BFRO-50- 296 / 81021 Technical Specification Involved 3.6.F.1

Reported Under Technical Specification 6.7.2.b(2)

Date of Occurrence 5/7/81 Time of Occurrence 1535 Unit 3

Identification and Description of Occurrence:

Removed 3B reactor recirculation pump from service to repair motor generator field breaker trip circuit.

Conditions Prior to Occurrence:

Unit 1 refueling outage.

Unit 2 at 37%

Unit 3 at 61%

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

None required

Apparent Cause of Occurrence:

Motor generator set field trip coil was open.

Analysis of Occurrence:

There was no danger to the health or safety of the public, no release of activity, no damage to the plant or equipment, and no resulting significant chain of events.

Corrective Action:

Replaced Breaker, tested and returned pump to service.

Failure Data:

None

*Retention: Period - Lifetime; Responsibility - Document Control Supervisor

*Revision: