

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 M A P P S 1 000-0000000-000 3 41111 4 5

01 REPORT SOURCE L 6 050-0293 7 082180 8 051881 9

02 On August 21, 1980 at approximately 1450 hours while conducting HPCI system per-
03 formance test 3.5.4.1, the HPCI system was declared inoperable. The HPCI system
04 steam throttle valve was oscillating. The HPCI control system was recalibrated.
05 the system satisfactorily tested and returned to service at approximately 1700
06 hours the same day.

09 SYSTEM CODE S F 11 CAUSE CODE X 12 CAUSE SUBCODE Z 13 COMPONENT CODE Z Z Z Z Z Z 14 COMP SUBCODE Z 15 VALVE SUBCODE Z 16
17 LER/RO REPORT NUMBER 80 EVENT YEAR 80 SEQUENTIAL REPORT NO. 058 OCCURRENCE CODE 03 REPORT TYPE L REVISION NO. 1
ACTION TAKEN Z 18 FUTURE ACTION Z 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0000 ATTACHMENT SUBMITTED N 23 NPRO-4 FORM SUB. N 24 PRIME COMP SUPPLIER N 25 COMPONENT MANUFACTURER T 1 4 7 26

10 Subsequent calibration of the control instrumentation indicated no anomaly. Tests
11 conducted with the assistance of a factory representative were satisfactory. It
12 is believed that dirt which eventually filtered through the system caused a
13 temporary malfunction of the turbine throttle valve.

15 FACILITY STATUS E 28 % POWER 100 29 OTHER STATUS N.A. 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Operational Event 32

16 ACTIVITY CONTENT Z 33 RELEASED OF RELEASE Z 34 AMOUNT OF ACTIVITY N.A. 35 LOCATION OF RELEASE N.A. 36

17 PERSONNEL EXPOSURES NUMBER 000 37 TYPE Z 38 DESCRIPTION N.A. 39

18 PERSONNEL INJURIES NUMBER 000 40 DESCRIPTION N.A. 41

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION N.A. 43

20 PUBLICITY ISSUED N 44 DESCRIPTION N.A. 45 NRC USE ONLY