LICENSEE EVENT REPORT

CONTROL BLOCK []]]] [PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION]
[] [] [A L B R F 1] [0 0 - 0 0 0 - 0 0 25 4 1 1 1 1 1 1 1 1 1
CON'S STREET LG 0 5 0 0 0 2 5 9 7 0 5 0 7 8 1 8 0 6 0 3 8 1 9
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
relay 14A-K19B was found to operate in 8.04 seconds, exceeding T.S. table 3.2.B
requirement of 6 to 8 seconds. There was no danger to the health or safety of the
Podundant systems were available and operable. There were no previous
oimilar events.
SYSTEM CAUSE CAUSE COMPONENT CODE SUBCODE SUBCODE
C B T E D A Y X T T T T T T T T T T T T T T T T T T
SEQUENTIAL OCCURRENCE REPORT NO.
1) REPORT 8 1
ACTION PITCHE SHOTLOWN METHOD HOURS (72) SUBMITTED FORM SUB SUPPLIER MANUFACTURER (72) SUBMITTED FORM SUB SUPPLIER (73) [G 0 8 0]
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (2) Time delay relay was out of calibration. General Electric time delay relay, model
[1] [414A42, type CR2820B, series A, 230/250 vdc, was adjusted and successfully tested.
Recurrence control: relays are scheduled to be replaced by Agastat timers on ECN
P0109. Units 2 and 3 have had relays replaced.
(30) METHOD OF DISCOVERY DESCRIPTION (32)
TACHTY STATUS OTHER STATUS ON BEGOVERY DISCOVERY BESCH TO BE BOUTINE TEST
ACTIVITY CONTENT 12 13 44 45 46 ACTIVITY CONTENT AMOUNT OF ACTIVITY 35 NA
1 6 Z 3 Z 3 NA 44 45
PERSONNEL EXPENDENCES NUMBER 10 10 10 10 10 10 10 10 10 10 10 10 10
1 9 arestones 11 12 14
NA DOOD ODICINAL SE
LOSS OF THE DAMAGE TO FACILITY (43) NA NA
NRC USE ONLY
NAME OF PREPARER PHONE:
106090919

LER SUPPLEMENTAL INFORMATION

BFRO-50- 259 / 81022 Technical Specification Involved Table 3.2.B
Reported Under Technical Specification 6.7.2.b(2)
Date of Occurrence 5/7/81 Time of Occurrence 000 Unit 1
Identification and Description of Occurrence: Core spray auto-sequencing timer 14A-K19B was found to operate in 8.04 seconds during SI 4.2.B-39D. T.S. Table 3.2.B requires between 6 and 8 seconds.
Conditions Prior to Occurrence:
Unit 1 refueling outage
Unit 2 at 40%
Unit 3 at 60%
Action specified in the Tachnical Specification Supplies Devices
Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.
Apparent Cause of Occurrence:
Time delay relay out of calibration.
Analysis of Occurrence: There was no danger to the health or safety of the public, no release of activity, no damage to the plant or equipment, and no resulting significant chain of events.
Corrective Action:
Relay was adjusted, tested, and returned to service. Relays are scheduled to be replaced by Agastat timers on PO109. Units 2 and 3 have had relays replaced.
Failure Data: None
*Retention: Period - Lifetime; Responsibility - Document Control Supervisor
Pavision: MA