LICENSEE EVENT REPORT

EIGENSEE EVENT HEIGHT
CONTROL BLOCK: [] [] [] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 1 L Q A D 1 2 0 0 0 - 0 0 0 - 0 0 0 3 4 1 1 1 1 1 0 57 CAT 58 6
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 The 1/2-A Diesel Fire Pump was taken out of service on October 28, 1980, because the
suction bay in the cribhouse was dewatered for necessary maintenance to the
old circulating water pumps during the Unit I outage. The probable consequences are
minimal because the 1/2-B Diesel Fire Pump is operable, the Service Water System is
old available for a backup supply and two portable diesel pumps are installed for
operation if needed.
7 8 9 SYSTEM CAUSE CAUSE COMP. VALVE
CODE SUBCODE COMPONENT CODE SUBCODE SU
17 REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 32
ACTION FUTURE TAKEN ACTION ON PLANT METHOD HOURS 22 ATTACHMENT SUBMITTED FORM SUB. PRIME COMP. MANUFACTURER X 18 Z 19 Z 20 Z 21 0 0 0 0 N 23 N 24 Z 25 Z Z Z Z 26 X 18 X 19 X 24 X 25 X 26 X 27 27 26 X 18 X 18 X 24 X 27 X 27 27 26 X 18 X 24 X 24 X 27 27 27 26 X 18 X 24 X 27 27 27 27 27 27 X 20 X 21 22 27 27 27 27 X 21 22 23 24 27 27 27 27 X 21 22 23 24 27 27 27 X 21 22 23 24 X 22 X 23 24 X 23 X 24 X 24 X 24 X 25 X 27 X 27 27 X 27 27 X 28 X 28 X 28 X X 28 X 28
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) TIO The cause for the 1/2-A Diesel Fire Pump being out of service is to prevent damage
to it while the suction bay is dewatered for circulating water pump repair. Two
portable diesel pumps are installed to take a suction from the discharge flume to
supply the main fire loop if needed. Temporary Procedure 1409 is written for the
1 4 operation of the portable pumps.
PACILITY STATUS OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)
1 6 Z 33 Z 34 NA
17 NUMBER 0 37 Z 38 DESCRIPTION 39 NA NA 80
PERSONNEL INJURIES NUMBER DESCRIPTION 41 NA NA 80
LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION NA NA
PUBLICITY AS DESCRIPTION 45
2 0 N (44) NA 68 69 80.
8106090733