

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

May 26, 1981

81-435-000

SQRD-50-328/81-34

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

SEQUOYAH NUCLEAR PLANT UNIT 2 - STEAM GENERATOR BLOWDOWN LINE - LOOP
NO. 2 PIPING ANALYSIS ERROR - SQRD-50-328/81-34 - FINAL REPORT

The subject deficiency was initially reported to NRC-OIE Inspector
R. V. Crlenjak on May 6, 1981 in accordance with 10 CFR 50.55(e) as
NCR SQN CEB 8112. Enclosed is our final report. We consider 10 CFR 21
applicable to this deficiency.

If you have any questions, please get in touch with D. L. Lambert at
FTS 857-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager
Nuclear Regulation and Safety

Enclosure

cc: Mr. Victor Stello, Director (Enclosure) ✓
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

S 8106110461

ENCLOSURE

SEQUOYAH NUCLEAR PLANT UNIT 2
STEAM GENERATOR BLOWDOWN LINE - LOOP NO. 2
PIPING ANALYSIS ERROR
SQRD-50-328/81-34
10 CFR 50.55(e)
FINAL REPORT

Description of Deficiency

Piping movements of the steam generator blowdown line, loop No. 2, were greater during hot functional testing than anticipated in the design; consequently, certain snubbers would have bottomed out. TVA discovered that a lateral support that had been installed before hot functional testing had been inadvertently omitted from the thermal load case analysis. Omitting the lateral support from the analysis resulted in smaller movements of the piping in the analysis than actually occurred.

Safety Implications

Snubbers bottoming out due to pipe movements greater than anticipated in the design would greatly increase the stresses in the pipe. Inordinate increases in these stresses could cause the pipe to break, resulting in a LOCA.

Corrective Action

TVA performed a reanalysis of the steam generator blowdown line and found that by omitting the support the analysis would result in acceptable design stress levels for all postulated load cases. Therefore, the lateral support will be removed before fuel loading.

TVA has instructed the contractor to ensure that existing check procedures, which are presently designed to catch deficiencies of this nature, are more closely adhered to. In addition, TVA has developed an independent checklist to be completed by TVA which reviews the contractor's analyses. This checklist will be attached to the analysis reports, documenting TVA's review.

PART 21 IDENTIFICATION NO. 81-435-000 COMPANY NAME TVA

DATE OF LETTER 5/26/81 DOCKET NO. 50-328

DATE DISTRIBUTED _____ ORIGINAL REPORT ☒ SUPPLEMENTARY ☐

DISTRIBUTION:

REACTOR (R) ☒

IE FILES

EES - *Mills*

REGIONS I,II,III,IV,V

VENDOR BR. R-IV

LOEB / MPA MNB 5715

AEOD MNB 7602
C&ED DMU MNB 7217
NRR/DOE

NRR/DSI

NRR/DST

NRR/DOL

ASLBP E/W 450

CENTRAL FILES 016

CENTRAL FILES (CHRON)

PDR

LPDR

TERA

ACTION:

PRELIMINARY EVALUATION OF THE ATTACHED REPORT INDICATES LEAD RESPONSIBILITY FOR FOLLOWUP AS SHOWN BELOW:

IE ☐

NRR ☐

NWSS ☐

OTHER ☐

EES

FUEL CYCLE & ☐
MATERIALS (M)

IE FILES

AD/FR/ST

REGIONS I,II,III,IV,V

VENDOR BR. R-IV

NWSS / FCMS SS-396

LOEB / MPA MNB 5715
AEOD MNB 7602
C&ED DMU MNB 7217
ASLBP E/W 450

SAP/SP MNB-7210A

CENTRAL FILES 016

CENTRAL FILES (CHRON)

PDR

LPDR

TERA



SAFEGUARDS (S) ☐

IE FILES

AD/SG

AD/ROI

REGIONS I,II,III,IV,V

VENDOR BR. R-IV

NRR/DOL

NWSS / SG SS-881

LOEB / MPA MNB 5715

AEOD MNB 7602
C&ED DMU MNB 7217
ASLBP E/W 450

CENTRAL FILES 016

CENTRAL FILES (CHRON)

CENTRAL FILES SS-396

PDR

LPDR

TERA