UPDATED	REPORT	-	PREVIOUS	REPORT	DATE	JUNE	3,	1981
OF DELEDE	LINE OFFE		* 100 4 7000	THUE WALF	DUTT	OOTAT	21	TOOT

.

U.S. NUCLEAR REGULATORY COMMISSION LICENSEE EVENT REPORT

$ \begin{array}{c} \text{CONTROL BLOCK } / / / / / (1) (\text{PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION}) \\ / 0/1/ / V/A/N/A/S/2/ (2) / 0/0/-/0/0/0/0/-/0/0/ (3) / 4/1/1/1/1/ (4) / / / (5) \\ \hline \text{LICENSEE CODE} & \text{LICENSE NUMBER} & \text{LICENSE TYPE} & \text{CAT} \end{array} $
$\frac{/0/1/}{\text{SCURCE}} \xrightarrow{/L/} (6) \frac{/0/5/0/0/3/3/9}{\text{DOCKET NUMBER}} (7) \frac{/0/5/1/0/8/1}{\text{EVENT DATE}} (8) \frac{/0/6/1/0/8/1}{\text{REPORT DATE}} (9)$
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
/0/2/ / On May 10, 1981 during Mode 5 operation, a blank flange was found to be in- /
<pre>/0/3/ / stalled on the redundant hydrogen recombiner (1-HC-HC-1) return piping to Unit /</pre>
/0/4/ / 2 containment. The hydrogen recombiner remained operable as required by T.S. /
/0/5/ / 3.6.4.2 through a discharge path to the process ventilation system and to Unit /
<pre>/0/6/ / No. 1 containment; therefore, the health and safety of the public were not _/</pre>
<pre>/0/7/ / affected. This item constitutes a loss of administrative control of an ESF /</pre>
/0/8/ / system and is therefore reportable pursuant to T.S. 6.9.1.9.c. / SYSTEM CAUSE CAUSE COMP. VALVE CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCODE
(0/9) (S/E) (11) (A) (12) (B) (13) $(X/X/X/X/X)$ (14) (Z) (15) (Z) (16)
SEQUENTIAL OCCURRENCE REPORT REVISION LER/RO EVENT YEAR REPORT NO. CODE TYPE NO.
(17) PEPORT
NUMBER $\frac{8/1}{1-1}$ $\frac{1}{0/3/9}$ $\frac{1}{1-1}$ $\frac{1}{1-1}$ $\frac{1}{1-1}$
ACTIONFUTUREEFFECTSHUTDOWNATTACHMENTNPRD-4PRIMECOMPONENTTAKENACTIONON PLANTMETHODHOURSSUBMITTEDFORMSUBSUPPLIERMANUFACTURER
$\underline{/X}$ (18) $\underline{/Z}$ (19) $\underline{/Z}$ (20) $\underline{/Z}$ (21) $\underline{/0/0/0/}$ (22) $\underline{/Y}$ (23) $\underline{/N}$ (24) $\underline{/A}$ (25) $\underline{/Z/9/9/9}$ (26)
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
/1/0/ / The black flange was installed during construction for the initial leak rate /
/1/1/ / testing of Unit 2 containment penetration No. 31. When testing was completed, /
/1/2/ / this blank flange was not removed. The blank flange was subsequently removed /
/1/3/ / and the 1-HC-HC-1 return flow path to Unit 2 containment established. /
/1/4/ //
FACILITY METHOD OF STATUS %POWER OTHER STATUS (30) DISCOVERY DESCRIPTION (32)
/1/5/ /D/ (28) /0/0/0/ (29) / NA / (30) /A/ (31) / OPERATOR OBSERVATION /
Land the lan
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)
ACTIVITY CONTENT
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36) /1/6/ /Z/ (33) /Z/ (34) / NA / / NA // NA // PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36) /1/6/ /Z/ (33) /Z/ (34) / NA / / NA // NA // NA // / NA // / NA // / / /
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36) /1/6/ /Z/ (33) /Z/ (34) / NA / / NA // NA // NA // NA // / NA // / NA // / / NA // / / /
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36) /1/6/ /Z/ (33) /Z/ (34) / NA // NA // NA // PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) /1/7/ /U/0/0/ (37) /Z/ (38) / NA // PERSONNEL INJURIES NUMBER DESCRIPTION (41) /1/8/ /0/0/0/ (40) / NA // LOSS OF OR DAMAGE TO FACILITY (43)
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36) /1/6/ /Z/ (33) /Z/ (34) / NA / / NA // NA // NA // NA // / NA // / NA // / / NA // / / /
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36) /1/6/ /2/ (33) /2/ (34) / NA / NA PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) /1/7/ /0/0/0/ (37) /2/ (38) / NA / PERSONNEL INJURIES NUMBER DESCRIPTION (41) / /1/8/ /0/0/0/ (40) NA / /1/8/ /0/0/0/ (40) NA / /1/8/ /0/0/0/ (40) / NA / /1/9/ /2/ (42) / NA / /1/9/ /2/ (42) / NA /
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36) /1/6/ /2/ (33) /2/ (34) / NA // NA // NA // PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) /1/7/ /0/0/0/ (37) /2/ (38) / NA // PERSONNEL INJURIES NUMBER DESCRIPTION (41) /1/8/ /0/0/0/ (40) / NA // LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION (43) /1/9/ /2/ (42) / NA
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36) /1/6/ /2/ (33) /2/ (34) / NA / NA / NA PERSONNEL EXPOSURES / NA NUMBER TYPE DESCRIPTION (39) // /1/7/ /0/0/0/ (37) /2/ (38) / NA / / PERSONNEL INJURIES // / NUMBER DESCRIPTION (41) // // /1/8/ /0/0/0/ (40) / NA / / LOSS OF OR DAMAGE TO FACILITY (43) // / TYPE DESCRIPTION (43) /1/9/ /2/ (42) / NA / PUBLICITY ISSUED DESCRIPTION (45)

Virginia Electric and Power Company North Anna Power Station, Unit #2 Docket No. 50-339 Report No. LER 81-039/03L-1

Attachment: Page 1 of 1

Description of Event

On May 10, 1)81 during Mode 5 operation, the Unit 2 Shift Supervisor noticed that a blank flange was installed on the discharge piping to Unit 2 containment from the Unit 1 Hydrogen Recombiner (1-HC-HC-1). This blank flange was originally installed during pre-operational leakage testing of Unit 2 containment penetration. Since both hydrogen recombiners remained operable at all times as per T.S. 3.6.4.2, there was no effect on the health and safety of the general public.

Probable Consequences of Occurrence

The hydrogen recombiner is required for the removal of hydrogen released into the containment within 24 hours following a postulated Loss of Coolant Accident. Installed redundant piping systems provide suction and discharge piping to two skid-mounted hydrogen recombiners which are completely interchangeable. In addition, an alternate discharge path is provided for each recombiner to the gaseous waste system via the containment vacuum pump discharge line and another path to the alternate containment.

Cause of Event

This event was caused by inadequate administrative control of the pre-operational leakage testing of containment penetration No. 31.

Immediate Corrective Action

The blank flange was removed.

Scheduled Corrective Action

No further corrective action required.

Actions Taken to Prevent Recurrence

No further action required.

Generic Implications

There are no generic implications of this event.