

CONTROL BLOCK:

						(1)
--	--	--	--	--	--	-----

0	1	A	L	J	M	F	2	2	0	0	-	0	0	0	0	0	-	C	0	3	4	1	1	1	1	4			5
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57 CAT 58	

REPORT SOURCE	60	61	DOCKET NUMBER							68	69	EVENT DATE					74	75	REPORT DATE					80	
	L	6	0	5	0	0	0	3	6	4	7	0	5	0	5	8	1	3	0	6	1	2	8	1	9

012 At 1026 on 5/5/81 and 0915 on 5/6/81, Diesel Generator 2B was declared inoperable due to

013 a lube oil leak and fuel oil leak respectively. Tech. Spec. 3.8.1.1, in part, requires

014 DC 2B to be operable. Tech. Spec. 3.8.1.1 action requirements were met. Health/safety

015 of the public was not affected. The occurrence on 5-5-81 was the sixth failure in the

016 last 100 valid tests.

07 _____

03 _____

7 3 9 80

SYSTEM CODE E E 11		CAUSE CODE E 12		CAUSE SUBCODE B 13		COMP. CODE ENGINE 14				COMP. SUBCODE Z 15		VALVE SUBCODE Z 16					
EVENT YEAR 8 1		SEQUENTIAL REPORT NO. 0 1 3		OCCURRENCE CODE 0 3		REPORT TYPE L		REVISION NO. 0									
ACTION TAKEN A 18		FUTURE ACTION Z 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 0 22		ATTACHMENT SUBMITTED Y 23		NPRO-4 FORM SUB. N 24		PRIME COMP. SUPPLIER A 25		COMPONENT MANUFACTURER F 0 1 0	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10	The cause for the first event was a leaking "O" ring on the lube oil strainer and the "O"
11	ring was replaced. The cause for the second event was a fatigue failure, due to vibra-
12	tion, of the compression fitting on a copper line. The line was replaced with stainless
13	steel and rerouted to reduce vibration. Following a successful timed start DG 2B was
14	returned to service at 1312 on 5/5/81 and 1425 on 5/6/81. This event occurred during

FACILITY STATUS			% POWER			OTHER STATUS			METHOD OF DISCOVERY			DISCOVERY DESCRIPTION		
1	5	G	29	0	0	0	29	NA	B	31	Surveillance Test	32		
ACTIVITY CONTENT			RELEASED OF RELEASE			AMOUNT OF ACTIVITY			LOCATION OF RELEASE					
1	6	Z	33	Z	34		35	NA		NA		36		
PERSONNEL EXPOSURES			NUMBER			TYPE			DESCRIPTION					
1	7	0	0	0	0	37	Z	38		NA				
PERSONNEL INJURIES			NUMBER			DESCRIPTION								
1	8	0	0	0	0	40		41		NA				
LOSS OF OR DAMAGE TO FACILITY			TYPE			DESCRIPTION								
1	9	Z	42				43	NA						
PUBLICITY			ISSUED			DESCRIPTION								
1	0	N	44				45	NA						

8106190326

NRC USE ONLY

LER NO. 81-013/03L-0

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (Continued)

Unit 2 startup testing, and falls within the scope of a special corrective action task force. Preliminary results of the task force evaluation have been submitted to NRC by separate correspondence.