

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | N | C | M | G | S | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34

01 | REPORT SOURCE | 1 | 8 | 0 | 5 | 0 | 0 | 0 | 3 | 6 | 9 | 7 | 0 | 3 | 3 | 0 | 8 | 1 | 8 | 0 | 4 | 2 | 9 | 8 | 1 | 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | While in Mode 5, initial fuel loading, during maintenance work on the Solid
03 | State Protection System cabinets, an inadvertent safety injection was initiated,
04 | The safety injection pump and the centrifugal charging pump breakers had been
05 | disconnected and the RHR system was aligned in the normal shutdown cooling mode,
06 | No significant volume of water was added to the RCS. The health and safety of
07 | the public were not affected. This is reportable per Technical Specification
08 | 6.9.1.13.c.

09 | SYSTEM CODE | S | F | 11 | CAUSE CODE | A | 12 | CAUSE SUBCODE | C | 13 | COMPONENT CODE | Z | Z | Z | Z | Z | Z | 14 | COMP. SUBCODE | Z | 15 | VALVE SUBCODE | Z | 16
17 | LER/NO REPORT NUMBER | 8 | 1 | 18 | SEQUENTIAL REPORT NO. | 0 | 3 | 7 | 19 | OCCURRENCE CODE | 0 | 3 | 20 | REPORT TYPE | L | 21 | REVISION NO. | 0 | 22
23 | ACTION TAKEN | H | 24 | FUTURE ACTION | G | 25 | EFFECT ON PLANT | Z | 26 | SHUTDOWN METHOD | Z | 27 | HOURS | 0 | 0 | 0 | 0 | 28 | ATTACHMENT SUBMITTED | Y | 29 | NO. OF FORMS SUB. | N | 30 | PRIME COMP. SUPPLIER | L | 31 | COMPONENT MANUFACTURER | Z | 9 | 9 | 9 | 32

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | Technicians working on the Solid State Protection System cabinet placed the
11 | "Input Error Inhibit" switch in the "Inhibic" position and the mode selector
12 | switch in the "Test" Position. Before completing the work they left the area
13 | and their supervisor assuming the work was done returned the switches to their
14 | normal positions. This actuated the SI system. Personnel were retrained and
15 | procedures were rewritten to preclude such occurrences from happening again.

15 | FACILITY STATUS | X | 28 | % POWER | 0 | 0 | 0 | 0 | 29 | OTHER STATUS | Mode 5 | 30 | METHOD OF DISCOVERY | A | 31 | DISCOVERY DESCRIPTION | Personnel Observation | 32
16 | ACTIVITY CONTENT | Z | 33 | RELEASED OF RELEASE | Z | 34 | AMOUNT OF ACTIVITY | NA | 35 | LOCATION OF RELEASE | NA | 36
17 | PERSONNEL EXPOSURES NUMBER | 0 | 0 | 0 | 37 | DESCRIPTION | NA | 38
18 | PERSONNEL INJURIES NUMBER | 0 | 0 | 0 | 40 | DESCRIPTION | NA | 41
19 | LOSS OF OR DAMAGE TO FACILITY TYPE | Z | 42 | DESCRIPTION | NA | 43
20 | PUBLICITY ISSUED | N | 44 | DESCRIPTION | NA | 45

NAME OF PREPARER: R. W. Ouellette

PHONE: (704) 373-7530

8106290 349