

## LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | S | C | N | E | F | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5 |

9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | 25 | 26 | 27 | 28 | 29 | 30 |

LICENSEE CODE | LICENSE NUMBER | LICENSE TYPE | CAT

01 | REPORT SOURCE | L | 0 | 5 | 0 | 0 | 0 | 2 | 7 | 0 | 7 | 0 | 3 | 0 | 4 | 8 | 1 | 8 | 0 | 4 | 0 | 9 | 8 | 1 | 9 |

31 | 32 | 33 | 34 | 35 | 36 | 37 | 38 | 39 | 40 | 41 | 42 | 43 | 44 | 45 | 46 | 47 | 48 | 49 | 50 |

DOCKET NUMBER | EVENT DATE | REPORT DATE

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | On March 4, 1981, the "2B" MDEFWP was declared inoperable due to arcing in the

03 | motor. Both the "2A" MDEFWP and the TDEFWP were operable during this incident,

04 | thus providing the necessary flow to prevent loss of steam generator feedwater.

05 | Hence, the health and safety of the public were not compromised by this in-

06 | cident.

07 |

08 |

09 |

SYSTEM CODE | CAUSE CODE | CAUSE SUBCODE | COMPONENT CODE | COMP SUBCODE | VALVE SUBCODE

H | H | E | A | M | O | T | O | R | X | Z | Z

11 | 12 | 13 | 14 | 15 | 16 |

17 | LER/RO REPORT NUMBER | 8 | 1 | SEQUENTIAL REPORT NO. | 0 | 0 | 4 | OCCURRENCE CODE | 0 | 3 | REPORT TYPE | L | REVISION NO. | 0 |

21 | 22 | 23 | 24 | 25 | 26 | 27 | 28 | 29 | 30 | 31 | 32 |

ACTION FUTURE ACTION | EFFECT ON PLANT | SHUTDOWN METHOD | HOURS | ATTACHMENT SUBMITTED | NRC-4 FORM SUB. | PRIME COMP. SUPPLIER | COMPONENT MANUFACTURER

A | Z | B | Z | 0 | 0 | 0 | 0 | Y | Y | L | X | 9 | 9 | 9

33 | 34 | 35 | 36 | 37 | 38 | 39 | 40 | 41 | 42 | 43 | 44 | 45 | 46 | 47 |

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | The exact cause for the failure is not known. Immediately after the motor

11 | flashed, the breaker was tagged out and investigation began. The motor was

12 | disassembled, and the failure was found in the coil slot. A spare motor was

13 | transferred to Oconee. Power reduction began after 60 hours limit expired.

14 | The motor was replaced, tested, and coupled to the pump. The unit began

15 | returning to 74% FP.

16 | FACILITY STATUS | % POWER | OTHER STATUS | METHOD OF DISCOVERY | DISCOVERY DESCRIPTION

E | 0 | 7 | 4 | NA | B | Monthly performance test on MDEFWP

28 | 29 | 30 | 31 | 32 |

17 | ACTIVITY CONTENT | RELEASED OF RELEASE | AMOUNT OF ACTIVITY | LOCATION OF RELEASE

Z | NA | NA |

33 | 34 | 35 | 36 |

18 | PERSONNEL EXPOSURES | NUMBER | TYPE | DESCRIPTION

0 | 0 | 0 | Z | NA

37 | 38 | 39 |

19 | PERSONNEL INJURIES | NUMBER | DESCRIPTION

0 | 0 | 0 | NA

40 | 41 |

20 | LOSS OF OR DAMAGE TO FACILITY | TYPE | DESCRIPTION

Z | NA

42 | 43 |

21 | PUBLICITY | ISSUED | DESCRIPTION

N | NA

44 | 45 |

NAME OF PREPARER J. L. Jones

PHONE: (704) 373-8197

0106800192