(7-77) LICENSEE EVENT REPORT
CONTROL BLOCK:
Image: State
CON'T REPORT LIG 0 5 0 0 0 3 1 1 0 0 6 0 3 8 1 8 0 6 1 8 8 1 9 SOURCE 50 61 DOCKET NUMBER 58 59 EVENT DATE 74 75 REPORT DATE 80 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
During reactor trip, the starting of the second fan cooling unit energized from
2B Vital Bus tripped the 4KV Feeder Breaker, 2B4D, de-energizing the 460/230 Volt
2B Vital Buses. Action Statements 3.8.2.1a and 3.6.2.3a were entered at 0445 hours
0 5 and 0645 hours, respectively, on June 3, 1981.
7 8 9 SYSTEM CODE CAUSE SUBCODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE 0 9 E B 11 B 12 A 13 R E L A L X 14 D 15 Z 16
7 8 9 10 11 12 13 18 19 20 7 8 9 10 11 12 13 OCCURRENCE REPORT REVISION DEVENT YEAR REPORT NO. CODE TYPE NO.
17 REPORT 8 1 0 2 8 0 3 1 31 32 NUMBER 21 22 23 24 26 27 28 29 30 31 32
ACTION FUTURE EFFECT SHUTDOWN HOURS 22 SUBMITTED FORM SUB. SUPPLIER MANUFACTURER Image: Imag
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
only one fan cooling unit. DCR-2EC-1243 was issued to reset the overcurrent
[12] protection relays. The circuit was tested satisfactorily and Action Statements
13 3.8.2.1a and 3.6.2.3a were terminated at 0630 and 2125, respectively on June 3, 1981
7 8 5 FACILITY STATUS T 5 B (28) 0 2 0 (29) N/A DISCOVERY DESCRIPTION (32) N/A Operator Observation
1 5 D 20 0 2 0 2 0 80 7 8 9 10 12 13 44 45 46 80 7 8 9 10 12 13 44 45 46 80
1 6 2 33 2 34 NA 7 8 9 10 11 44 45 80
17 0 0 0 037 Z 38 NA 80
PERSONNEL INJURIES NUMBER DESCRIPTION (1)
7 8 9 11 12 LOSS OF OR DAMAGE TO FACILITY (3) TYPE DESCRIPTION
8 9 10 107060277 810618 J. J. Espey PHONE 609-935-0998
DR ADOCK 05000311 EPARER