


August 28, 1981

Docket No. 50-29  
LS05-81-08-072



Mr. James A. Kay  
Senior Engineer - Licensing  
Yankee Atomic Electric Company  
1617 Worcester Road  
Framingham, Massachusetts 01701

Dear Mr. Kay:

SUBJECT: SEP TOPIC VII-6, FREQUENCY DECAY SAFETY EVALUATION FOR  
YANKEE ROWE

The enclosed staff safety evaluation is based on a contractor document that has been made available to you previously. This evaluation is the staff's position regarding design of your facility in the subject area. With regard to the referenced topic, the staff has concluded your facility meets current licensing criteria.

Sincerely,

Dennis M. Crutchfield, Chief  
Operating Reactors Branch No. 5  
Division of Licensing

Enclosures:  
As stated

cc w/enclosures:  
See next page

SE04  
5  
//  
DS4 use (11)

OFFICE	SEP B	SEP B	SEP B	ORB #5	ORB #5	AD:SA:DL
SURNAME	cho11:b1	RHermann	WRussett	RCaruso	DCrutchfield	GLamas
	8/25/81	8/26/81	8/26/81	8/26/81	8/27/81	8/27/81

8109020296 810828  
PDR ADOCK 05000029  
P PDR

OFFICIAL RECORD COPY

Mr. James A. Kay

YANKEE ROWE  
Docket No. 50-29

cc

Mr. James E. Tribble, President  
Yankee Atomic Electric Company  
25 Research Drive  
Westborough, Massachusetts 01581

Greenfield Community College  
1 College Drive  
Greenfield, Massachusetts 01301

Chairman  
Board of Selectmen  
Town of Rowe  
Rowe, Massachusetts 01367

Energy Facilities Siting Council  
14th Floor  
One Ashburton Place  
Boston, Massachusetts 02108

U. S. Environmental Protection  
Agency  
Region I Office  
ATTN: EIS COORDINATOR  
JFK Federal Building  
Boston, Massachusetts 02203

Resident Inspector  
Yankee Rowe Nuclear Power Station  
c/o U.S. NRC  
Post Office Box 28  
Monroe Bridge, Massachusetts 01350

SYSTEMATIC EVALUATION PROGRAM  
TOPIC VII-6  
YANKEE ROWE

TOPIC VII-6 FREQUENCY DECAY

I. Introduction

Issue 9 of NUREG-0138 states that the staff should require that a postulated rapid decay of the frequency of the offsite power system be included in the accident analysis and that the results be demonstrated to be acceptable. Alternatively, the reactor coolant pump (RCP) circuit breakers should be designed to protection system criteria and tripped to separate the pump motors from the offsite power system because rapid decay of the frequency of offsite power system has the potential for slowing down or braking the RCP thereby reducing the coolant flow rates to levels not considered in previous analyses.

II. Review Criteria

The review criteria for reactor trip systems are presented in Table 7-1 of the Standard Review Plan.

III. Related Safety Topics and Interfaces

Set Points (Topic VII-1.A) and Degraded Grid (Topic VIII-1.A) are related review areas that are outside the scope of this Topic.

Although Topic VIII-1.A is not dependent on the present topic for completion, the conclusions with regard to frequency decay should be compatible.

IV. Review Guidelines

Issue 9 of NUREG-0138, "Staff Discussion of Fifteen Technical Issues Listed in Attachment to November 3, 1976 Memorandum from Director, NRR to NRR Staff," provides suitable guidance for this review.

V. Evaluation

Oak Ridge National Laboratory (ORNL), under a technical assistance program, reviewed the frequency decay rate phenomena and its effects on RCP's. The results of the review are presented in Section 4 of NUREG CR 1464, "Review of Nuclear Power Plant Offsite Power Source Reliability and Related Recommended Changes to the NRC Rules and Regulations." In summary, the report shows that the conditions required for dynamic braking of reactor coolant pumps are a sustained and rapid decrease in frequency while maintaining bus voltage. These conditions are only realized in a highly capacitive system using large amounts of buried transmission cables (such as Long Island). The Yankee Atomic Electric system does not use large amounts of buried transmission cable.

VI. Conclusion

The conditions necessary for an unacceptable frequency decay rate are not present in the Yankee Rowe offsite electrical distribution system. Accordingly, the staff considers this issue not to be applicable to Yankee Rowe.