SUPPLEMENTARY INFORMATION

Report No .:

50-302/81-066/03L-0

Facility:

Crystal River Unit 3

Report Date:

November 6, 1981

Occurrence Date:

October 10, 1981

Identification of Occurrence:

Various reactor protection instruments were found out-of-tolerance during shutdown surveillance activities. These events were not attributed to specific shutdown activities as required by Regulatory Guide 1.16, and, therefore, are being reported as contrary to Technical Specification 3.3.1.1.

Conditions Prior to Occurrence:

Mode 6 refueling (0%).

Description of Occurrence:

On October 10, 1981, during performance of SP-112, Calibration of the Reactor Protection System, RC-14A-DPT4 was found out-of-tolerance. On October 11, 1981, during performance of SP-112, RC-14A-DPT1 was found out-of-tolerance. On October 13, 1981, during performance of SP-112, RC-14B-DPT4 and RC-14B-DPT1 were found out-of-tolerance. On October 17, 1981, during performance of SP-112, RC-14B-DPT2 was found out-of-tolerance. On October 20, 1981, during performance of SP-112, RC-14B-DPT3 was found out-of-tolerance. On October 26, 1981, during performance of SP-112, RC-3B-PT1 and RC-3B-PT2 were found out-of-tolerance. On October 27, 1981, during performance of SP-112, RC-3A-PT1 was found out-of-tolerance.

Designation of Apparent Cause:

RC-14A-DPT4 had a bellows failure. The bellows was replaced. RC-14A-DPT1, RC-14B-DPT4, RC-14B-DPT1, and RC-14B-DPT2, RC-3B-PT1, and RC-3B-PT2, and RC-3A-PT1, all failed due to instrument drift. RC-14B-DPT3 had a loose test point output terminal. The terminal was tightened.

Analysis of Occurrence:

There was no effect upon the health or safety of the general public.

Corrective Action:

All instruments were satisfactorily recalibrated. No further corrective action is deemed necessary.

Failure Data:

Nine instruments were found out-of-tolerance. This is the ninth event reported under this Specification.