James A. FitzPatrick Nuclear Power Plant P.O. Box 41 Lycoming, New York 13093 315 342-3840



William Fernandez II Resident Manager

January 2, 1990 JAFP-90-0002

United States Nuclear Regulatory Commission Document Control Desk Mail Station P1-137 Washington, D.C. 20555

REFERENCE: DOCKET NO. 50-333 LICENSEE EVENT REPORT: 89-025-00

Dear Sir:

This Licensee Event Report is submitted in accordance with 10 CFR 50.73.

Questions concerning this report may be addressed to Mr. Hamilton Fish at (315) 349-6013.

Very truly yours,

WILLIAM FERNANDEZ

WF:HCF:lar

Enclosure

cc: USNRC, Region I INPO Records Center American Nuclear Insurers NRC Resident Inspector

NANC Par (8-83) 1.	• •				uc	ENSEE EVE	NT RE	PORT	(LER)	UAM	CLEAR REQULAT	0AY COMMISSION 0. 3180-0104
PACILIT	-										(2)	PARE
	JAME	S A. I	1121	ATRICK NUC	LEAR POI	NER PLANT				0 15 10 10	10131313	1 OF 017
TITLE IA	High	Pres	sure	Coolant	Injectio	on Turbine	Inop	erabl	e Due to	High Ste	am Flow I	solation
	from	Over	ly C	onservati	ve Setpo	oint and P	erfor	mance	Limits			
ev	INT DATE					REPORT DAY	. (7)		OTHER	ACILITIES INVO	LVED (B)	
MONTH	DAY	YEAR	YEAR	NUMBER	NUMBER	MONTH DAY	YEAR		FACILITY NAM		DOCKET NUMBER	A(8)
		253.5					-				0 18 10 10	10111
111	310	810	0 0	-01215	-010	0/1 0/2	0101			A. Contract		
1 1 1	12101	0 9			D PUPPUANT T		9 0 10			I the following II	0 101010	
	DOL (0)	NH	1	4026)		20.408(a)		lv.			72.710)	
POWE			-		-	80,38(a)(12		x	10.73(2)(2)(v)		72,71(0)	
LEVE	- 111	010	-			60.36(a)(2)		-			OTHER /Se	anthe in Absorbert
						80.73(a)(2)(i)					Selew and in	Test, NAC Form
			30.			80.73(a)(2)(8)			00.73(a)(2)(vill)(0			
						80.734s)(2)(HI)			0.73(a)(2)(a)			
					L	CENSEE CONTACT	FOR THIS	LER (12)				
NAME					a sin si		No. 1997.				TELEPHONE NUM	ben
ł	lamil	ton	с.	Fish						AREA CODE		
										31115	314191-	160 1-13
	<u> </u>			COMPLETE	ONE LINE POR	EACH COMPONENT	PAILURE	DESCRIBE	D IN THIS REPOR	T (13)	-	
CAUSE	SYSTEM	COMPON	ENT	TURER	TO NPRDS		CAUSE	SYSTEM	COMPONENT	MANUFAC TURER	TO NPROS	2
	.											
												•
	1	11	1	111					1.1.1			
				SUPPLEME	NTAL REPORT	EXPECTED (14)	4				MONTH	DAY VEAR
				NUMBER OF						EXPECTE SUBMISSI	DN	
YE	1 (If you, an	mpion EXP	ECTED	SUMISSION DATE	7	X NO				DATE (1)		
ABETRAC	T ILinte to	1400 000	n, i.e., a	peroximetery fifteen	single-space type	written lines/ (16)				(

EIIS Codes are in []

At 4:46 A.M. on 11/30/89 with the reactor at full power, the High Pressure Coolant Injection (HPCI) [BJ] system isolated on a high steam flow signal during a surveillance test initiating a 7-day Limiting Condition for Operation (LCO). An extensive testing program was initiated to identify the cause. HPCI was successfully tested and returned to service ending the LCO on 12/3/89 at 1:05 P.M. HPCI was removed from service for maintenance and further testing at 6:10 A.M. on 12/5/89, initiating a second 7-day LCO. It failed to meet operability testing criteria during surveillance testing at 10:00 P.M. by requiring more than 25 seconds to achieve full flow. Additional recording instruments were connected, vendor field engineers were obtained and extensive testing was performed through 12/11/89 when HPCI was declared operable at 7:31 P.M. The NRC granted a temporary waiver of the setpoint requirements for the high steam flow isolation prior to expiration of the 7-day LCO and subsequently approved a Technical Specification amendment increasing the high steam flow differential pressure setpoint. PORC approved increasing the FSAR design basis required actuation time for HPCI from 25 to 30 seconds. A 1981 vendor recommendation was implemented increasing the turbine start-up ramp time from 9 seconds to 15 seconds. Causes included an overly conservative Technical Specification limit for high steam flow isolation and FSAR basis for maximum actuation time and implementation of a more conservative test procedure. Related LERs: 89-002, 89-018, and 86-015.

NRC Form JORA		U.S. NUCLEAR REQULATORY COMMISSION
	LICENSEE EVENT REPORT (LER) TEXT CONTINUATION	APPROVED DM8 ND. 3150-0104 EXPIRES 8/31/86

ACILITY NAME (1)	DOCKET	DOCKET NUMBER (2) LER NUMBER (6)			PAGE (3)																
JAMES A. FITZPATRICK								Y	AR		SEO	UNNT	AL		NUN	-	-				
NUCLEAR POWER PLANT	0 15	01	0	10	13	13	1	8	19	_	0	121	5	_	0	10	0	12	OF		17
		-			-		-	10			1.	-	-			1	-	1-		-	1

EIIS Codes are in []

Description

On November 30, 1989, with the reactor operating at 100% power, the surveillance test ST-4B for "HPCI Pump and MOV Operability" was in progress. At 4:46 A.M. an isolation signal closed the outboard isolation valves 23MOV-16 and 23MOV-60 on the steam supply line to the High Pressure Coolant Injection (HPCI) [BJ] system rendering the HPCI inoperable and initiating a seven-day Limiting Condition for Operation (LCO). The annunciator for "HPCI Turbine Exhaust Discharge Pressure High" activated. However, although this is a turbine trip signal, it is not an isolation signal. The source of the isolation signal was not apparent. At 10:10 A.M. the B logic train for HPCI isolation logic was reset to facilitate testing. At 11:30 P.M. the surveillance test was satisfactory.

An additional six channels of strip chart recording instrumentation were connected to HPCI to obtain additional data to determine the cause of the isolation. Positioning the HPCI discharge test valve is a manual operation. The test is normally run by holding the control switch to the open position for five seconds. A range of 3 to 7 seconds was believed to bound the actual time during which an operator might have held the switch open. On December 1, 1989, the surveillance test was run three times between 11:30 A.M. and 12:45 P.M. For each test the valve position control switch for the HPCI test discharge valve (23MOV-21) to the Condensate Storage Tank (CST) was held open for a different time interval. For these tests, the switch was held open for intervals of 3, 5, or 7 seconds. Holding the discharge valve open for a shorter time interval results in higher discharge head pressure and requires increased steam flow demand to meet this pressure, potentially leading to a high steam flow isolation signal. An isolation signal was received during the 7 second test interval. The test way repeated at 5:00 P.M. and another isolation signal was received. At 11:10 P.M. the test was run at 5 seconds without an isolation.

It was subsequently noted that performing the three tests within the short time interval (less than one hour) did not simulate the cold start conditions for which the control system was designed. Accordingly, the tests were repeated on December 2, 1989 between 1:10 A.M. and 3:15 A.M. with approximately one hour allowed between each turbine start. All three tests were completed satisfactorily. The test was repeated at 11:40 P.M. following adjustment of the governor. After review of the data from the tests, it was determined that 5 seconds would continue to be used as the time interval to preposition the discharge test valve.

HAC Form SIGA	VENT REPORT (LER) TEXT CONT	INUATION APPROVE EXPIRES	REGULATON COMMISSION D DNS NO. 3150-0104 8/31/86
PACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)	PAGE (3
JAMES A. FITZPATRICK		YEAR SEQUENTIAL MEVE	ON

0 |5 |0 |0 |3 |3 |3 |8 |9 ---

01215

010

013 OF 0 17

Four more test runs of HPCI were made on December 3, 1989 between midnight and 6:00 A.M. At 11:50 A.M. Surveillance Test 4N, "HPCI Flow Rate and Inservice Test (IST)" was performed satisfactorily. At 1:05 P.M. Surveillance Test 4B was again performed satisfactorily and HPCI was declared to be operable, ending the seven-day LCO.

On December 5, HPCI was removed from service at 6:10 A.M. for planned maintenance, further testing, and adjustment. This again initiated a 7-day LCO. An electrical ground in the HPCI speed control circuit actuator developed and is reported separately as a supplement to LER-89-019. The ground was eliminated by replacing the actuator. The new actuator required adjustment of the actuator needle valve which is part of the turbine speed control hydraulic mechanism. ST-4N was run at 10:00 P.M. and did not meet the full flow requirement within the 25 seconds used as a basis in the Final Safety Analysis Report (FSAR).

The turbine acceleration time (ramp speed) was decreased from 14 to 12 seconds. Ramp speed adjustment controls the rate at which the turbine speed is increased from zero to rated RPM. This in turn effects the rate of steam flow. Shorter ramp speed results in increased steam flow. On December 6, ST-4B was run and the turbine tripped on high steam flow isolation at 1:22 P.M. Vendor field engineers arrived and for the next three days, December 7, 8, and 9, the turbine was operated multiple times using a temporary operating procedure, TOP-107, to collect data and evaluate the effect of adjustments to control circuits. The HPCI full flow test, ST-4N, was run on December 10 and was terminated at 9:32 A.M. by an outboard high steam flow isolation.

On December 11 the Plant Operations Review Committee (PORC) reviewed and recommended approval of an update of the HPCI system FSAR design basis for actuation time to be consistent with the current loss of coolant accident analysis. This increased the maximum permitted time from receipt of initiation signal to injection by HPCI at design flow from 25 seconds to 30 seconds. The increase in response time in turn allows lower steam flows and reduced probability of high steam flow isolation. The PORC also recommended approval of a proposed emergency change to the Technical Specifications for the differential pressure setpoint for the HPCI high steam flow isolation setpoint increasing it from 106 inches of water to 160 inches of water. This change in setpoint had the effect of permitting higher steam flows before an isolation signal would be generated. The changes to the test procedures permitting a 30 second response time were implemented. At 6:00 P.M. the HPCI full flow test, ST-4N was performed satisfactorily. At 6:18 P.M. the NRC granted a temporary waiver of the requirements of Item 13 in Table 3.2-2 of the Technical Specifications for the high steam flow isolation setpoint. This permitted continued operation of the plant. The change to the high steam flow setpoint was implemented. At 7:31 P.M. HPCI successfully completed ST-4B but was administratively considered to remain in an inoperable status pending completion of further testing and analysis.

NUCLEAR POWER PLANT

MRC Form 304 1171

	E EVEN (REPORT (LER) TEXT CONT		U.S. NUC	LATORY COMMISSION 8 NO. 3180-0104 85
PACILITY NAME (1)	DOCKET NUMBER (2)	LER NU	MBER (6)	PAGE (3
JAMES A. FITZPATRICK		TIAR SEQU	MALE NUMBER	Real Contraction

0 |5 |0 |0 |0 |3 |3 |3 8 |9 - 0 |2 |5 - 010 014 OF 0 17

ST IN more aparts & required, use additional MRC Parm 3864 's/ (17)

NUCLEAR POWER PLANT

On December 12, a complete retest of the HPCI and the high steam flow isolation setpoints was conducted and HPCI was declared to be operable at 3:00 A.M. ending the LCO. To demonstrate continued reliability, HPCI was tested again on December 13 and 19 with satisfactory results. On December 15, 1989 the NRC issued Amendment No. 147 to the Technical Specifications and related bases increasing the trip level setpoint for the HPCI steam line high flow isolation.

Cause

The immediate cause of the isolation signal and subsequent closing of the HPCI steam supply isolation valves was a flow of steam in excess of the setpoint for the high steam flow differential pressure sensors. The setpoint itself was overly conservative. The HPCI was able to be operated within this conservatism for 14 years until several changes were made within the HPCI system such as test methodology, new hydraulic actuator, and a rewiring of the turbine stop valve (see LER-89-002). These changes, combined with the unnecessarily conservative design basis for response time resulted in steam flows occasionally exceeding the existing isolation setpoint. There was also a failure to fully appreciate the integrated nature of the control system which led to a failure to thoroughly test and analyze HPCI transients following procedural changes and component replacement.

A summary of these five causes follows:

1. Overly conservative value for high steam flow isolation signal:

Although the FSAR Section 7.4.3.2.7 uses an analytical limit for determination of a break in the HPCI steam line of 300% rated flow, tests have shown that the Technical Specification setpoint isolates at a differential pressure equivalent to only 200% of rated flow.

2. Change to make test procedure more conservative:

For fourteen years HPCI had been tested by fully opening the discharge test valve (23MOV-21) to the CST prior to starting the turbine. In March 1989, acting on INPO guidance, the discharge test valve was manually prepositioned to simulate the discharge head against reactor pressure during the pump speed ramp up rather than first opening the valve and then closing down on it to obtain the required discharge pressure. In addition, a requirement to measure the HPCI response time against an acceptance criteria of 25 seconds was added to the procedure. The result of these changes was a demand for higher initial steam flow to provide the energy required for higher initial discharge pressures and to meet the response time criteria.

NRC form (6-83)	LILLASEE EVENT REPO	ORT (LER) TEXT CONTINU	U.S. HUCLEAR REGULATORY COMMENS APPROVED OMS NO. 3180-0104 EXPIRES 8/31.05								
PACILITY	NAME (1)	DOCKET NUMBER (2)	T		1	PAGE (3					
JAM	ES A. FITZPATRICK		YEAR	NUMBER	NUMBER	T					
NUC	LEAR POWER PLANT	0 15 10 10 10 13 13 13	819-	-01215	-010	015 0	F 0 17				
-	re apare à reputret, une salational MRC Farm SELA's/ (17)		101.51	101-12	1 1010	1.1.21-	1.1.				
3.	Overly conservative FSAR	design basis for	HPCI	respon	se tim	e:					
	The FSAR actuation time is receipt of reactor vesses pressure signals to achieve requirement was in the or recent plant specific and vendor SAFER/GESTR LOCA as response time parameters seconds. The current fue value. Other documentates achieve full flow and does in the full open position actuated. The result of initial steam flow demand isolation.	for HPCI was define l low low water le evement of design riginal vendor des alysis (10CFR50.46 application method . The assumed val el reload analysis ion clearly define es not require that n for HPCI to be of the 25 second req d and resulting po	ed as vel o basis ign s o, App lology ue in also s thi at the consid uirem tenti	25 se or high flow. pecifi redef the an assum s as t disch ered to ent was al for	conds drywe This cation K) base ines HI nalysis es this he time arge va o be fis s a his system	from 11 . Mon ed on PCI s is : s e to alve h ully gher n	re 30 be				
4.	Failure to appreciate the system led to the associa start-up transient stabil to the test procedure, ac replacement of individual Adjustment to a single co interfacing controls. It control and adjust it to signals and testing to re start-up and speed control	e integrated natur ated failure to te lity in sufficient djustment of compo l components in th ontrol requires re t is not sufficien its previous setp eadjust interfacin ol system.	e of st an dept nent e con eadjus t to oint g con	the HP d analy h follo control trol s tment simply withou trols	CI cont yze the owing o ls, and ystem. of all replac t using in the	trol e test change d other ce a g inpu	t es r it				
Ana	lysis										
The high of l turn pump vess elec	HPCI system is an engineer hly reliable source of wate sufficient volume to mainta hypothetical accident condi- bine driven, high pressure, p. The steam supply to the sel thus ensuring availabil ctrical power supplies.	red safety feature er into the reacto ain core coverage itions. The princ , high volume mult e turbine comes di lity regardless of	desi throu ipal i-sta rectl the	gned to rated p gh a bi compone ge cen y from condit:	o injec pressur road sp ent is trifuga the re ion of	ct a re and pectru a al eacton the A	d um c AC				
Beck	ause the HPCI system was in	noperable due to a	n iso	lation	signal	l, it					

pecause the HPCI system was inoperable due to an isolation signal, it qualifies as an event reportable under 10CFR50.73(a)(2)(v) as a condition that alone could have prevented the fulfillment of the safety function of a system needed to remove residual heat or mitigate the consequences of an accident. It is also reportable under 10CFR50.73(a)(2)(iv) as an activation of an engineered safety feature for automatic isolation.

NRC Form 354 (8-83)		T (LER) TEXT CONTINU	ATIO	N	U.S. NU A	PROVED C		3150-0	104
JAMES A. FITZPATRICK		DOCKET NUMBER (2)			• (•)		-	-	31
NUCLE	S A. FITZPATRICK AR POWER PLANT	0.15.10.10.10.10.10.10.10		NUME	AL E	NUMBER			
	man is required, use additional MRC Farm SELL's/ (17)		019	-012	5 -	10 10	0 0	01	0 1/
Surv succ was low spra inje	eillance tests of back-up e essfully completed. While assured by the automatic de pressure emergency core coc y systems [BM] and two resi ction) systems [BO].	emergency core co HPCI was not ava epressurization s bling systems inc dual heat remova	olin ilah yste ilud: il (1	ng syst ble, co em toge ing the low pre	ems ore the two ssu	wer cove r wi o co re c	e rage th t re oola	he he	
Corr	ective Action:								
Imme	diate:								
1.	The operability testing of performed as required by T	back-up core co Cechnical Specifi	olir .cati	ng syst ions.	ems	was			
2.	The HPCI turbine start-up 15 seconds.	speed control ra	imp s	speed v	7as	adju	sted	l to	>
3.	The HPCI steam supply line instrumentation setpoint w	high steam flow as changed to 14	dii 8 in	fferent nches c	ial of w	pre	ssur	e	
4.	Surveillance Test 4N, "HPC and 4B, "HPCI pump and MOV reflect the 30 second limi control of the pre-position test valve (23MOV-21) to t	CI Flow Rate and 7 Operability Tes 2t on response ti 25 oning opening time 25 the CST.	Inse t" v me f	ervice vere re for HPC or HPCI	Tes vis I a di	t (I ed to nd c scha:	ST)' o lose rge	r	
5.	The FSAR was revised to re time for HPCI as the desig	flect a 30 secon n basis.	d pe	ermitte	ed r	espo	nse		
6.	Technical Specification Ta reflect a maximum permitte setting of 160 inches of w	able 3.2-2, Item ad high steam flo vater.	13 v w di	vas rev Lfferer	vise itia	d to 1 pro	essu	ire	
Long	-Term:								
1.	A detailed engineering rev operating history will be further corrective actions assigned to this review.	view of the compl performed. It i will be recomme	ete s ar ndec	HPCI s nticips d by th	yst ited ie t	em an tha ask	nd i t forc	ts e	
2.	Existing surveillance proc procedures will be develop transient performance stab	edures will be r ed to monitor th oility including	evis le HI peak	sed or PCI sta c flow	new rt- mea	up sure	nent	s.	

NRC Form 325A (9-83)		U.S. NUCLEAR REGULATORY COMMIN						
PACILITY NAME (1)		DOCKET NUMBER (2)	1 .	ER NUMBER (6)	PADE (3)			
JAMES A. FITZPAT	RICK		YEAR	SEQUENTIAL NEV	MEEN			
NUCLEAR POWER	LANT	0 15 10 10 10 13 13 11	819 -	01215 0	10 0 17 OF 0 17			
TEXT IN more appear to required, use a	Alliana' MRC Form 3884's/ (17)							
Related Lice	nsee Event Repo	rts:						
LER-86-015	RCIC isolate air in senso	d due to false high r transmitter.	h steam	flow sign	al due to			
LER-89-002	HPCI wiring	error between stear	m stop	valve and	speed			

LER-89-018 HPCI isolated due to false high steam flow signal due to air in sensor transmitter. (LER-89-018 will be revised to change the then stated cause to reflect the true causes as reported in this LER.)

. . .

114-