

Portland General Electric Company Trojan Nuclear Plant 71760 Columbia River Hwy Rainier, Oregon 97048 (503) 556-3713

January 4, 1990 CPY-007-90

U.S. Nuclear Regulatory Commission Document Control Desk Washington DC 20555

## Gentlemen:

Licensee Event Report No. 89-29, Revision 1 is attached. This report updates events in which fire damper surveillances were missed due to personnel errors in scheduling and tracking of surveillances, to include other fire suppression systems.

Sincerely,

C. P. Yundt General Manager Trojan Nuclear Plant

c: Mr. John B. Martin Regional Administrator, Region V US Nuclear Regulatory Commission

> Mr. David Stewart-Smith State of Oregon Department of Energy

Mr. R. C. Barr USNRC Resident Inspector Trojan Nuclear Plant

9001120109 900104 PDR ADOCK 05000344 S PDC JE22

APPROVED OMB NO 3150-0104 LICENSEE EVENT REPORT (LER) EXPIRES 0/31/00 DOCKET NUMBER (2) Trojan Nuclear Plant 0 15 10 10 10 13 1 41 1 OFD Fire Dampers and Penetrations Surveillances not Performed Within the to Personnel Errors LER NUMBER IS REPORT DATE (7) OTHER FACILITIES INVOLVED (8) DAY SEQUENTIAL MONTH YEAR DAY DOCKET NUMBERIS N/A 0 | 5 | 0 | 0 | 0 0 0 1 0 0 4 0 15 10 10 10 1 THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § (Check one or more of the following) (11) OPERATING 20.402(b) 50.73(a)(2)(iv) 73.71(6) 20.405(+)(1)(i) 80.33(e)(1) 50.73(a)(2)(v) 73.71(e) OTHER (Specify in Abstract below and in Text, NRC Form 366A) 01917 20 406(4)(1)(0) 80 36(e)(2) 00 73(a)(2)(vii) 20.406(a)(1)(HI) 60 73(a)(2)(i) 60.73(e)(2)(viii)(A) 20 408 (a) (1) ((v) 80 73(a)(2)(iii) 00.73(a)(2)(viii)(0) 20 406 (a) (1) (v) 90.73(4)(2)((6) LICENSEE CONTACT FOR THIS LER (12) ELEPHONE NUMBER AREA CODE Scott A. Bauer, Nuclear Regulation Branch Manager COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13 EPORTABLE TO NPRDS CAUSE SYSTEM COMPONENT MANUFAC-MANUFAC TO NPROS CAUSE COMPONENT SUPPLEMENTAL REPORT EXPECTED (14) MONTH YEAR DAY EXPECTED YES I'I VOL COMPINE EXPECTED SUBMISSION DATE!

During an evaluation on November 15, 1989, it was determined that seven surveillances required by Trojan Technical Specification (TTS) 3.7.9. "Penetration Fire Barriers" for fire dampers had not been performed. The procedures for conducting the surveillances had recently been changed to require testing the dampers under flow conditions. The dampers of concern could not be tested in this manner, which was recognized at the time the surveillances were due, but was not properly resolved. During a review of the chronology for this event it was determined the surveillance periodicity time requirements for most fire dampers and penetrations had not been met since at least 1986. The compensatory measures of TTS 3.7.9 (checking local smoke detectors and establishing an hourly fire patrol) have been established for each of these dampers/penetrations. The issue concerning testing under flow conditions has been resolved and all damper and penetration inspections were completed by November 30, 1989. A task group evaluated the TTS surveillance program to ensure past surveillance periodicities have not been exceeded. The report of this task group is under review, but it has identified an additional missed surveillanca of four sprinkler systems. Fire watches were established and the required surveillance performed as immediate corrective actions for this additional event. A second task group is evaluating the TTS surveillance program to ensure future requirements are met. This Licensee Event Report (LER) abstract will be updated with a full LER by January 15, 1990 to report the findings and actions from the evaluation of these events. This LER is submitted in accordance with 10 CFR 50.73 (a)(2)(i)(B) as a missed surveillance and in accordance with the special reporting requirements of TTS 3.7.9 and 3.7.8.2, "Spray, Sprinkler, and/or Deluge Systems".

ABSTRACT (Limit to 1400 spaces, i.e. approximately fifteen single space typowritten lines) (16)