



Carolina Power & Light Company

Brunswick Nuclear Project
P. O. Box 10429
Southport, NC 28461-0429
January 4, 1990

FILE: B09-13510C
SERIAL: BSEP/90-0007

10CFR50.73

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555

BRUNSWICK STEAM ELECTRIC PLANT UNIT 1
DOCKET NO. 50-325
LICENSE NO. DPR-71
LICENSEE EVENT REPORT 1-89-026

Gentlemen:

In accordance with Title 10 to the Code of Federal Regulations, the enclosed Licensee Event Report is submitted. This report fulfills the requirement for a written report within thirty (30) days of a reportable occurrence and is in accordance with the format set forth in NUREG-1022, September 1983.

Very truly yours,

J. L. Harness, General Manager
Brunswick Nuclear Project

TH/mcg

Enclosure

cc: Mr. S. D. Ebnetter
Mr. E. G. Tourigny
BSEP NRC Resident Office

9001120223 900104
PDR ADCK 05000325
S PLC

LICENSEE EVENT REPORT (LER)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 60.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20535, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)

DOCKET NUMBER (2)

PAGE (3)

Brunswick Steam Electric Plant Unit 1

0 5 0 0 0 3 2 1 5 1 OF 0 1

TITLE (4)

Loss of E3 Bus While Deenergizing Bus 2D for Scheduled Maintenance

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)										
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)								
1	2	1	0	8	9	8	9	0	2	6	0	0	1	0	4	9	0	BSEP Unit 2	0 5 0 0 0 3 2 1 4
OPERATING MODE (9)			THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 8. (Check one or more of the following) (11)																
POWER LEVEL (10)			20.402(b)			20.406(c)			X			80.73(a)(2)(iv)			73.71(b)				
1			20.405(a)(1)(i)			80.38(a)(1)						80.73(a)(2)(v)			73.71(c)				
0			20.405(a)(1)(ii)			80.38(a)(2)						80.73(a)(2)(vi)			OTHER (Specify in Abstract below and in Text, NRC Form 366A)				
			20.405(a)(1)(iii)			80.73(a)(2)(i)						80.73(a)(2)(viii)(A)							
			20.405(a)(1)(iv)			80.73(a)(2)(ii)						80.73(a)(2)(viii)(B)							
			20.405(a)(1)(v)			80.73(a)(2)(iii)						80.73(a)(2)(ix)							

LICENSEE CONTACT FOR THIS LER (12)

NAME

TELEPHONE NUMBER

M. J. Pastva Jr., Regulatory Compliance Specialist

AREA CODE

9 1 1 9 4 5 1 7 1 - 1 2 3 1 1 5

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC

SUPPLEMENTAL REPORT EXPECTED (14)

EXPECTED SUBMISSION DATE (15)

MONTH	DAY	YEAR
0	2	1
1	6	9
0	1	0

☒ YES (Yes, complete EXPECTED SUBMISSION DATE)☐ NO

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

At 0553 hours on 12/10/89, Units' 1 and 2 common emergency bus E3 unexpectedly deenergized when the output breaker of emergency diesel generator (DG) No. 3, which was synchronized and loaded to the bus, opened. This event occurred when the master/slave feeder breakers of the normal power source to E3 from balance of plant bus 2D were opened to remove bus 2D from service for scheduled maintenance activities. Per design DG No. 3 automatically tied on to supply E3. The loss of E3 resulted in the following: Primary Containment isolations, Standby Gas Treatment System automatic initiation, and Reactor Building Ventilation System isolations (both units), and a B logic Reactor Scram signal (Unit 2 only). At the time, Unit 1 was operating at 100% and Unit 2 was defueled while in its 1989-1990 refuel/maintenance outage. By 0605 hours, normal power to E3 from bus 2D was restored and the incurred isolations and initiations of the affected systems on both units were reset and the systems were returned to normal.

A preliminary investigation has determined this event is the result of a procedural inadequacy of the involved Plant Electric System Operating Procedure (OP)-50 and the DG Emergency Power System OP-50.1. Upon completion of the investigation, a supplement to this report will be submitted by 2/16/90 to further detail the cause(s) and corrective action to this event.