



Arkansas Power & Light Company  
Arkansas Nuclear One  
Route 3, Box 137 G  
Russellville, AR 72801  
Tel 501 964 3100

January 8, 1990

1CANØ19ØØ7

U. S. Nuclear Regulatory Commission  
Document Control Desk  
Mail Station P1-137  
Washington, D. C. 20555

SUBJECT: Arkansas Nuclear One - Unit 1  
Docket No. 50-313  
License No. DPR-51  
Licensee Event Report 50-313/89-043-00

Gentlemen:

In accordance with 10CFR50.73(a)(2)(ii), attached is the subject report concerning the boric acid corrosion of a control rod drive mechanism flange assembly caused by a deteriorated gasket which resulted in a Reactor Coolant System pressure boundary degradation.

Very truly yours,

E. C. Ewing  
General Manager,  
Technical Support  
and Assessment

ECE/RHS/sgw  
attachment

cc: Regional Administrator  
Region IV  
U. S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 1000  
Arlington, TX 76011

INPO Records Center  
1500 Circle 75 Parkway  
Atlanta, GA 30339-3064

IE22  
1/1

9001120365 900108  
PDR ADOCK 05000313  
S PIC

NRC Form 366  
(9-83)

U.S. Nuclear Regulatory Commission  
Approved OMB No. 3750-0104  
Expires: 8/31/85

L I C E N S E E E V E N T R E P O R T ( L E R )

FACILITY NAME (1) Arkansas Nuclear One, Unit One | DOCKET NUMBER (2) | PAGE (3)  
| 05 | 010 | 01 | 3 | 1 | 3 | 10 | 0 | 13

TITLE (4) Boric Acid Corrosion of a Control Rod Drive Mechanism Flange Fastening Assembly Caused by a Deteriorated Gasket Results in Reactor Coolant System Pressure Boundary Degredation

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
Month	Day	Year	Sequential Number	Revision Number	Month	Day	Year	Facility Names	Docket Number(s)		
11	21	08	043	01	01	08	09		05010101		

OPERATING MODE (9) THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §:

OPERATING MODE (9)	N	(Check one or more of the following) (11)
POWER LEVEL (10)		20.402(b)   20.405(c)   50.73(a)(2)(iv)   73.71(b)
		20.405(a)(1)(i)   50.36(c)(1)   50.73(a)(2)(v)   73.71(c)
		20.405(a)(1)(ii)   50.36(c)(2)   50.73(a)(2)(vii)   Other (Specify in
		20.405(a)(1)(iii)   50.73(a)(2)(i)   50.73(a)(2)(viii)(A)   Abstract below and
		20.405(a)(1)(iv)   X   50.73(a)(2)(ii)   50.73(a)(2)(viii)(B)   in Text, NRC Form
		20.405(a)(1)(v)   50.73(a)(2)(iii)   50.73(a)(2)(x)   366A

LICENSEE CONTACT FOR THIS LER (12)

Name	Telephone Number
Larry A. Taylor, Nuclear Safety and Licensing Specialist	Area   Code   5011964-1311010

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

Cause	System	Component	Manufacturer	Reportable to NPRDS	Cause	System	Component	Manufacturer	Reportable to NPRDS

SUPPLEMENT REPORT EXPECTED (14)

EXPECTED SUBMISSION DATE (15)	Month	Day	Year

Yes (If yes, complete Expected Submission Date)  No

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On December 6, 1989, while removing the nut ring from beneath the reactor vessel (RV) nozzle flange at Control Rod Drive Mechanism (CRDM) location L-2, plant maintenance personnel discovered that approximately 50 percent of one of the nut ring halves had corroded away and that two of the four bolt holes in the corroded nut ring half were degraded to the point where there was no bolt/thread engagement. A total of six CRDM flanges had been identified to be potentially leaking during a video camera inspection on November 28, 1989 while the plant was in hot shutdown. After the plant was taken to cold shutdown, maintenance personnel disassembled and inspected the six CRDM flanges which had been identified during this inspection. All of the gasket seating surfaces were found to be undamaged with the exception of L-2. The RV nozzle flange at L-2 was eroded and pitted. An inspection of the flanges and spiral wound gaskets which were removed from between the flanges revealed that the cause of the leaks was the gradual deterioration of the gaskets with age. An Engineering evaluation concluded that the L-2 nozzle flange was acceptable for use. A replacement CRDM was installed at location L-2. Additionally, the gaskets on the six CRDMs were replaced with new design graphite type gaskets.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)
		Year	Sequential	Revision	
			Number	Number	
Arkansas Nuclear One, Unit One	05000313	89	043	0	02013

TEXT (If more space is required, use additional NRC Form 366A's) (17)

A. Plant Status

At the time of discovery of this condition, Arkansas Nuclear One, Unit 1 (ANO-1) was in the cold shutdown condition. Midcycle outage 1489 was in progress.

B. Event Description

On December 8, 1989, while removing the nut ring from beneath the reactor vessel (RV) nozzle flange at Control Rod Drive Mechanism (CRDM) location L-2, plant maintenance personnel discovered that approximately 50 percent of one of the nut ring halves had corroded away and that two of the four bolt holes in the corroded nut ring half were degraded to the point where there was no bolt/thread engagement.

The CRDMs are attached to the RV by eight hold down bolts which pass through the CRDM flange and the RV nozzle flange and thread into a nut ring which is positioned below the RV nozzle flange. The nut ring is a two piece carbon steel ring with four threaded holes in each section.

The disassembly of the L-2 CRDM flange was being performed as a result of its being identified as leaking on November 28 while the plant was in the hot shutdown condition. At that time, a video camera inspection of a RV level monitoring instrumentation (Rad Cal) flange which had been repaired in May, 1989 was being conducted. During this inspection, a small amount of water was observed to be dripping from flange L-2. Upon discovery of this leak, a 100 percent inspection of the CRDM flanges was conducted with the video camera. Boron deposits were observed on five additional CRDM flanges which indicated that they could possibly have been leaking. The Rad Cal flange was also observed to be leaking.

After the plant was taken to cold shutdown, maintenance personnel disassembled and inspected the flanges of the six CRDMs which had been identified as potential leakers. The location numbers of these flanges are; E-5, D-8, G-9, H-8, N-8 and L-2. The RV nozzle flange at L-2 was eroded and pitted. All other inspected flanges were undamaged.

C. Safety Significance

An Engineering evaluation was conducted which determined that in its as-found condition, with two of the eight bolts carrying no load, the L-2 CRDM flange and nut ring assembly was within code allowable stress limits and would have withstood the worst case faulted condition loads. However, the ring nut assembly at L-2 was severely corroded and did represent a significant degradation of a Reactor Coolant System (RCS) [AB] pressure boundary. Had this condition gone undetected, the nut ring would have continued to corrode and could have resulted in a significant non-isolable RCS leak. It is unlikely, however, that the leak rate could have become significant without being detected due to the various RCS leakage detection methods/systems used at ANO. During power operation, RCS leakage is monitored by the Inventory Balance System, the Reactor Building (RB) Sump Monitoring System, and the RB Air Monitoring System. If the total RCS leakage exceeds 10 gallons per minute (gpm) or if unidentified RCS leakage exceeds 1 gpm, the plant's Technical Specifications require that the reactor be shut down.

In addition, prior to depressurizing in preparation for outages, and after repressurization before resuming power operation, the RCS is inspected for leaks. This inspection includes the RV head area. Any identified RCS leaks are evaluated for boric acid corrosion effects.

D. Root Cause

An inspection of the flanges and the spiral wound gaskets which were removed from between the flanges revealed that the cause of the leaks was the gradual deterioration of the gasket material with age. The gasket at L-2 had been in place since initial plant operation. The initial leakage flowpath at L-2 was across the face of the flange, down the hold down bolts and on to the carbon steel nut ring. This leakage flowpath had not been previously anticipated. Since the leakage did not travel to the outside edge of the flange and because the nut ring area is not easily viewed, it was not detected during previous routine inspections of the RV head area. The five other CRDM flange leaks were the result of minor gasket deterioration. The Rad Cal leak was caused by a defective seal.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)
		Year	Number	Revision Number	
Arkansas Nuclear One, Unit One	05000313	89	043	0	0130F03

TEXT (If more space is required, use additional NRC Form 366A's) (17)

E. Basis For Reportability

Since this condition represented a significant degradation of an RCS pressure boundary, it is considered reportable pursuant to 10CFR50.73 (a)(2)(11).

This condition was also reported in accordance with 10CFR50.72 on December 12, 1989, via the Emergency Notification System.

F. Corrective Actions

An Engineering evaluation was performed by Babcock and Wilcox (B&W) which concluded that, although the L-2 RV nozzle flange was eroded and pitted, it was acceptable for use. B&W is presently developing a method by which the flange can be remachined. After development of this method, the L-2 flange will be remachined during the first outage of sufficient duration. The RV dome area and the RV head bolts were visually inspected for boric acid corrosion. This inspection revealed no significant corrosion or metal loss in this area.

A design change was implemented which installed new design graphite type gaskets, which were recommended by the vendor, in the six CRDM flanges and the Rad Cal flange.

A replacement CRDM was installed in location L-2. Additionally, the nut rings, bolts and washers were replaced on all six of the CRDM flanges and on the Rad Cal flange.

The defective Rad Cal seal design was modified to prevent leakage.

The "Inspection and Evaluation of Boric Acid Leaks" procedure will be revised by June 15, 1990, to require the inspection of the nut rings and associated hardware whenever a CRDM flange leak is identified. There are no RV head area inspections anticipated prior to this date.

The new design graphite gaskets which have been installed will be evaluated to determine if they are more reliable than the spiral wound gaskets which were originally installed. If the graphite gaskets prove to be more reliable, the spiral wound gaskets will be replaced, as necessary.

G. Additional Information

Similar events in which abnormal degradation of RCS pressure boundary components resulted from boric acid corrosion were reported in LERs 50-313/86-006-00 and 50-368/87-003-01.

Energy Industry Identification System (EIIS) codes are indicated in the text as [XX].