



Portland General Electric Company
Trojan Nuclear Plant
71760 Columbia River Hwy
Rainier, Oregon 97048
(503) 556-3713

January 4, 1990
CPY-005-90

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

Gentlemen:

Special Report

Limiting Condition for Operation (LCO) 3.7.9 "Penetration Fire Barriers" of the Trojan Technical Specifications (TTS) requires submittal of a Special Report if a three-hour fire barrier is nonfunctional for greater than seven days. The fire barriers in the areas described below were declared inoperable on the dates indicated and remained inoperable for greater than seven days.

Six (6) six inch electrical conduits located in the Control Building Switchgear Room (located at the bottom of A201 and A208 cabinets) are not adequately sealed. The penetrations were discovered and declared inoperable on December 13, 1989. They will be repaired by June 30, 1990. These penetrations were discovered during an engineering walkdown.

The compensatory measures of Technical Specification 3.7.9 (checking local smoke detectors and establishing an hourly fire patrol) were established immediately for each seal, as required.

Sincerely,

C. P. Yundt
General Manager
Trojan Nuclear Plant

c: Mr. John B. Martin
Regional Administrator, Region V
U. S. Nuclear Regulatory Commission

Mr. David Stewart-Smith
State of Oregon
Department of Energy

Mr. R. Barr
USNRC Resident Inspector
Trojan Nuclear Plant

Distribution

9001160169 900104
FDR ADOCK 05000344
S FDC

IE22
1/0